

ASS. REC. BY:

REF: CS3/AWA20001468/Btd3

Special Instruction:

Signature: M. Kim

ASSIGNMENT (Office)

18/2/2020

From (Person):

Stella Goh

of

AWAC

Date/Time:

24/01/2020 @ 10:46am

Estimated Cost:

Bill to:

OD: TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLH 1201X

Insured:

GBJ 3548R

at Workshop n/s

Auto Pro

Tel:

9188 3197

of

51 ubi Avenue 1 #05-02

Policy No:

BVCPSB0096371900

Claim No:

NSV 2000027

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17/01/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

10:53am @ 24/1/2020

Person Contacted:

Christina

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>SLH 1201X</u>
	<u>GBJ 3548R</u>
<u>14/2/2020</u>	<u>Submit PRS Report</u>
	<u>5 days</u>
	<u>Submit lump sum \$57007 - (Red: 2300! 28%)</u>

21/02/2020 - To submit
COR renewal.

21/02/2020

21/02/2020

21/02 - File pass to typist

URGENT

ASS. REC. BY:

REF:

AWA

ASSIGNMENT

From: _____ Date: 23/1/2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLH 1201Xat Workshop m/s: Auto proof 51 Lib Ave 1 #05-02

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 24000/-

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLH 1201X Yr Regn: 5/3/2007Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Wish 1.8AUX C.C. 1734Colour: White A/C: Insured / Std / NI / NASp. Reading: 123812 T/Radio: Insured / Std / NI / NAEng/No: 123323716C/No: 170612 N103602150Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 135/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 17/1/2020 D.O.I. 29/1/2020Survey held at Auto pro 12-12Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Resurvey 30/1/2020
	After repair - 14/2/2020
	455700/2 T. G. M. M. 23/2/2020
	MV 28,800/2
	PV 12,911/2
	NV 15,089/2
	T. G. M. M. 14/2/2020

Date/Time, File Pass to?

☐ : Preli. Report

11/4/2 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: PRS

Lump Sum / F.P. / G.

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 150

Transportation:

S. + P.S. SI

Photos

Others

TOTAL

Nivitha (LKK Auto)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Tuesday, 18 February 2020 3:16 PM
To: assignments
Subject: FW: AW REF: NSV2000027_ SLH 1201X _ Paper Survey
Attachments: IND REPORT - 1201.pdf

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Kin <Kin.Wong@awac.com>
Sent: Tuesday, 18 February 2020 2:41 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: AW REF: NSV2000027_ SLH 1201X _ Paper Survey

Hi Denise

Can you do a paper-re asap and send us the softcopy

Thank you.

Regards,

Kin Wong (Mr.)
Assistant Claims Manager, Asia-Pacific Claims Group
Allied World Assurance Company, Ltd.
60 Anson Road #08-01
Singapore 079914
T: +65 6423 0894
F: +65 6423 0864
E: kin.wong@awac.com
W: www.awac.com

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Friday, 14 February 2020 3:18 PM
To: Wong, Kin <Kin.Wong@awac.com>
Subject: RE: SLH 1201X at Auto Pro _ PRS

CAUTION: External Email

Dear Kin,

Enclosed PRS survey report, hard copy will follow up to your good office.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Kin <Kin.Wong@awac.com>

Sent: Tuesday, 4 February 2020 9:57 AM

To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Subject: SLH 1201X at Auto Pro _ PRS

Hi

PRS prelim Report Ready ma?

Thank you.

Regards,

Kin Wong (Mr.)

Assistant Claims Manager, Asia-Pacific Claims Group

Allied World Assurance Company, Ltd.

60 Anson Road #08-01

Singapore 079914

T: +65 6423 0894

F: +65 6423 0864

E: kin.wong@awac.com

W: www.awac.com

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, Ltd or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.



Inspection Services Pte Ltd

Date : 14 February 2020

To : **1st Autopro Pte Ltd**
51 Paya Ubi Ave 1
#05-02 Paya Ubi Industrial Park
Singapore 408934

AJAX Inspection Services Pte Ltd
120 Lower Delta Road
#08-08, Cendex Centre
Singapore 169208
Tel: +65 6255 0808
Fax: +65 6849 9155
info@ajaxinspection.com

Invoice No – AV23430
Company Reg No -201318067R
GST Reg No - 201318067R

TAX INVOICE

YOUR REF / CLAIM NUMBER : SLH1201X
OUR REF : AV52020-22488/BL
TP VEHICLE NO : SLH1201X
CLAIM TYPE : THIRD PARTY SURVEY
DATE OF SURVEY : 29 January 2020

No.	Description	Amount (S\$)
1	Professional fee	600.00

Subtotal	600.00
GST 7.00%	42.00
Total	642.00

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows:

Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd

Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

INSPECTION REPORT

1st Autopro Pte Ltd

51 Paya Ubi Ave 1 #05-02 Paya Ubi Industrial Park Singapore 408934

Assign Date:	29/01/2020	Inspection Date:	29/01/2020	TP Report Date:	18/01/2020
Accident Date:	17/01/2020	TP Policy No:	GA454907	Our Ref:	AVS2020-22488/BL
Place of Inspection:	1st Autopro Pte Ltd			Your Ref:	SLH1201X
	51 Paya Ubi Ave 1 #05-02 Paya Ubi Industrial Park			Claimant:	Mohamed Sanwan Bin Musafir
	Singapore 408934				

Description of Vehicle:

Veh. No:	SLH1201X	Make/Model:	Toyota Wish 1.8 Auto	Sum Insured (\$\$):	Market Value
Colour:	White	Engine No:	1ZZ3232916	Mkt Value (\$\$):	\$30,000.00
Engine Capacity:	1,794 cc	Chassis No:	JTDER12W103002180		
Odometer:	123819	Reg. Date:	05/03/2009		


Condition of Vehicle:

General:	Good	Modification:	No	Steering:	Serviceable
Air-Conditioner:	Yes	Radio/Cassette/CD:	Yes	Wing Mirror:	Yes
Handbrake:	Serviceable	Footbrake:	Serviceable	Paint work:	Good
Tyre Make:	Michelin				
Front Tyre Size:	195/65R15	Front Left Side:	5mm	Front Right Side:	5mm
Rear Tyre Size:	195/65R15	Rear Left Side:	5mm	Rear Right Side:	5mm

Description of Damage:

The damage was found on the rear portion. The rear tailgate, rear bumper, rear end panel, rear inner trims, rear tail lamps and among other parts were affected.

Point of Impact:



Adjuster:

BM Loh
Motor Appraiser

Date

COMPLETED 10 FEB 2020

Note: This report is confidential and solely for the use of the client. The inspection was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:			SLH1201X	Our Ref: AVS2020-22488/BL	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
List Items					
1	1	Rear bumper	Cracked	1,090.00	1,090.00 CRH 865.30
2	1	Rear bumper retainer	Necessary	205.00	205.00 NEG 131.20
3	1	Rear bumper bracket	Buckled	185.00	185.00 BT 95.90
4	1	Rear bumper reflector LH	Cracked	115.00	115.00 BRV 125.00
5	1	Rear bumper reflector RH	Not necessary	115.00	-- SVL
6	1	Rear tailgate	Bent	1,460.00	✓1,218.70 DDV
7	1	Rear taillamp LH	Cracked	630.00	630.00 BRV 441.90
8	1	Rear taillamp RH	Cracked	630.00	630.00 BRV 441.90
9	1	Rear tailgate absorber LH	Malfunction	370.00	370.00 } JAMV 224.63
10	1	Rear tailgate absorber RH	Malfunction	370.00	370.00 } 224.63
11	1	Rear tailgate inner trim	Cracked	560.00	560.00 CRAV 258.28
12	1	Rear end panel	Bent	780.00	780.00 DDV 662.10
13	1	Rear end panel top garnish	Cracked	420.00	378.00 DL 322.56
14	1	Rear tailgate chrome	Not necessary	420.00	-- SVL
15	1	Rear left fender inner trim	Cracked	620.00	620.00 CRAV
16	1	Rear right fender inner trim	Cracked	620.00	620.00 CRAV
17	1	Rear pare tyre panel	Repair	880.00	--
18	1	Rear lower spare tyre bracket	Not necessary	450.00	-- SVL
19	1	Rear tailgate moulding (rubber)	Deformed	360.00	360.00 NEG 210.00
20	1	Rear exhaust	Dented	800.00	800.00 NDX
21	1	Rear tailgate lock	Dented	365.00	365.00 NDX
Sub Total:				11,445.00	9,296.70 6462.6
Discount (less 25%):				0.00	2,324.18 1615.61
				11,445.00	6,972.53 4846.91

Special Nett Items

1	1	Rear bumper clips	Necessary	50.00	30.00 NECV
2	1	Rear end panel sealant	Necessary	80.00	30.00 40.00 NECV
3	1	Rear bumper sensor	Dented	350.00	100.00 250.00 DDV
4	1	Rear tailgate inner garnish clips	Necessary	50.00	30.00 NECV
5	1	Rear left fender trim clips	Necessary	50.00	30.00 NECV

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R



Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:				SLH1201X		Our Ref: AVS2020-22488/BL	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$		
6	1	Rear right fender trim clips	Necessary	50.00	30.00	NECV	
7	1	Rear number plate	Cut	50.00	35.00	MAX	SUL
Sub Total:				680.00	445.00		285.00
Total Parts Price:				12,125.00	7,417.53		

Labour Cost			
1	Wiring check.	80.00	40.00 20.00 ✓
2	To remove and refit rear windscreen.	200.00	120.00 ✓
3	To remove and refit rear tailgate.	150.00	80.00 50.00 ✓
4	To remove and refit rear trims garnish.	150.00	80.00 40.00 ✓
5	To remove and refit rear exhaust.	150.00	80.00 50.00 ✓
6	To remove and refit rear bumper sensor, check settings.	120.00	40.00 ✓
7	To panel beat rear portion.	1,200.00	1,000.00 300.00 ✓
8	To spray paint rear portion.	1,200.00	1,000.00 300.00 ✓
9	Anti rust rear portion.	120.00	80.00 60.00 ✓
10	End panel sealant.	80.00	60.00 30.00 ✓
11	To provide rear windscreen sealant.	80.00	40.00 30.00 ✓
Sub Total:		3,530.00	2,620.00 2040.00
Grand Total:		15,655.00	10,037.53 7171.95

Recommendation and Conclusion:

We have inspected the actual damages found on the vehicle and recommended the replacement of parts and repairs accordingly. The estimate repair cost is S\$15,655.00. The repairer has agreed to undertake the repairs at our adjusted lumpsum amount of S\$8,000.00.

We have not authorised the repair. Under normal circumstances, estimated six (06) working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.

The inspection was conducted entirely on a "Without Prejudice" basis.


Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Inspection Services Pte Ltd

Our Ref: AVS2020-22488/BL
Your Ref: SLH1201X



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.


AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2020-22488/BL
Your Ref: SLH1201X



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.






AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2020-22488/BL
Your Ref: SLH1201X



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.





AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2020-22488/BL
Your Ref: SLH1201X



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.





AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2020-22488/BL
Your Ref: SLH1201X



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.




AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2020-22488/BL
Your Ref: SLH1201X



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS3/AWA20001468/Btd3e2-1		
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 24-02-2020		
		Code : AWA		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 3548R	Veh. Inspected	SLH 1201X	
Policy No.	BVCPSB0096371900	Coverage (\$)	0.00	
Claim No.	NSV2000027	Excess (\$)	0.00	
Assign From	KIN WONG	Assign Date	18/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH 1.8 AUTO	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTDER12W103002180	Colour	WHITE	
Odometer	123819	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	5 mm	
L/H Front Tyre	195/65 R15	MICHELIN	5 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	5 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/01/2020	Inspection Date	29/01/2020	
Survey held at	AUTO PRO - 51 UBI AVENUE 1 #05-02 SINGAPORE 408934			
Repairer	-			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 1201X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CRACKED	1,090.00	865.90
1	REAR BUMPER RETAINER	NECESSARY	205.00	131.20
1	REAR BUMPER BRACKET	BENT	185.00	95.90
1	REAR BUMPER REFLECTOR LH	BROKEN	125.00	125.00
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	115.00	-
1	REAR TAILGATE	DENTED	1,460.00	1,218.70
1	REAR TAILLAMP LH	BROKEN	630.00	441.90
1	REAR TAILLAMP RH	BROKEN	630.00	441.90
1	REAR TAILGATE ABSORBER LH	JAMMED	370.00	224.63
1	REAR TAILGATE ABSORBER RH	JAMMED	370.00	224.63
1	REAR TAILGATE INNER TRIM	CRACKED	560.00	258.28
1	REAR END PANEL	DENTED	780.00	662.10
1	REAR END PANEL TOP GARNISH	DISLODGE	420.00	322.50
1	REAR TAILGATE CHROME	SERVICEABLE	420.00	-
1	REAR LEFT FENDER INNER TRIM	CRACKED	620.00	620.00
1	REAR RIGHT FENDER INNER TRIM	CRACKED	620.00	620.00
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	880.00	-
1	REAR LOWER SPARE TYRE BRACKET	SERVICEABLE	450.00	-
1	REAR TAILGATE MOULDING (RUBBER)	NECESSARY	360.00	210.00
1	REAR EXHAUST	NOT DAMAGED	800.00	-
1	REAR TAILGATE LOCK	NOT DAMAGED	365.00	-
	LESS 25% DISCOUNT		-	-1,615.66
			11,455.00	4,846.98
SPECIAL NETT ITEMS				
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	30.00
1	REAR BUMPER SENSOR (SN)	DENTED	350.00	100.00
1	REAR TAILGATE INNER GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR LEFT FENDER TRIM CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR RIGHT FENDER TRIM CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR NUMBER PLATE (SN)	SERVICEABLE	50.00	-
			680.00	250.00

Report Ref No. CS3/AWA20001468/Btd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	WIRING CHECK.		80.00	20.00
	TO REMOVE AND REFIT REAR WINDSCREEN.		200.00	120.00
	TO REMOVE AND REFIT REAR TAILGATE.		150.00	50.00
	TO REMOVE AND REFIT REAR TRIMS GARNISH.		150.00	40.00
	TO REMOVE AND REFIT REAR EXHAUST.		150.00	50.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR, CHECK SETTINGS.		120.00	40.00
	TO PANEL BEAT REAR PORTION. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL.		1,200.00	800.00
	TO SPRAY PAINT REAR PORTION.		1,200.00	800.00
	ANTI RUST REAR PORTION.		120.00	60.00
	END PANEL SEALANT.		80.00	30.00
	TO PROVIDE REAR WINDSCREEN SEALANT.		80.00	30.00
			3,530.00	2,040.00
	GRAND TOTAL		15,665.00	7,136.98
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,700.00

Report Ref No. CS3/AWA20001468/Btd3e2-1

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.