


Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Trans Cab
 of _____
 Insured: SLQ 80605
 Policy No: MK000575
 Claims No: M2001321
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SITC 56884 Yr Regn: 06, 15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Perant Lotitud c.c. 1995
 Colour M. White Red A/C: Insured / Std / NI / NA
 Sp. Reading 381338 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: VF1ABL15AUC - 281648
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: WT / S/Rim / STD A/Rim or _____
 Tyre Size: F: Goji 215/60R16
 R: Sedun
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 7 mm Rear R/Bal. 9 mm
 L/Bal. 7 mm L/Bal. 6 mm
 D.O.A. 12/2/20 D.O.I. 18/2/2020
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 844,6111
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 21 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

The U/C / Chassis frame & Body Structure affected due to collision. ✓

Date / Time	Action / Instruction
<u>1</u>	<u>Got injury</u>
	<u>SITC 56884 - CC3/TM1 18027674 / Teluk 2</u>
	<u>SLQ 80605 - CC3 / ICR / 2016 / 1841 / kvf3n2</u>
	<u>Dist - 25/04/2018</u>
	<u>P. CA - 01/01/2018</u>
<u>19/2/20</u>	<u>Email GIA x preli revised to TMS</u>
<u>24/3/20</u>	<u>L/Rep 8/13, 200 confirmed by email (Recd 76,191.04, 857)</u>
<u>25/3/20</u>	<u>Kenneth seen OI GIA</u>

RECEIVED 25 MAR 2020

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 21
 Resurvey No. of Trip: _____

2) 25/3 - typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	<u>250</u>
S - RS - SI	<u>11</u>
Fuel/os	
Others	
TOTAL	<u>261</u>

Report Format: merimen
 Lump Sum / I.B.I.: (\$ 13,200)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED

Our ref: CC3/TMI20002831/Kvf3

Date :19/2/2020

The Motor Claims Department
M/S TOKIO MARINE INSURANCE SINGAPORE LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SHC 5688Y

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/2/2020 at the premises of M/ TRANS-CAB AUTO SERVICES PTE TLD and have the following to report:-

Workshop Estimate Amount	: S\$89,391.04
Revised Estimate Amount	: S\$22,342.70
"Check" Items Amount	: S\$10,794.95
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion. The undercarriage and body structure affected due to collision



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 19 February 2020 2:46 PM
To: SUR; motorclaims@tokiomarine.com.sg
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 12/2/2020 , SHC 5688Y (TP Vehicle), SLQ 8060S (OI Vehicle)
Attachments: EST.pdf; GIA.pdf; POLICE REPORT.pdf; PRELI REVISED.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 5688Y at M/s: TRANS-CAB AUTO SERVICES PTE LTD,NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 18/2/2020

Enclosed herewith a copy of TP's GIA report, police report, estimated cost of repair and preliminary revised.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Feb 2020		19 Feb 2020 15:26 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LION CITY RENTALS PTE LTD , Co. Reg. No.: 201504621K								
Main Claimant:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHC5688Y	Date of Loss:	12/02/2020 00:00 - :59						
Claim Type:	TP / M2001321	Policy/Cover Note No.:	MK000575 (Third Party Only) Coverage: 25/06/2019 - 24/02/2020						
Vehicle Reg. No. (Insured):	SLQ8060S	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Teima Gomez - 65926402]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/02/2020]								
Adj Asp. Remarks:	- SURVEYED ON 18/02/2020 - OUR INSURED HAS NOT FILED SAS								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 24 March 2020 9:01 AM
To: Veron Chen (LKKAuto)
Cc: SUR
Subject: FW: SHC 5688Y-DOA: 12/2/2020 -- AAD2002-104
Attachments: MARK EST.pdf

Without prejudice

Dear Veron

Amount confirmed \$ 13,200 (before GST).

I still pending our workshop to send me the repair photo, will send to you when I get it.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 17 March, 2020 12:24 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; SUR <sur@lkkauto.com>
Cc: jasminetan@transcab.com.sg
Subject: SHC 5688Y-DOA: 12/2/2020

Dear Wai Yin,

WITHOUT PREJUDICE

Lump Sum \$13,200 (Max), @ 21 working days.

Kindly forward us after paint photos.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHC5688Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Feb 2020
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002556
Chassis No.:	VF1ABL15AUC281648
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	05 Jun 2015
First Registration Date:	05 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2023
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jun 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$52,886.00
COE Rebate Amount:	\$21,860.00
Total Rebate Amount:	\$31,233.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/02/2020 14:56
Date Of Accident	12/02/2020 06:20
Exact Location Of Accident	COMMONWEALTH AVENUE
Country/State of Loss	MALAYSIA/WILAYAH PERSEKUTUAN

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5688Y
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	2XXXXX878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876686

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

Driver

Name of Driver	TAN SAY FOO
NRIC No	SXXXX242I
Date Of Birth	11/12/1960
Occupation	OUTDOOR
Date Of Driving Pass	10/06/1999
Driving Experience	20 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84391434
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 219 SERANGOON AVENUE 4 #09-204
Postcode	550219
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MR KWEK GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/20200214/2054

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	MR KWEK
Phone Number	90904666
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ8060S
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category PRIVATE HIRE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN SAY FOO
Approximate Age
Injuries Sustain
Injured person in which vehicle? SHC5688Y
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 2

Name MR KWEK
Approximate Age
Injuries Sustain
Injured person in which vehicle? SHC5688Y
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report T/20200214/2054.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20200214/2054

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20200214/2054

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/02/2020 13:09		Vide Report No.: D/20200212/0023		Station Diary No.:	
Informant's Particulars					
Name of Informant: TAN SAY FOO			Address: APT BLK 219 SERANGOON AVENUE 4 #09-204 SERANGOON GREEN SINGAPORE 550219		
ID Type / ID No.: NRIC NO / S1449242I			Contact No.:		Mobile: 84391434
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 59	Date of Birth: 11/12/1960	Type of Informant: Driver		
Race:		Language:	Institution / School Name:		
Occupation: OTHERS		Driving Licence Information: Class: 3,4		Date of Expiry:	

General Information of the Accident					
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 12/02/2020 06:20	Type of Location:	
Location: Along Road 1 COMMONWEALTH AVENUE THE TRAFFIC JUNCTION AFTER THE COMMONWEALTH MRT STATION					
Weather: Clear		Road Surface:		Road Speed Limit:	
Traffic Flow:		Traffic Control:		Traffic Volume: No Traffic	
Type of Collision:				Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC5688Y	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20200214/2054

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20200214/2054

CONTINUATION OF REPORT

Driver			
Name	TAN SAY FOO	ID No.	S1449242I
Related Vehicle	SHC5688Y (Car)	Contact No.	84391434
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	07	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE AND TIME,

I WAS AT THE CROSS JUNCTION AREA AND WAS WAITING TO MAKE A RIGHT TURN THUS I STOPPED AT THE RIGHT HAND SIDE OF THE ROAD AS THE TRAFFIC LIGHTS WERE STILL RED. AT THAT POINT IN TIME, THERE WERE NO VEHICLES IN FRONT OR BEHIND ME. HOWEVER ANOTHER VEHICLE SUDDENLY COLLIDED INTO THE REAR OF MY VEHICLE. BOTH MYSELF AND MY PASSENGER WERE IN PAIN, THE OTHER DRIVER TOOK SOME TIME BEFORE COMING TO CHECK UP ON US. MY PASSENGER MANAGED TO TAKE A FEW PHOTOS OF THE ACCIDENT AND SENT THEM TO ME. THERE IS AN IN CAR CAMERA IN MY TAXI AND THE POLICE WHO CAME DOWN TO THE SCENE TOOK IT FROM ME. LATER I WAS CONVEYED TO THE HOSPITAL.

THAT IS ALL



**SINGAPORE
POLICE FORCE**



T/20200214/2054

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20200214/2054

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: TP / LEE CHEN EN
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / SI VILTON HIA WEE SIANG Contact No.: 65476178

Signature Of Informant: 
Date/Time: 14/02/2020 13:09
Classification Of Case:  SINGAPORE POLICE FORCE
Signature: 

Authentication Stamp
NP168

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y**AAD2002-104***Not Authorised
L/Sing &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

18 FEB 2020

SHC 5688Y

VF1ABL15AUC281648

RENAULT

LATITUDE

12.2.2020

TOKIO MARINE

5/6/2015

PART	LIST
1 BUMPER COVER REAR	\$ B ₁ 561.70 ✓
1 BUMPER LOWER REAR	\$ mi 411.90 ✓
1 BUMPER BRACKET CTR REAR	\$ CM 98.10 ✓
1 BUMPER BRACKET SIDE RH REAR	\$ Di 82.10 ✓
1 BUMPER RETAINER RH REAR	\$ Di 59.80 ✓
1 BUMPER REFLECTOR RH	\$ CM 16.60 ✓
1 BUMPER BRACKET SIDE LH REAR	\$ CM 80.80 ✓
1 BUMPER RETAINER LH REAR	\$ Di 54.20 ✓
1 BUMPER REFLECTOR LH	\$ mi 16.60 ✓
1 BUMPER BEAM REAR	\$ B ₁ 547.80 ✓
1 BUMPER BEAM BRACKET LH REAR	\$ B ₁ 114.50 ✓
1 BUMPER BEAM BRACKET RH REAR	\$ Di 100.90 ✓
1 BUMPER BLOCK LH REAR	\$ NIP 75.70 X
1 BUMPER BLOCK RH REAR	\$ NIP 76.50 ^
1 BUMPER HARNESS REAR	\$ S ₁ 301.10 X
1 BOOT REAR	\$ B ₁ 1,677.20 ✓
1 BOOT FINISHER	\$ way 344.70 ✓
1 BOOT WHEATERSTRIP	\$ Di 178.20 50 21 ~ 89.10
1 BOOT REFLECTOR LAMP LH	\$ B ₁ 277.70 ✓
1 BOOT REFLECTOR LAMP RH	\$ B ₁ 277.70 ✓
1 BOOT BADGE 'RENAULT'	\$ N ₁ 82.40 ✓
1 BOOT BADGE	\$ N ₁ 95.80 ✓
1 BOOT STRUT LH	\$ S ₁ 145.10 X
1 BOOT STRUT RH	\$ S ₁ 145.10 X
1 BOOT HINGE LH	\$ B ₁ 254.20 ✓
1 BOOT HINGE RH	\$ Di 253.80 ✓

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

1	BOOT INNER TRIM BOARD	\$	Return	611.00	✓
1	BOOT SWITCH	\$	Sm	113.00	
1	BOOT LOCK	\$	Tm	246.60	✓
1	BOOT LOCK CATCH	\$	Dit	41.70	✓
2	LICENCE PLATE LAMP	\$	Sm	26.30	X
2	BOOT RUBBER PLUG	\$	Sm	139.30	X
1	BOOT LOCK LINKAGE	\$	Sm	20.60	X
1	BOOT LOCK LINKAGE HOLDER	\$	Sm	99.50	X
2	BOOT BUFFER	\$	Sm	26.80	X
1	FENDER PANEL REAR LH	\$	Bz	1,933.20	✓
1	WHEELARCH REAR LH	\$	CM	181.60	✓
1	FENDER PANEL INNER TRIM REAR LH	\$	Return	671.45	✓
1	FENDER PANEL REAR RH	\$	Bz	1,933.20	✓
1	WHEELARCH REAR RH	\$	Sm	275.40	X
1	FENDER PANEL INNER TRIM REAR RH	\$	Bz	671.45	✓
1	AIR VENT RH	\$	Sm	59.40	X
1	AIR VENT LH	\$	Dd	59.40	✓
1	TAILLAMP RH	\$	Sm	401.40	X
1	TAILLAMP PANEL RH	\$	R	401.40	X
1	TAILLAMP LH	\$	Bz	401.40	✓
1	TAILLAMP PANEL LH	\$	Bz	401.40	✓
1	OUTER PANEL REAR (End Panel)	\$	Bz	745.80	✓
1	OUTER PANEL REAR (End Panel) TRIM	\$	Dit	404.56	✓
1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Btl/Bz	1,229.40	✓
1	SPARE WHEEL PANEL TRIM	\$	Sm	612.21	X
1	SPARE TYRE BOARD	\$	Sm	680.90	X
1	SPARE WHEEL PANEL BRACKET LH L70Y	\$	R	70.60	X
1	SPARE WHEEL PANEL BRACKET RH L70Y	\$	R	69.20	X
1	EXHAUST REAR	\$	R	5,263.60	X
1	EXHAUST CAP REAR	\$	Sm	125.40	X
1	CHASSIS PANEL REAR LH	\$	R	2,192.40	X
1	FENDER PANEL INNER REAR LH L70Y	\$	Bz	1,241.60	✓
1	FENDER INNER BOARD LH L70Y	\$	R	561.40	X
1	FENDER WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09	X

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

1	FUEL FLAP	\$	244.70	✓
1	FUEL TANK FILLER NECK	\$	473.10	X
1	FUEL TANK CAP	\$	136.90	X
1	FUEL TANK	\$	2,748.95	X
1	FUEL TANK PUMP	\$	1,266.53	X
1	FUEL PIPE SHORT	\$	611.80	X
1	FUEL PIPE LONG	\$	1,148.12	X
1	TUBE FILLER	\$	297.19	X
1	KNUCKLE ARM REAR RH L70Y	\$	472.10	X
1	BRAKE DISC REAR RH L70Y	\$	266.50	X
1	WHEEL HUB NUT L70Y	\$	41.80	X
1	WHEEL HUB CAP L70Y	\$	30.50	X
1	ABS SENSOR REAR RH L70Y	\$	190.50	X
1	REAR AXLE L70Y	\$	3,469.00	X
1	AXLE ARM RH L70Y	\$	69.50	} X
1	REAR AXLE SPACER RH	\$	49.00	
1	REAR AXLE ARM ROD RH	\$	69.50	
1	LOWER ARM REAR RH L70Y	\$	543.50	
1	AXLE SPRING ARM RH	\$	220.60	
1	ABSORBER REAR RH	\$	217.30	
1	ABSORBER DUST COVER REAR RH	\$	47.10	
1	ABSORBER MOUNTING REAR RH	\$	49.40	
1	STABILIZER BAR REAR	\$	427.90	
1	STABILIZER LINK REAR RH	\$	55.20	
1	BRAKE CALIPER REAR RH	\$	659.10	} X
1	BRAKE CALIPER BRACKET REAR LH/RH	\$	384.00	
1	BRAKE HOSE REAR RH	\$	79.50	
1	KNUCKLE HUB+ BEARING RH	\$	272.30	
1	SUBFRAME ARM REAR RH	\$	198.33	
1	RODE- LONG REAR RH	\$	120.16	
1	KNUCKLE ARM REAR LH L70Y	\$	472.10	
1	BRAKE DISC REAR LH L70Y	\$	266.50	
1	WHEEL HUB NUT L70Y	\$	41.80	
1	WHEEL HUB CAP L70Y	\$	30.50	

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

1	ABS SENSOR REAR LH L70Y	\$	190.50	X	
1	AXLE ARM LH L70Y	\$	69.50	X	
1	REAR AXLE ARM ROD LH	\$	69.50	X	
1	LOWER ARM REAR LH L70Y	\$	543.50	X	} Sur
1	AXLE SPRING ARM LH	\$	220.60	X	
1	ABSORBER REAR LH	\$	217.30	X	
1	ABSORBER DUST COVER REAR LH	\$	47.10	X	
1	ABSORBER MOUNTING REAR LH	\$	49.40	X	
1	BRAKE CALIPER REAR LH	\$	659.10	X	
1	BRAKE CALIPER BRACKET REAR LH/RH	\$	384.00	X	
1	BRAKE HOSE REAR LH	\$	79.50	X	
1	KNUCKLE HUB+ BEARING LH	\$	272.30	X	
1	SUBFRAME ARM REAR LH	\$	198.33	X	
1	RODE- LONG REAR LH	\$	120.16	X	
1	REAR AXLE SPACER LH	\$	49.00	X	
1	STABILIZER LINK REAR LH	\$	55.20	X	
1	BRAKE PAD REAR	\$	145.60	X	
1	WINDSCREEN REAR L70Y	\$	817.20		Shatten ✓
1	WINDSCREEN GARNISH INNER LH	\$	257.40		Dis ✓
2	WINDSCREEN SEALANT	\$	109.20		Sur 405A
1	WINDSCREEN GARNISH INNER RH	\$	257.40	X	
1	WINDSCREEN LOWER GRILLE COVER	\$	310.60	X	
1	SHELF ASSY (WINDSCREEN UNDER PANEL)	\$	443.76	X	
1	SHELF AR	\$	730.60	X	
1	EXTENSION-RR LH SIDE MEMBER	\$	247.69	✓	
1	EXTENSION-RR RH SIDE MEMB	\$	245.79	X	
1	DOOR PANEL REAR RH	\$	758.70	X	
1	DOOR LOCK REAR RH L70Y	\$	467.30	X	
1	ROCKER PANEL INNER GARNISH LH	\$	466.51	X	
1	ROCKER PANEL INNER LH	\$	1,024.79	X	
1	ROCKER PANEL OUTER LH	\$	1,184.99	X	
1	DOOR PANEL REAR LH	\$	758.70	X	
1	DOOR LOCK REAR LH L70Y	\$	468.20	X	
1	DOOR CATCH REAR LH/RH	\$	73.70	X	

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

1 DOOR FINISHER REAR LH	\$	Sm	230.30	}
1 DOOR WEATHESTRIP REAR LH L70Y	\$	Sm	240.50	
1 DOOR SEAL REAR LH	\$	Sm	119.40	
1 DOOR WAIST SEAL OUTER REAR LH	\$	Sm	116.10	
1 ROOF PANEL	\$	R	2,900.70	
1 ROOF SIDE PANEL OUTER LH	\$	R	704.21	
1 ROOF TOP CHANNEL MOLDING LH	\$	Sm	291.27	
1 ROOF TOP CHANNEL MOLDING RH	\$	Sm	291.27	

TOTAL	\$	65,482.71
10%	\$	6,548.27
	\$	58,934.44

Special Nett

1SET PARKING AID	\$	nd	700.00	400sm
1SET REAR BUMPER CLIP	\$	na	66.00	—
1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	✓
1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
1SET BUMPER LOWER REAR CLIP	\$	na	66.00	—
1 EXHAUST MOUNTING REAR	\$	na	16.00	X
1SET BOOT FINISHER CLIP	\$	na	24.20	—
1 BOOT STICKER "Trans-cab"	\$	na	30.00	—
1 BOOT STICKER "6555-3333"	\$	na	30.00	—
1 BOOT INNER TRIM CLIP	\$	na	45.00	—
1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	—
1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	—
1 FENDER INNER TRIM CLIP LH	\$	na	28.00	—
1 FENDER INNER TRIM CLIP RH	\$	na	28.00	X
1 TAILLAMP CLIP RH	\$	na	5.00	X
1 TAILLAMP CLIP LH	\$	na	5.00	—

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

1	WINDSCREEN MOULDING	\$	<i>nn</i>	160.00	<i>x</i>
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	<i>301n</i>
1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>su</i>	385.00	<i>x</i>
1	SPARE TYRE	\$	<i>su</i>	330.00	<i>x</i>
1	RIGHT REAR TYRE	\$	<i>su</i>	330.00	<i>x</i>
1	RIGHT REAR TYRE RIM	\$	<i>su</i>	380.00	<i>x</i>
1	RIGHT LEFT TYRE	\$	<i>su</i>	330.00	<i>501n 165</i>
1	RIGHT LEFT TYRE RIM	\$	<i>su</i>	380.00	<i>x</i>
1	EXHAUST BRACKET REAR	\$	<i>x</i>	24.80	} <i>x</i>
1	REAR RH DOOR STICKER "6555-3333"	\$	<i>nn</i>	100.00	
1	REAR LH DOOR STICKER "6555-3333"	\$	<i>nn</i>	100.00	
1	REAR BUMPER PROTECTOR	\$	<i>nn</i>	100.00	
1Set	REAR LICENCE PLATE WITH HOLDER	\$	<i>su</i>	100.00	
2	BOOT LOCK SCREW	\$	<i>su</i>	6.10	
2	BOOT LOCK CATCH SCREW	\$	<i>su</i>	12.50	
TOTAL		\$		4,066.60	

TOTAL PARTS \$ 63,001.04**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	9,900.00	<i>17601</i> <i>24001</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	9,900.00	<i>24001</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	<i>601</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	350.00	<i>1201</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>601</i>

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

To Rust-Proofing Of The Affected Areas.	\$	170.00	1501
To repair and realign rear exhaust pipe.	\$	<i>Repaired</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	} 801
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	220.00	601
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	2501
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	X

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

To Check Electrical Lighting Concerned.	\$	170.00	201
Towing Fees	\$	150.00	501
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>na</i> 350.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	2201
To drop diesel/petrol tank, pipes, hoses and renew the necessary parts and final checking and testing for leak.	\$	440.00	601
To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing.	\$	<i>Repair</i> 380.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>4</i> 380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	<i>na</i> 380.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>na</i> 380.00	X
TOTAL	\$	26,390.00	
Over All Total	\$	89,391.04	

LUMP SUM (Repair Days)~~35 DAYS~~

21 days

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI20002831/KVF3N2
Date: 31/03/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MK000575
Claimant Vehicle No : SHC5688Y **Insured Vehicle No :** SLQ8060S
 Date of Loss: 12/02/2020 Nature of Claim: TP Claim No: M2001321

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5688Y**
 Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) Engine No: M9R8839C002556
 Reg. Date: 05/06/2015 (Man. Year: 2015) Chassis No: VF1ABL15AUC281648
 Colour: Metallic White/Red Odometer: 381338 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
 Front Left Side: Giti 7 mm Rear Left Side: Sailun 6 mm
 Front Right Side: Giti 7 mm Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	63,001.04	16,872.70	46,128.34	73.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	26,390.00	5,470.00	20,920.00	79.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	89,391.04	22,342.70	67,048.34	75.01
Approved Total (Overridden) (S\$)		13,200.00		
(S\$)	89,391.04	13,200.00	76,191.04	85.23
+ GST 7.00/7.00% (S\$)	6,257.37	924.00	5,333.37	85.23
Nett Amount (S\$)	95,648.41	14,124.00	81,524.41	85.23

INSPECTION

Date of Assignment: 19/02/2020
 Date Inspected: 18/02/2020 Inspected At: Trans-Cab Services Pte Ltd (HQ)
 2 Ang Mo Kio Street 63
 Singapore 569111
 Estimated Period of Repair: 21.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Mar 2020)

Parts: 143 RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC5688Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Reference	Amount
1	1	*BUMPER COVER REAR	Bent	561.70 FL	-	*561.70 FL
2	1	*BUMPER LOWER REAR	Missing	411.90 FL	-	*411.90 FL
3	1	*BUMPER BRACKET CTR REAR	Cracked	98.10 FL	-	*98.10 FL
4	1	*BUMPER BRACKET SIDE RH REAR	Distorted	82.10 FL	-	*82.10 FL
5	1	*BUMPER RETAINER RH REAR	Distorted	59.80 FL	-	*59.80 FL
6	1	*BUMPER REFLECTOR RH	Cracked	16.60 FL	-	*16.60 FL
7	1	*BUMPER BRACKET SIDE LH REAR	Cracked	80.80 FL	-	*80.80 FL
8	1	*BUMPER RETAINER LH REAR	Distorted	54.20 FL	-	*54.20 FL
9	1	*BUMPER REFLECTOR LH	Missing	16.60 FL	-	*16.60 FL
10	1	*BUMPER BEAM REAR	Bent	547.80 FL	-	*547.80 FL
11	1	*BUMPER BEAM BRACKET LH REAR	Bent	114.50 FL	-	*114.50 FL
12	1	*BUMPER BEAM BRACKET RH REAR	Distorted	100.90 FL	-	*100.90 FL
13	1	*BUMPER BLOCK LH REAR	No such part	75.70 FL	-	*-FL
14	1	*BUMPER BLOCK RH REAR	No such part	76.50 FL	-	*-FL
15	1	*BUMPER HARNESS REAR	Serviceable	301.10 FL	-	*-FL
16	1	*BOOT REAR	Bent	1,677.20 FL	-	*1,677.20 FL
17	1	*BOOT FINISHER	Warped	344.70 FL	-	*344.70 FL
18	1	*BOOT REFLECTOR LAMP LH	Broken	277.70 FL	-	*277.70 FL
19	1	*BOOT REFLECTOR LAMP RH	Broken	277.70 FL	-	*277.70 FL
20	1	*BOOT BADGE RENAULT	Necessary	82.40 FL	-	*82.40 FL
21	1	*BOOT BADGE	Necessary	95.80 FL	-	*95.80 FL
22	1	*BOOT STRUT LH	Serviceable	145.10 FL	-	*-FL
23	1	*BOOT STRUT RH	Serviceable	145.10 FL	-	*-FL
24	1	*BOOT HINGE LH	Bent	254.20 FL	-	*254.20 FL
25	1	*BOOT HINGE RH	Distorted	253.80 FL	-	*253.80 FL
26	1	*BOOT INNER TRIM BOARD	Deformed	611.00 FL	-	*611.00 FL
27	1	*BOOT SWITCH	Serviceable	113.00 FL	-	*-FL
28	1	*BOOT LOCK	Jammed	246.60 FL	-	*246.60 FL
29	1	*BOOT LOCK CATCH	Distorted	41.70 FL	-	*41.70 FL
30	2	*LICENCE PLATE LAMP	Serviceable	26.30 FL	-	*-FL
31	2	*BOOT RUBBER PLUG	Serviceable	139.30 FL	-	*-FL
32	1	*BOOT LOCK LINKAGE	Serviceable	20.60 FL	-	*-FL
33	1	*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	-	*-FL
34	2	*BOOT BUFFER	Serviceable	26.80 FL	-	*-FL
35	1	*FENDER PANEL REAR LH	Bent	1,933.20 FL	-	*1,933.20 FL
36	1	*WHEELARCH REAR LH	Cracked	181.60 FL	-	*181.60 FL
37	1	*FENDER PANEL INNER TRIM REAR LH	Deformed	671.45 FL	-	*671.45 FL
38	1	*FENDER PANEL REAR RH	Buckled	1,933.20 FL	-	*1,933.20 FL
39	1	*WHEELARCH REAR RH	Serviceable	275.40 FL	-	*-FL
40	1	*FENDER PANEL INNER TRIM REAR RH	Bent	671.45 FL	-	*671.45 FL
41	1	*AIR VENT RH	Serviceable	59.40 FL	-	*-FL
42	1	*AIR VENT LH	Dented	59.40 FL	-	*59.40 FL
43	1	*TAILLAMP RH	Serviceable	401.40 FL	-	*-FL
44	1	*TAILLAMP PANEL RH	Repair	401.40 FL	-	*-FL
45	1	*TAILLAMP LH	Broken	401.40 FL	-	*401.40 FL
46	1	*TAILLAMP PANEL LH	Bent	401.40 FL	-	*401.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Reference	Amount
47	1	*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	-	*745.80 FL
48	1	*OUTER PANEL REAR (END PANEL) TRIM	Distorted	404.56 FL	-	*404.56 FL
49	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Bent/Buckled	1,229.40 FL	-	*1,229.40 FL
50	1	*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	-	*-FL
51	1	*SPARE TYRE BOARD	Serviceable	680.90 FL	-	*-FL
52	1	*SPARE WHEEL PANEL BRACKET LH L70Y	Repair	70.60 FL	-	*-FL
53	1	*SPARE WHEEL PANEL BRACKET RH L70Y	Repair	69.20 FL	-	*-FL
54	1	*EXHAUST REAR	Repair	5,263.60 FL	-	*-FL
55	1	*EXHAUST CAP REAR	Serviceable	125.40 FL	-	*-FL
56	1	*CHASSIS PANEL REAR LH	Repair	2,192.40 FL	-	*-FL
57	1	*FENDER PANEL INNER REAR LH L70Y	Bent	1,241.60 FL	-	*1,241.60 FL
58	1	*FENDER INNER BOARD LH L70Y	Repair	561.40 FL	-	*-FL
59	1	*FENDER WHEEL HOUSING PANEL REAR LH	Repair	4,682.09 FL	-	*-FL
60	1	*FUEL FLAP	Bent	244.70 FL	-	*244.70 FL
61	1	*FUEL TANK FILLER NECK	Serviceable	473.10 FL	-	*-FL
62	1	*FUEL TANK CAP	Serviceable	136.90 FL	-	*-FL
63	1	*FUEL TANK	Serviceable	2,748.95 FL	-	*-FL
64	1	*FUEL TANK PUMP	Serviceable	1,266.53 FL	-	*-FL
65	1	*FUEL PIPE SHORT	Serviceable	611.80 FL	-	*-FL
66	1	*FUEL PIPE LONG	Serviceable	1,148.12 FL	-	*-FL
67	1	*TUBE FILLER	Serviceable	297.19 FL	-	*-FL
68	1	*KNUCKLE ARM REAR RH L70Y	Serviceable	472.10 FL	-	*-FL
69	1	*BRAKE DISC REAR RH L70Y	Serviceable	266.50 FL	-	*-FL
70	1	*WHEEL HUB NUT L70Y	Serviceable	41.80 FL	-	*-FL
71	1	*WHEEL HUB CAP L70Y	Serviceable	30.50 FL	-	*-FL
72	1	*ABS SENSOR REAR RH L70Y	Serviceable	190.50 FL	-	*-FL
73	1	*REAR AXLE L70Y	Serviceable	3,469.00 FL	-	*-FL
74	1	*AXLE ARM RH L70Y	Serviceable	69.50 FL	-	*-FL
75	1	*REAR AXLE SPACER RH	Serviceable	49.00 FL	-	*-FL
76	1	*REAR AXLE ARM ROD RH	Serviceable	69.50 FL	-	*-FL
77	1	*LOWER ARM REAR RH L70Y	Serviceable	543.50 FL	-	*-FL
78	1	*AXLE SPRING ARM RH	Serviceable	220.60 FL	-	*-FL
79	1	*ABSORBER REAR RH	Serviceable	217.30 FL	-	*-FL
80	1	*ABSORBER DUST COVER REAR RH	Serviceable	47.10 FL	-	*-FL
81	1	*ABSORBER MOUNTING REAR RH	Serviceable	49.40 FL	-	*-FL
82	1	*STABILIZER BAR REAR	Serviceable	427.90 FL	-	*-FL
83	1	*STABILIZER LINK REAR RH	Serviceable	55.20 FL	-	*-FL
84	1	*BRAKE CALIPER REAR RH	Serviceable	659.10 FL	-	*-FL
85	2	*BRAKE CALIPER BRACKET REAR LH/RH	Serviceable	384.00 FL	-	*-FL
86	1	*BRAKE HOSE REAR RH	Serviceable	79.50 FL	-	*-FL
87	1	*KNUCKLE HUB + BEARING RH	Not Necessary	272.30 FL	-	*-FL
88	1	*SUBFRAME AMR REAR RH	Serviceable	198.33 FL	-	*-FL
89	1	*RODE-LONG REAR RH	Serviceable	120.16 FL	-	*-FL
90	1	*KNUCKLE ARM REAR LH L70Y	Serviceable	472.10 FL	-	*-FL
91	1	*BRAKE DISC REAR LH L70Y	Serviceable	266.50 FL	-	*-FL
92	1	*WHEEL HUB NUT L70Y	Serviceable	41.80 FL	-	*-FL
93	1	*WHEEL HUB CAP L70Y	Serviceable	30.50 FL	-	*-FL
94	1	*ABS SENSOR REAR LH L70Y	Serviceable	190.50 FL	-	*-FL
95	1	*AXLE ARM LH L70Y	Serviceable	69.50 FL	-	*-FL
96	1	*REAR AXLE ARM ROD LH	Serviceable	69.50 FL	-	*-FL
97	1	*LOWER ARM REAR LH L70Y	Serviceable	543.50 FL	-	*-FL
98	1	*AXLE SPRING ARM LH	Serviceable	220.60 FL	-	*-FL
99	1	*ABSORBER REAR LH	Serviceable	217.30 FL	-	*-FL
100	1	*ABSORBER DUST COVER REAR LH	Serviceable	47.10 FL	-	*-FL
101	1	*ABSORBER MOUNTING REAR LH	Serviceable	49.40 FL	-	*-FL
102	1	*BRAKE CALIPER REAR LH	Serviceable	659.10 FL	-	*-FL
103	2	*BRAKE CALIPER BRACKET REAR LH/RH	Serviceable	384.00 FL	-	*-FL
104	1	*BRAKE HOSE REAR LH	Serviceable	79.50 FL	-	*-FL
105	1	*KNUCKLE HUB + BEARING LH	Not Necessary	272.30 FL	-	*-FL
106	1	*SUBFRAME ARM REAR LH	Serviceable	198.33 FL	-	*-FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Reference	Amount
107	1	*RODE-LONG REAR LH	Serviceable	120.16 FL	-	*-FL
108	1	*REAR AXLE SPACER LH	Serviceable	49.00 FL	-	*-FL
109	1	*STABILIZER LINK REAR LH	Serviceable	55.20 FL	-	*-FL
110	1	*BRAKE PAD REAR	Serviceable	145.60 FL	-	*-FL
111	1	*WINDSCREEN REAR L70Y	Shattered	817.20 FL	-	*817.20 FL
112	1	*WINDSCREEN GARNISH INNER LH	Distorted	257.40 FL	-	*257.40 FL
113	1	*WINDSCREEN GARNISH INNER RH	Serviceable	257.40 FL	-	*-FL
114	1	*WINDSCREEN LOWER GRILLE COVER	Serviceable	310.60 FL	-	*-FL
115	1	*SHELF ASSY (WINDSCREEN UNDER PANEL)	Repair	443.76 FL	-	*-FL
116	1	*SHELF AR	Serviceable	730.60 FL	-	*-FL
117	1	*EXTENSION-RR LH SIDE MEMBER	Repair	247.69 FL	-	*-FL
118	1	*EXTENSION-RR RH SIDE MEMB	Repair	245.79 FL	-	*-FL
119	1	*DOOR PANEL REAR RH	Repair	758.70 FL	-	*-FL
120	1	*DOOR LOCK REAR RH L70Y	Repair	467.30 FL	-	*-FL
121	1	*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	-	*-FL
122	1	*ROCKER PANEL INNER LH	Repair	1,024.79 FL	-	*-FL
123	1	*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	-	*-FL
124	1	*DOOR PANEL REAR LH	Repair	758.70 FL	-	*-FL
125	1	*DOOR LOCK REAR LH L70Y	Repair	468.20 FL	-	*-FL
126	2	*DOOR CATCH REAR LH/RH	Repair	73.70 FL	-	*-FL
127	1	*DOOR FINISHER REAR LH	Serviceable	230.30 FL	-	*-FL
128	1	*DOOR WEATHERSTRIP REAR LH L70Y	Serviceable	240.50 FL	-	*-FL
129	1	*DOOR SEAL REAR LH	Serviceable	119.40 FL	-	*-FL
130	1	*DOOR WAIST SEAL OUTER REAR LH	Serviceable	116.10 FL	-	*-FL
131	1	*ROOF PANEL	Repair	2,900.70 FL	-	*-FL
132	1	*ROOF SIDE PANEL OUTER LH	Repair	704.21 FL	-	*-FL
133	1	*ROOF TOP CHANNEL MOLDING LH	Serviceable	291.27 FL	-	*-FL
134	1	*ROOF TOP CHANNEL MOLDING RH	Serviceable	291.27 FL	-	*-FL
135	1	*SET PARKING AID	Dented	700.00 FS	-	*400.00 FS
136	1	*SET REAR BUMPER CLIP	Necessary	66.00 FS	-	*66.00 FS
137	1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	-	*33.00 FS
138	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	-	*-FS
139	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	-	*-FS
140	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	-	*-FS
141	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	-	*-FS
142	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	-	*-FS
143	1	*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	-	*66.00 FS
144	1	*EXHAUST MOUNTING REAR	Not Necessary	16.00 FS	-	*-FS
145	1	*SET BOOT FINISHER CLIP	Necessary	24.20 FS	-	*24.20 FS
146	1	*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	-	*30.00 FS
147	1	*BOOT STICKER 6555-3333	Necessary	30.00 FS	-	*30.00 FS
148	1	*BOOT INNER TRIM CLIP	Necessary	45.00 FS	-	*45.00 FS
149	1	*SET FENDER WHEELARCH REAR RH CLIP	Necessary	35.00 FS	-	*35.00 FS
150	1	*SET FENDER WHEELARCH REAR LH CLIP	Necessary	35.00 FS	-	*35.00 FS
151	1	*FENDER INNER TRIM CLIP LH	Necessary	28.00 FS	-	*28.00 FS
152	1	*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	-	*-FS
153	1	*TAILLAMP CLIP RH	Not Necessary	5.00 FS	-	*-FS
154	1	*TAILLAMP CLIP LH	Necessary	5.00 FS	-	*5.00 FS
155	1	*WINDSCREEN MOULDING	Not Necessary	160.00 FS	-	*-FS
156	1	*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	100.00 FS	-	*30.00 FS
157	1	*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	-	*-FS
158	1	*SPARE TYRE	Serviceable	330.00 FS	-	*-FS
159	1	*RIGHT REAR TYRE	Serviceable	330.00 FS	-	*-FS
160	1	*RIGHT REAR TYRE RIM	Serviceable	380.00 FS	-	*-FS
161	1	*RIGHT LEFT TYRE (50%)	Punctured	330.00 FS	-	*165.00 FS
162	1	*RIGHT LEFT TYRE RIM	Serviceable	380.00 FS	-	*-FS
163	1	*EXHAUST BRACKET REAR	Repair	24.80 FS	-	*-FS
164	1	*REAR RH DOOR STICKER 6555-3333	Not Necessary	100.00 FS	-	*-FS
165	1	*REAR LH DOOR STICKER 6555-3333	Not Necessary	100.00 FS	-	*-FS
166	1	*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	-	*-FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
167	1		*SET REAR LICENCE PLATE WITH HOLDER	Serviceable	100.00 FS	-	*- FS
168	2		*BOOT LOCK SCREW	Serviceable	6.10 FS	-	*- FS
169	2		*BOOT LOCK CATCH SCREW	Serviceable	12.50 FS	-	*- FS
170	1		*BOOT WEATHERSTRIP (50%)	Distorted	160.38 FS	-	*89.10 FS
171	2		*WINDSCREEN SEALANT	Necessary	98.28 FS	-	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	69,520.57	18,622.86
- List Item Discount on L Items 10.00/10.00% (\$)	6,519.53	1,750.16
Total Parts (\$)	63,001.04	16,872.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	9,900.00	1,760.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	9,900.00	2,400.00
3	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	60.00
4	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	350.00	120.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	150.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST)	New	170.00	80.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING)	New	380.00	0.00
11	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
12	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
13	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
14	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
15	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
16	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
17	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	250.00
18	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
19	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
20	TOWING FEES	New	150.00	50.00
21	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	350.00	0.00
22	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	220.00
23	TO DROP DIESEL/PETROL TANK,PIPES,HOSES AND RENEW THE NECESSARY PARTS AND FINAL CHECKING AND TESTING FOR LEAK	New	440.00	60.00
24	TO DISMANTLE AND REFIT REAR AXLE ASSY,REMOVE AND RENEWAL OF PARTS,FINAL CHECKING AND TESTING	New	380.00	0.00
25	TO CHECK ABS AND BRAKE EFFICIENCY,FINAL CHECKING AND TESTING	New	380.00	0.00
26	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING	New	380.00	0.00
27	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
Gross Labour Cost (\$\$)			26,390.00	5,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >