

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG20002836/ATD3E2

Date: 22/04/2020

REFERENCE

Insured/Claimant:	GOH YEO YIN	Policy No:	1900139726	
Date of Loss:	16/02/2020	Nature of Claim:	OD	Claim No: 9157140284SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ901H		
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Engine No:	CHZB23499
Reg. Date:	24/07/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8V9KA090969
Colour:	Green	Odometer:	8382 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,810.64	10,428.40	8,382.24	44.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,642.00	4,302.00	4,340.00	50.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,452.64	14,730.40	12,722.24	46.34
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	26,852.64	14,130.40	12,722.24	47.38
+ GST 7.00/7.00% (S\$)	1,879.68	989.13	890.55	47.38
Nett Amount (S\$)	28,732.32	15,119.53	13,612.79	47.38

INSPECTION

Date of Assignment:	19/02/2020		
Date Inspected:	18/02/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,756.00 FS	*1,404.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	176.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	36.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Cracked	151.00 FS	*120.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	280.00 FS	*223.60 FS
6	1		*FRONT BUMPER CLOSING ELEMENT - RH	Cracked	280.00 FS	*223.60 FS
7	1		*RADIATOR GRILLE	Cracked	1,338.00 FS	*1,070.40 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Deformed	177.00 FS	*141.20 FS
9	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	681.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	178.00 FS	*- FS
11	1		*FOAM FILLER PIECE COVER	Not Necessary	115.00 FS	*- FS
12	1		*AIRCON STICKER	Necessary	7.00 FS	*5.36 FS
13	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.24 FS
14	1		*SIGNAL HORN RETAINER - RH LOW TONE	Not Necessary	188.00 FS	*- FS
15	1		*WHEEL HOUSING LINER - RH	Deformed	159.00 FS	*127.20 FS
16	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	54.00 FS	*- FS
17	1		*LED HEADLIGHT - RH	Cut	5,193.00 FS	*4,154.40 FS
18	1		*LIFT CYLINDER - RH	Not Necessary	134.00 FS	*- FS
19	1		*NOISE INSULATION	Cracked	244.00 FS	*195.20 FS
20	1		*LOCK CARRIER	Cracked	685.00 FS	*547.60 FS
21	1		*AIRCON CONDENSER	Not Necessary	519.00 FS	*- FS
22	1		*REFRIGERANT LINE	Not Necessary	613.00 FS	*- FS
23	1		*REFRIGERANT LINE	Not Necessary	471.00 FS	*- FS
24	1		*ADDITIONAL RADIATOR	Not Necessary	851.00 FS	*- FS
25	1		*READY MIX COOLANT	Necessary	169.00 FS	*134.72 FS
26	1		*RADIATOR AIR GUIDE - RH	Cracked	23.00 FS	*18.16 FS
27	1		*FRONT NO PLATE	Necessary	40.00 FS	*40.00 FS
28	1		*SUNDRIES	Necessary	300.00 FS	*154.88 FS
29	1		*RADIATOR	Dented	745.20 FS	*745.20 FS
30	1		*RADIATOR FAN WITH FAN RING	Broken	856.00 FS	*856.00 FS
31	1		*RADIATOR SEAL RIGHT OUTER	Crumpled	5.92 FS	*5.92 FS
32	1		*COOLANT HOSE WITH QUICK RELEASE COUPLING LOWER	Torn	102.40 FS	*102.40 FS
33	1		*WHEEL HOUSING LINER LHS	Torn	127.20 FS	*127.20 FS
34	1		*A/C COMPRESSOR	Not Necessary	2,123.00 FS	*- FS
35	1		*HEXAGON BOLT	Necessary	19.92 FS	*19.92 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (\$)	18,810.64	10,428.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
3	TO REMOVE AND RENEW AIRCOND CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
4	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,850.00	2,000.00
5	TO CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REMOVE AND RENEW A/C COMPRESSOR	New	480.00	0.00
8	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	550.00
Gross Labour Cost (S\$)			8,642.00	4,302.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >