

CC3/Ala 20002836/Atd3

ASSIGNMENT

MEMMEN

Estimate No. _____ Date: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV _____
 To Item of Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess: **600**
 (Client's Record)
 Make of Veh: _____

Veh No: **SKZ901H** Reg: **2014 July**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Audi A3 SB** cc: **999**
 Colour: **Green** A/C: Insured / Std / NI / NA
 Sp. Reading: **8382** T/Radio: Insured / Std / NI / NA
 Eng No: _____
 C/No: **WAUZZZ8V9KA090969**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Tyre Size: F: **205/55R16**
 R: **205/55R16**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TCYO / YOKO or
 Front Rear
 R/Bal. **06** mm R/Bal. **06** mm
 L/Bal. **06** mm L/Bal. **06** mm
 D.O.A. _____ D.O.I. **18/02/20**
 Survey held at **Premium**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

| Date / Time | Action / Instruction |
|-------------|---|
| | 00 ALB |
| | SKZ 901H - (CC3/Ala/19014295/Atf3e2) DOR: 10/08/2019 |
| | MV: 100K 19/2 - Revert via memmen |
| | PV: 45.6K 20/2 - 16:50 mandate request approval |
| | Nett: 54.4K 20/2 @ 4:57pm email premium authorise |
| | Excess \$600 - |
| | Part by Part \$14,730.40 cred: |

Date/Time, File Pass to? Prel. Report Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3+PS: _____

Excess: _____

Other: _____

Artd Fee: Site Insp. (\$) Interview (\$) Tech. Insp. (\$) Wash up (\$)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 29789

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0179/2020/NS
Date : 18-Feb-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Goh Yeo Yin
Address : Blk 12B Hougang Street 11
#07-62
Singapore 534073
Telephone : +65 98263464
Type of Claim : Own Damage Claims
Policy No. : 1900139726
Vehicle No : **SKZ 901 H**
Model Code : Audi A3 Sportsback 1.0 TF
Model / Year : Jul-19
Engine No : CHZ B23499
Chassis No : WAUZZZ8V9KA090969
Mileage : 8382
Date In : 17-Feb-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Feb-20
Place of Accident : Upper Paya Lebar

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKZ 901 H

| S/N | Nature of Jobs | | Estimated Charges | Surveyor's Recommendations |
|---------------------------------|---|----------|---------------------|--|
| 1 | To tow vehicle from scene of accident | S/N \$ | 280.00 | X |
| 2 | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy. | S/N \$ | 360.00 | ✓ |
| 3 | To remove and renew aircond condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas. | S/N \$ | 1,200.00 | ? ✓ |
| 4 | To dismantle and renew front bumper and rhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. | \$ | 3,850.00 | 750 (Without Lock Carrier) ✓ 2000 (With Lock Carrier) |
| SUB TOTAL LABOUR CHARGES | | : | \$ 5,690.00 | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKZ 901 H

| <u>S/N</u> | <u>Nature of Jobs</u> | | <u>Estimated Charges</u> | <u>Surveyor's Recommendations</u> |
|-----------------------------|--|-----|-----------------------------|-----------------------------------|
| 5 | To respray front bumper and rhs front fender. ✓ X | | \$ 2,000.00 | 550 ✓ |
| 6 | To carry out wheel lignment. | S/N | \$ 280.00 | X |
| 7 | To carry out diagnostic check. | S/N | \$ 192.00 | ✓ ✓ |
| TOTAL LABOUR CHARGES | | | : \$ <u>8,162.00</u> | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKZ 901 H

| S/N | Parts Description | Damage Parts & Prices | |
|--------------------------------------|---|-----------------------|------------------|
| | | S/Nett | Remarks |
| 1 | FRONT BUMPER <i>distld</i> | \$ 1,756.00 | ✓ 1404.80 |
| 2 | FRONT BUMPER FIXING PARTS <i>the new</i> | \$ 176.00 | ? X |
| 3 | FRONT BUMPER GUIDE SECTION - RH <i>new</i> | \$ 36.00 | + X |
| 4 | FRONT BUMPER GRILLE - CENTRE <i>could</i> | \$ 151.00 | — 120.40 |
| 5 | FRONTBUMPER CLOSING ELEMENT - LOWER CENTRE <i>could</i> | \$ 280.00 | — 223.60 |
| 6 | FRONTBUMPER CLOSING ELEMENT - RH <i>could</i> | \$ 280.00 | — 223.60 |
| 7 | RADIATOR GRILLE <i>could</i> | \$ 1,338.00 | — 1070.40 |
| 8 | FRONT BUMPER AIR GUIDE GRILLE - RH <i>del'd</i> | \$ 177.00 | — 141.20 |
| 9 | FRONT BUMPER SIDE REINFORCEMENT BEAM <i>the new</i> | \$ 681.00 | ? X |
| 10 | FRONT BUMPER FOAM FILLER PIECE <i>the new</i> | \$ 178.00 | ? X |
| 11 | FOAM FILLER PIECE COVER <i>the new</i> | \$ 115.00 | ? X |
| 12 | AIRCON STICKER <i>the new</i> | NEC \$ 7.00 | — 5.36 |
| 13 | CAUTION SIGN STICKER <i>the new</i> | NEC \$ 13.00 | — 10.24 |
| 14 | SIGNAL HORN RETAINER - RH LOW TONE <i>the new</i> | \$ 188.00 | ? X |
| 15 | WHEEL HOUSING LINER - RH <i>del'd</i> | \$ 159.00 | — 127.20 |
| 16 | WHEEL HOUSING LINER ATTACHMENT PARTS <i>the new</i> | \$ 54.00 | ? X |
| 17 | LED HEADLIGHT - RH <i>cut</i> | \$ 5,193.00 | ✓ 4154.40 |
| 18 | LIFT CYLINDER - RH <i>the new</i> | \$ 134.00 | ? X |
| 19 | NOISE INSULATION <i>could</i> | \$ 244.00 | ? 195.20 |
| 20 | LOCK CARRIER <i>could</i> | \$ 685.00 | ? 547.60 |
| SUB TOTAL SPARE PARTS CHARGES | | : \$ | 11,845.00 |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKZ 901 H

| S/N | Parts Description | Damage Parts & Prices | | Remarks |
|----------------------------------|------------------------------------|-----------------------|---------------------|----------|
| | | S/Nett | | |
| 21 | AIRCON CONDENSER <i>new</i> | \$ | 519.00 | X |
| 22 | REFRIGERANT LINE <i>new</i> | \$ | 613.00 | X |
| 23 | REFRIGERANT LINE <i>new</i> | \$ | 471.00 | X |
| 24 | ADDITIONAL RADIATOR <i>new</i> | \$ | 851.00 | X |
| 25 | READY MIX COOLANT <i>new</i> | \$ | 169.00 | > 134.72 |
| 26 | RADIATOR AIR GUIDE - RH <i>new</i> | \$ | 23.00 | ? 18.16 |
| 27 | FRONT NO PLATE <i>new</i> | S/N \$ | 40.00 | ✓ 40 |
| 28 | SUNDRIES <i>new</i> | \$ | 300.00 | ? 154.88 |
| TOTAL SPARE PARTS CHARGES | | : | \$ 14,831.00 | |
| TOTAL LABOUR CHARGES | | : | \$ 8,162.00 | |
| GRAND TOTAL | | : | \$ 22,993.00 | |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan Lj
Surveyed Date : 18/02/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

04 Days (Without Lock Carried)
07 Days (With Lock Carried)

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0179/2020/NS
Date 24-Feb-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SKZ 901 H
Model No Audi A3 Sportsback 1.0 TF

| Quantity | Description | Unit Price | Amount |
|--------------|--|-------------|---------------|
| <u>Parts</u> | | | |
| 1 | Radiator / <i>OD</i> | \$ 932.00 | <i>745.20</i> |
| 2 | Radiator fan with fan ring / <i>DR</i> | \$ 1,070.00 | <i>856</i> |
| 3 | Radiator seal right outer / <i>CRU</i> | \$ 8.00 | <i>5.92</i> |
| 4 | Coolant hose with quick release coupling lower / <i>TN</i> | \$ 128.00 | <i>102.40</i> |
| 5 | Wheel housing liner LHS / <i>TN</i> | \$ 159.00 | <i>127.20</i> |
| 6 | A/C compressor <i>He nu</i> | \$ 2,123.00 | <i>X</i> |
| 7 | Hexagon bolt <i>He nu</i> | \$ 25.00 | <i>19.92</i> |

Labours

| | | | |
|---|-------------------------------------|---------------|----------|
| 1 | To remove and renew A/C Compressor. | S/N \$ 480.00 | <i>X</i> |
|---|-------------------------------------|---------------|----------|

TOTAL \$ 4,925.00

For Premium Automobiles Pte Ltd

Steve (CLKK)
24/2/20, 2.39pm

Authorised Signature

12/3
t

$$\begin{aligned} & 0 \cdot c \\ & 360 \cdot + \\ & 1,200 \cdot + \\ & 2,000 \cdot + \\ & = \\ & 3,560 \cdot * \end{aligned}$$

$$\begin{aligned} & 0 \cdot c \\ & 550 \cdot + \\ & 192 \cdot + \\ & = \\ & 742 \cdot * \end{aligned}$$

$$\begin{aligned} & 0 \cdot c \\ & 1,404 \cdot 8+ \\ & 120 \cdot 4+ \\ & 223 \cdot 6+ \\ & 223 \cdot 6+ \\ & 1,070 \cdot 4+ \\ & 141 \cdot 2+ \\ & 5 \cdot 36+ \\ & 10 \cdot 24+ \\ & 127 \cdot 2+ \\ & 4,154 \cdot 4+ \\ & 195 \cdot 2+ \\ & 547 \cdot 6+ \\ & 134 \cdot 72+ \\ & 18 \cdot 16+ \\ & 40 \cdot + \\ & 154 \cdot 28+ \\ & = \\ & 8,571 \cdot 76* \end{aligned}$$

$$\begin{aligned} & 0 \cdot c \\ & 745 \cdot 2+ \\ & 856 \cdot + \\ & 5 \cdot 92+ \\ & 102 \cdot 4+ \\ & 127 \cdot 2+ \\ & 10 \cdot 92+ \\ & = \\ & 1,856 \cdot 64* \end{aligned}$$

$$\begin{aligned} & 0 \cdot c \\ & 0 \cdot c \\ & 3,560 \cdot + \\ & 742 \cdot + \\ & 8,571 \cdot 76+ \\ & 1,856 \cdot 64+ \\ & = \\ & 14,730 \cdot 4* \end{aligned}$$