



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2007622  
INV Date 12/11/2020  
Reference CC4/FCI20002861/Kka3s2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. PA 4355E  
Insured Veh. SHA 8067E  
Claim No. D20001066MFSH/1  
Policy No. D-20094921MFSH  
Accident Date 14/02/2020  
Inspection Date 18/02/2020

Description	Total
Third Party Express Settlement	600.00
<b>Subtotal</b>	<b>600.00</b>
<b>GST (7%)</b>	<b>42.00</b>
<b>Grand Total</b>	<b>642.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20002861/Kka3s2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 12-11-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHA 8067E	<b>Veh. Inspected</b>	PA 4355E
<b>Policy No.</b>	D-20094921MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D20001066MFSH/1	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	MERINA CHIA	<b>Assign Date</b>	18/02/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	NISSAN URVAN (M)	<b>c.c</b>	2953
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2003
<b>Chassis No.</b>	JN1TG4E25Z0700405	<b>Colour</b>	SILVER
<b>Odometer</b>	475473	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195 R15X8	OHTSU	8 mm
<b>L/H Front Tyre</b>	195 R15X8	OHTSU	8 mm
<b>R/H Rear Tyre</b>	195 R15X8	CHAO YANG	9 mm
<b>L/H Rear Tyre</b>	195 R15X8	CHAO YANG	9 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	14/02/2020	<b>Inspection Date</b>	18/02/2020
<b>Survey held at</b>	TROPICAL TECH AUTOMOBILE SERVICES BLK 5032, ANG MO KIO AVENUE 3 #01-303 IND. PARK 2 SINGAPORE 569535		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **11 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 4355E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT WINDSCREEN	SERVICEABLE	1,443.00	-
1	FRONT WINDSCREEN RUBBER	NO SUCH PARTS	165.00	-
1	FRONT WINDSCREEN MOULDING	NECESSARY	198.00	198.00
1	FRONT WIPER PANEL GARNISH	SERVICEABLE	375.00	-
1	FRONT PANEL	BENT	1,288.00	1,288.00
2	FRONT CORNEL PANEL @ \$300.00	TO REPAIR SEE LABOUR	600.00	-
1	FRONT GRILLE	CRACKED	611.00	611.00
1	SET FRONT GRILLE CLIP	NECESSARY	86.00	86.00
1	FRONT GRILLE EMBLEM	NECESSARY	123.00	123.00
2	FRONT HEAD-LAMP @ \$411.00	MTG BROKEN	822.00	822.00
2	FRONT SIGNAL LAMP @ \$174.00	CRACKED	348.00	348.00
1	FRONT BUMPER	BUCKLED	621.00	621.00
2	FRONT BUMPER FOG LAMP @ \$367.00	SERVICEABLE	734.00	-
2	FRONT BUMPER FOG LAMP GRILLE @ \$123.00	SERVICEABLE	246.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	495.00	495.00
1	REAR WINDSCREEN	SERVICEABLE	1,221.00	-
1	REAR WINDSCREEN RUBBER	NO SUCH PARTS	165.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	165.00	165.00
1	REAR BOOT	BENT	1,998.00	1,998.00
1	REAR BOOT OUTER HANDLE	SERVICEABLE	411.00	-
2	REAR BOOT DAMPER @ \$278.00	SERVICEABLE	556.00	-
1	REAR BOOT UPPER LOCK	DENTED	489.00	489.00
2	REAR TAIL LAMP @ \$255.00	CRACKED	510.00	510.00
1	REAR END PANEL	BENT	405.00	405.00
1	REAR BUMPER (STEP BOARD)	DENTED	285.00	285.00
1	REAR BUMPER PARKING SENSOR	CRACKED	200.00	200.00
2	REAR BUMPER SIDE BRACKET @ \$36.00	BENT	72.00	72.00
1	REAR SILENCER BOX (TAIL PIPE)	BENT	1,221.00	1,221.00
1	RADIATOR SUPPORT PANEL	NOT NECESSARY	465.00	-
1	AIR CON COOLING COIL AIR DUCT (NPA) (ADDITIONAL)	CRACKED	-	-

Report Ref No. CC4/FCI20002861/Kka3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	AIR CON COOLING COIL CASING (NPA) (ADDITIONAL)	CRACKED	-	-
2	HEATER COOLING COIL CASING (NPA) (ADDITIONAL)	CRACKED	-	-
1	HEATER COOLING COIL HOSE (SHORT) (ADDITIONAL)	DENTED	40.00	40.00
	LESS 10% DISCOUNT		-1,635.80	-997.70
			14,722.20	8,979.30
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT LICENCE SMART PLATE (SN)	BENT	35.00	20.00
1	REAR BOOT EMBLEM (SN)	NECESSARY	123.00	123.00
1	REAR BOOT '70 KMH' LABEL (SN)	NECESSARY	15.00	15.00
1	REAR BOOT 'EMERGENCY DOOR' LABEL (SN)	NECESSARY	15.00	15.00
1	REAR BOOT 'PULL TO OPEN' LABEL (SN)	NECESSARY	15.00	15.00
1	BTE AIR CON COMPRESSOR OIL TREATMENT. FILLING AIR CON 134A GAS (SN) (ADDITIONAL) }	NECESSARY	150.00	10.00
1	BTE CONDUCT AIR CON VACUUM TEST COOLANT (SN) (ADDITIONAL) }		30.00	-
			383.00	198.00
	<b><u>LABOUR</u></b>			
	REMOVE AND REFIT FRONT DASH-BOARD. INCLUSIVE OF THE REPAIR OF FRONT CORNELL PANEL.		300.00	250.00
			300.00	250.00
	<b>GRAND TOTAL</b>		<b>15,405.20</b>	<b>9,427.30</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>8,400.00</b>

Report Ref No. CC4/FCI20002861/Kka3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PA 4355E

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PA 4355E

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PA 4355E

RE-INSPECTION

