

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Feb 2020 Edit Reg		19 Feb 2020 00:00 Edit Adj Rpt	S\$19,450.00 Edit Estimates	S\$19,450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: HU HAO , Co. Reg. No.: -									
Main Claimant: YIP KAI SUM									
Vehicle Reg. No.: SMK33T		Date of Loss: 07/02/2020 22:00 - :59 [15 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 9431867560SG		Policy/Cover Note No.: 1800103682 (Comprehensive)							
Vehicle Reg. No. (Insured): SMD7478J		Policy No. (Claimant):							
		Excess:							
Repairer: SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 28/02/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
- AIG_SG_EXPRESS (25/08/2020): Alert - Adj Mandate Approved (S\$22750.00) - SMK33T - Claim Handler: Tan, Bennie-... - AIG_SG_EXPRESS (11/08/2020): Alert - Adj Mandate Maintained - SMK33T - Claim Handler: Tan, Bennie-WZ									
ALL ASSOCIATED TASKS ▾				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMK33T (9431867560SG)**
[SMD7478J]
TP
YIP KAI SUM
Feb 7 2020 10:00PM
[HU HAO]
SK Automobile Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/08/20 00:46	OI Video - Accident (rear)	Load AVI	
Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/03/20 20:58	Odometer Reading	Load JPG	☒
2	24/03/20 20:58	General View	Load JPG	☒
3	24/03/20 20:58	General View	Load JPG	☒
4	24/03/20 20:58	General View	Load JPG	☒
5	24/03/20 20:58	General View	Load JPG	☒
6	24/03/20 20:58	General View	Load JPG	☒
7	24/03/20 20:58	General View	Load JPG	☒
8	24/03/20 20:58	General View	Load JPG	☒
9	24/03/20 20:58	General View	Load JPG	☒
10	24/03/20 20:58	General View	Load JPG	☒
11	24/03/20 20:58	General View	Load JPG	☒
12	24/03/20 20:58	General View	Load JPG	☒
13	24/03/20 20:58	General View	Load JPG	☒
14	24/03/20 20:58	General View	Load JPG	☒
15	24/03/20 20:58	General View	Load JPG	☒
16	24/03/20 20:58	General View	Load JPG	☒
17	24/03/20 20:58	General View	Load JPG	☒
18	24/03/20 20:58	General View	Load JPG	☒
19	24/03/20 20:58	General View	Load JPG	☒
20	24/03/20 20:58	General View	Load JPG	☒
21	24/03/20 20:58	General View	Load JPG	☒
22	24/03/20 20:58	General View	Load JPG	☒
23	24/03/20 20:58	General View	Load JPG	☒
24	24/03/20 20:58	General View	Load JPG	☒
25	24/03/20 20:58	General View	Load JPG	☒
26	24/03/20 20:58	General View	Load JPG	☒
27	24/03/20 20:58	General View	Load JPG	☒
28	24/03/20 20:58	General View	Load JPG	☒
29	24/03/20 20:59	General View	Load JPG	☒
30	24/03/20 20:59	General View	Load JPG	☒
31	24/03/20 20:59	General View	Load JPG	☒
32	24/03/20 20:59	General View	Load JPG	☒
33	24/03/20 20:59	General View	Load JPG	☒
34	24/03/20 20:59	General View	Load JPG	☒

Video				1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
35	24/03/20 20:59	General View		Load JPG	☒
36	24/03/20 20:59	General View		Load JPG	☒
37	24/03/20 20:59	General View		Load JPG	☒
38	24/03/20 20:59	General View		Load JPG	☒
39	24/03/20 20:59	General View		Load JPG	☒
40	24/03/20 20:59	General View		Load JPG	☒
41	24/03/20 20:59	General View		Load JPG	☒
42	24/03/20 20:59	General View		Load JPG	☒
43	24/03/20 20:59	General View		Load JPG	☒
44	24/03/20 20:59	General View		Load JPG	☒
45	24/03/20 20:59	General View		Load JPG	☒
46	24/03/20 20:59	General View		Load JPG	☒
47	24/03/20 20:59	General View		Load JPG	☒
48	24/03/20 20:59	General View		Load JPG	☒
49	24/03/20 20:59	General View		Load JPG	☒
50	24/03/20 20:59	General View		Load JPG	☒
51	24/03/20 20:59	General View		Load JPG	☒
52	24/03/20 20:59	General View		Load JPG	☒
53	24/03/20 20:59	General View		Load JPG	☒
54	24/03/20 20:59	General View		Load JPG	☒
55	24/03/20 20:59	General View		Load JPG	☒
56	24/03/20 20:59	General View		Load JPG	☒
57	24/03/20 20:59	General View		Load JPG	☒
58	24/03/20 20:59	General View		Load JPG	☒
59	24/03/20 20:59	General View		Load JPG	☒
60	24/03/20 20:59	General View		Load JPG	☒
61	24/03/20 20:59	General View		Load JPG	☒
62	24/03/20 20:59	General View		Load JPG	☒
63	24/03/20 20:59	General View		Load JPG	☒
64	24/03/20 20:59	General View		Load JPG	☒
65	24/03/20 20:59	General View		Load JPG	☒
66	24/03/20 20:59	General View		Load JPG	☒
67	24/03/20 20:59	General View		Load JPG	☒
68	24/03/20 20:59	General View		Load JPG	☒
69	24/03/20 21:00	General View		Load JPG	☒
70	24/03/20 21:00	General View		Load JPG	☒
71	24/03/20 21:00	General View		Load JPG	☒
72	24/03/20 21:00	General View		Load JPG	☒
73	24/03/20 21:00	General View		Load JPG	☒
74	24/03/20 21:00	General View		Load JPG	☒
75	24/03/20 21:00	General View		Load JPG	☒
76	24/03/20 21:00	General View		Load JPG	☒
77	24/03/20 21:00	General View		Load JPG	☒
78	24/03/20 21:00	General View		Load JPG	☒
79	24/03/20 21:00	General View		Load JPG	☒
80	24/03/20 21:00	General View		Load JPG	☒
81	24/03/20 21:00	General View		Load JPG	☒
82	24/03/20 21:00	General View		Load JPG	☒
83	24/03/20 21:00	General View		Load JPG	☒
84	24/03/20 21:00	General View		Load JPG	☒
85	24/03/20 21:00	General View		Load JPG	☒
86	24/03/20 21:00	General View		Load JPG	☒
87	24/03/20 21:00	General View		Load JPG	☒

Video				1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
88	24/03/20 21:00	General View		Load JPG	☒
89	24/03/20 21:00	General View		Load JPG	☒
90	24/03/20 21:00	General View		Load JPG	☒
91	24/03/20 21:01	Reinspection Photo		Load JPG	☒
92	24/03/20 21:01	Reinspection Photo		Load JPG	☒
93	24/03/20 21:01	Reinspection Photo		Load JPG	☒
94	24/03/20 21:01	Reinspection Photo		Load JPG	☒
95	24/03/20 21:01	Reinspection Photo		Load JPG	☒
96	24/03/20 21:01	Reinspection Photo		Load JPG	☒
97	24/03/20 21:01	Reinspection Photo		Load JPG	☒
98	24/03/20 21:01	Reinspection Photo		Load JPG	☒
99	24/03/20 21:01	Reinspection Photo		Load JPG	☒
100	24/03/20 21:01	Reinspection Photo		Load JPG	☒
101	24/03/20 21:01	Reinspection Photo		Load JPG	☒
102	24/03/20 21:01	Reinspection Photo		Load JPG	☒
103	24/03/20 21:01	Reinspection Photo		Load JPG	☒
104	24/03/20 21:01	Reinspection Photo		Load JPG	☒
105	24/03/20 21:01	Reinspection Photo		Load JPG	☒
106	24/03/20 21:01	Reinspection Photo		Load JPG	☒
107	24/03/20 21:01	Reinspection Photo		Load JPG	☒
108	24/03/20 21:01	Reinspection Photo		Load JPG	☒
109	24/03/20 21:01	Reinspection Photo		Load JPG	☒
110	24/03/20 21:01	Reinspection Photo		Load JPG	☒
111	24/03/20 21:01	Reinspection Photo		Load JPG	☒
112	24/03/20 21:01	Reinspection Photo		Load JPG	☒
113	24/03/20 21:01	Reinspection Photo		Load JPG	☒
114	24/03/20 21:01	Reinspection Photo		Load JPG	☒
115	24/03/20 21:01	Reinspection Photo		Load JPG	☒
116	24/03/20 21:01	Reinspection Photo		Load JPG	☒
117	24/03/20 21:01	Reinspection Photo		Load JPG	☒
118	24/03/20 21:01	Reinspection Photo		Load JPG	☒
119	24/03/20 21:01	Reinspection Photo		Load JPG	☒
120	24/03/20 21:01	Reinspection Photo		Load JPG	☒
121	24/03/20 21:01	Reinspection Photo		Load JPG	☒
122	24/03/20 21:01	Reinspection Photo		Load JPG	☒
123	24/03/20 21:01	Reinspection Photo		Load JPG	☒
124	24/03/20 21:01	Reinspection Photo		Load JPG	☒
125	24/03/20 21:01	Reinspection Photo		Load JPG	☒
126	24/03/20 21:01	Reinspection Photo		Load JPG	☒
127	24/03/20 21:01	Reinspection Photo		Load JPG	☒
128	24/03/20 21:01	Reinspection Photo		Load JPG	☒
129	24/03/20 21:01	Reinspection Photo		Load JPG	☒
130	24/03/20 21:01	Reinspection Photo		Load JPG	☒
131	24/03/20 21:01	Reinspection Photo		Load JPG	☒
132	24/03/20 21:01	Reinspection Photo		Load JPG	☒
133	24/03/20 21:01	Reinspection Photo		Load JPG	☒
134	24/03/20 21:01	Reinspection Photo		Load JPG	☒
135	24/03/20 21:01	Reinspection Photo		Load JPG	☒
136	24/03/20 21:01	Reinspection Photo		Load JPG	☒
137	24/03/20 21:01	Reinspection Photo		Load JPG	☒
138	24/03/20 21:01	Reinspection Photo		Load JPG	☒
139	24/03/20 21:01	Reinspection Photo		Load JPG	☒
140	24/03/20 21:01	Reinspection Photo		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
141	24/03/20 21:02	Reinspection Photo		Load JPG	☒
142	24/03/20 21:02	Reinspection Photo		Load JPG	☒
143	24/03/20 21:02	Reinspection Photo		Load JPG	☒
144	24/03/20 21:02	Reinspection Photo		Load JPG	☒
145	24/03/20 21:02	Reinspection Photo		Load JPG	☒
146	24/03/20 21:02	Reinspection Photo		Load JPG	☒
147	24/03/20 21:02	Reinspection Photo		Load JPG	☒
148	24/03/20 21:02	Reinspection Photo		Load JPG	☒
149	24/03/20 21:02	Reinspection Photo		Load JPG	☒
150	24/03/20 21:02	Reinspection Photo		Load JPG	☒
151	24/03/20 21:02	Reinspection Photo		Load JPG	☒
152	24/03/20 21:02	Reinspection Photo		Load JPG	☒
153	24/03/20 21:02	Reinspection Photo		Load JPG	☒
154	24/03/20 21:02	Reinspection Photo		Load JPG	☒
155	24/03/20 21:02	Reinspection Photo		Load JPG	☒
156	24/03/20 21:02	Reinspection Photo		Load JPG	☒
157	24/03/20 21:02	Reinspection Photo		Load JPG	☒
158	24/03/20 21:02	Reinspection Photo		Load JPG	☒
159	24/03/20 21:02	Reinspection Photo		Load JPG	☒
160	24/03/20 21:02	Reinspection Photo		Load JPG	☒
161	24/03/20 21:02	Reinspection Photo		Load JPG	☒
162	24/03/20 21:02	Reinspection Photo		Load JPG	☒
163	24/03/20 21:02	Reinspection Photo		Load JPG	☒
164	24/03/20 21:02	Reinspection Photo		Load JPG	☒
165	24/03/20 21:02	Reinspection Photo		Load JPG	☒
166	24/03/20 21:02	Reinspection Photo		Load JPG	☒
167	24/03/20 21:02	Reinspection Photo		Load JPG	☒
168	24/03/20 21:02	Reinspection Photo		Load JPG	☒
169	24/03/20 21:02	Reinspection Photo		Load JPG	☒
170	24/03/20 21:02	Reinspection Photo		Load JPG	☒
171	24/03/20 21:02	Reinspection Photo		Load JPG	☒
172	24/03/20 21:02	Reinspection Photo		Load JPG	☒
173	24/03/20 21:02	Reinspection Photo		Load JPG	☒
174	24/03/20 21:02	Reinspection Photo		Load JPG	☒
175	24/03/20 21:02	Reinspection Photo		Load JPG	☒
176	24/03/20 21:02	Reinspection Photo		Load JPG	☒
177	24/03/20 21:02	Reinspection Photo		Load JPG	☒
178	24/03/20 21:02	Reinspection Photo		Load JPG	☒
179	24/03/20 21:02	Reinspection Photo		Load JPG	☒
180	24/03/20 21:02	Reinspection Photo		Load JPG	☒
181	24/03/20 21:02	Reinspection Photo		Load JPG	☒
182	24/03/20 21:02	Reinspection Photo		Load JPG	☒
183	24/03/20 21:02	Reinspection Photo		Load JPG	☒
184	24/03/20 21:02	Reinspection Photo		Load JPG	☒
185	24/03/20 21:02	Reinspection Photo		Load JPG	☒
186	24/03/20 21:02	Reinspection Photo		Load JPG	☒
187	24/03/20 21:02	Reinspection Photo		Load JPG	☒
188	24/03/20 21:02	Reinspection Photo		Load JPG	☒
189	24/03/20 21:02	Reinspection Photo		Load JPG	☒
190	24/03/20 21:02	Reinspection Photo		Load JPG	☒
191	24/03/20 21:02	Reinspection Photo		Load JPG	☒
192	24/03/20 21:02	Reinspection Photo		Load JPG	☒
193	24/03/20 21:02	Reinspection Photo		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
194	24/03/20 21:02	Reinspection Photo		Load JPG	☒
195	24/03/20 21:02	Reinspection Photo		Load JPG	☒
196	24/03/20 21:02	Reinspection Photo		Load JPG	☒
197	24/03/20 21:02	Reinspection Photo		Load JPG	☒
198	24/03/20 21:02	Reinspection Photo		Load JPG	☒
199	24/03/20 21:02	Reinspection Photo		Load JPG	☒
200	24/03/20 21:02	Reinspection Photo		Load JPG	☒
201	24/03/20 21:03	Reinspection Photo		Load JPG	☒
202	24/03/20 21:03	Reinspection Photo		Load JPG	☒
203	24/03/20 21:03	Reinspection Photo		Load JPG	☒
204	24/03/20 21:03	Reinspection Photo		Load JPG	☒
205	24/03/20 21:03	Reinspection Photo		Load JPG	☒
206	24/03/20 21:03	Reinspection Photo		Load JPG	☒
207	24/03/20 21:03	Reinspection Photo		Load JPG	☒
208	24/03/20 21:03	Reinspection Photo		Load JPG	☒
209	24/03/20 21:03	Reinspection Photo		Load JPG	☒
210	24/03/20 21:03	Reinspection Photo		Load JPG	☒
211	24/03/20 21:03	Reinspection Photo		Load JPG	☒
212	24/03/20 21:03	Reinspection Photo		Load JPG	☒
213	24/03/20 21:03	Reinspection Photo		Load JPG	☒
214	24/03/20 21:03	Reinspection Photo		Load JPG	☒
215	24/03/20 21:03	Reinspection Photo		Load JPG	☒
216	24/03/20 21:03	Reinspection Photo		Load JPG	☒
217	24/03/20 21:03	Reinspection Photo		Load JPG	☒
218	24/03/20 21:03	Reinspection Photo		Load JPG	☒
219	24/03/20 21:03	Reinspection Photo		Load JPG	☒
220	24/03/20 21:03	Reinspection Photo		Load JPG	☒
221	24/03/20 21:03	Reinspection Photo		Load JPG	☒
222	24/03/20 21:03	Reinspection Photo		Load JPG	☒
223	24/03/20 21:03	Reinspection Photo		Load JPG	☒
224	24/03/20 21:03	Reinspection Photo		Load JPG	☒
225	24/03/20 21:03	Reinspection Photo		Load JPG	☒
226	24/03/20 21:03	Reinspection Photo		Load JPG	☒
227	24/03/20 21:03	Reinspection Photo		Load JPG	☒
228	24/03/20 21:03	Reinspection Photo		Load JPG	☒
229	24/03/20 21:03	Reinspection Photo		Load JPG	☒
230	24/03/20 21:03	Reinspection Photo		Load JPG	☒
231	24/03/20 21:03	Reinspection Photo		Load JPG	☒
232	24/03/20 21:03	Reinspection Photo		Load JPG	☒
233	24/03/20 21:03	Reinspection Photo		Load JPG	☒
234	24/03/20 21:03	Reinspection Photo		Load JPG	☒
235	24/03/20 21:03	Reinspection Photo		Load JPG	☒
236	24/03/20 21:03	Reinspection Photo		Load JPG	☒
237	24/03/20 21:03	Reinspection Photo		Load JPG	☒
238	24/03/20 21:03	Reinspection Photo		Load JPG	☒
239	24/03/20 21:03	Reinspection Photo		Load JPG	☒
240	24/03/20 21:03	Reinspection Photo		Load JPG	☒
241	24/03/20 21:03	Reinspection Photo		Load JPG	☒
242	24/03/20 21:03	Reinspection Photo		Load JPG	☒
243	24/03/20 21:03	Reinspection Photo		Load JPG	☒
244	24/03/20 21:03	Reinspection Photo		Load JPG	☒
245	24/03/20 21:03	Reinspection Photo		Load JPG	☒
246	24/03/20 21:03	Reinspection Photo		Load JPG	☒

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
247	24/03/20 21:03	Reinspection Photo		Load JPG ☒
248	24/03/20 21:04	After Repair Photo		Load JPG ☒
249	24/03/20 21:04	After Repair Photo		Load JPG ☒
250	24/03/20 21:04	After Repair Photo		Load JPG ☒
251	24/03/20 21:04	After Repair Photo		Load JPG ☒
252	24/03/20 21:04	After Repair Photo		Load JPG ☒
253	24/03/20 21:04	After Repair Photo		Load JPG ☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	19/02/20 16:15	EMAIL FROM AIG DD19022020		Load PDF
2	19/02/20 16:15	TP GIA REPORT		Load PDF
3	19/02/20 16:16	NOTIFICATION FROM WKSP		Load PDF
4	21/02/20 09:54	TP ESTIMATE-MARKED		Load PDF
5	24/02/20 09:26	EMAIL TO OI		Load PDF
6	12/08/20 09:49	TP LOD		Load PDF
7	08/09/20 11:31	Authorisation to Act		Load PDF
8	08/09/20 11:31	LOD		Load PDF
9	08/09/20 11:31	LTA SEARCH		Load PDF
10	08/09/20 11:31	Release Voucher		Load PDF
11	08/09/20 11:31	RENTAL RECEIPT		Load PDF
12	08/09/20 11:31	WORKSHOP INVOICE		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	20/02/20 09:06	OI GIA REPORT		Load PDF
2	11/08/20 14:10	TP GIA report		Load PDF
3	11/08/20 15:20	Interim CLEAR		Load XLSX
4	25/08/20 01:01	CLEAR v1		Load XLSX

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMD7478J (Insd veh)	Model:	TOYOTA LEXUS 2.5 ES250 4DR
	SMK33T (TP veh)		SEDAN (AUTO) LUXURY (A)
Date of Accident:	07/02/2020		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	: \$	90,456.80	
Final Repair Cost	: \$		
Loss of Use	: \$	days at \$0.00 per day	
Rental (if any)	: \$	16 days	
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (GLOBAL SUM)	: \$	22,750.00	
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ 0 ____ (%)	
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	SK Automobile Pte Ltd	: \$	22,750.00
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

08 Sep
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20002862/HES3S2**Date:** 08/09/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800103682
Claimant Vehicle No :	SMK33T	Insured Vehicle No :	SMD7478J
Date of Loss:	07/02/2020	Nature of Claim:	TP
		Claim No:	9431867560SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK33T		
Make & Model:	TOYOTA LEXUS, 2.5 ES250 4DR SEDAN (AUTO) LUXURY (A)	Engine No:	A25A0215995
Reg. Date:	16/10/2018 (Man. Year: 2018)	Chassis No:	JTHB11B1X02001385
Colour:	Blue	Odometer:	11411 km
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	74,519.07	20,095.27	54,423.80	73.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,020.00	4,230.00	5,790.00	57.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	84,539.07	24,325.27	60,213.80	71.23
Approved Total (Overridden) (\$\$)		19,450.00		
(\$\$)	84,539.07	19,450.00	65,089.07	76.99
+ GST 7.00/7.00% (\$\$)	5,917.73	1,361.50	4,556.23	76.99
Nett Amount (\$\$)	90,456.80	20,811.50	69,645.30	76.99
+ Car Rental (16.0 x S\$160.00/day + 7.00% GST) (\$\$)		2,739.20		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		23,558.15		
Global Sum Settlement (\$\$)		22,750.00		

INSPECTION

Date of Assignment:	19/02/2020	8 Kaki Bukit Ave 4 #08-46 Premier Singapore
Date Inspected:	19/02/2020 Inspected At:	415933
		Repairer: SK Automobile Pte Ltd
Estimated Period of Repair:	13.0 days	

Adjuster: LEE HOCK ANN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LICENCE PLATE GARNISH (FRT)	Bent	289.00 FL	*131.80 FL
2	4		*FRONT PARKING SENSOR UNIT	Shorted 2pcs Only	1,956.00 FL	*500.00 FL
3	4		*FRONT PARKING SENSOR HOLDER	Necessary 2pc ONLY	275.20 FL	*60.40 FL
4	4		*FRONT PARKING SENSOR RETAINER CLAMP	Repeated	128.00 FL	*- FL
5	1		*FRONT PARKING SENSOR WIRE HARNESS	Cracked	658.00 FL	*380.80 FL
6	1		*FRONT BUMPER	Cracked	895.00 FL	*730.80 FL
7	1		*FRONT BUMPER UPPER SEAL	Necessary	154.00 FL	*154.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Bent	1,024.00 FL	*480.80 FL
9	1		*FRONT BUMPER REINFORCEMENT SPACER	Cracked	375.60 FL	*198.70 FL
10	1		*FRONT BUMPER REINFORCEMENT FOAM	Cracked	282.60 FL	*210.80 FL
11	2		*FRONT BUMPER SUPPORT BRACKET	Bent	315.20 FL	*200.60 FL
12	2		*FRONT BUMPER SUPPORT COSS BAR	Bent 1pc Only	568.00 FL	*148.80 FL
13	1		*FRONT BUMPER TOP SUPPORT BRACKET	Cracked	218.00 FL	*137.80 FL
14	2		*FRONT BUMPER SIDE RETAINER	Crushed	368.00 FL	*240.60 FL
15	1		*FRONT BUMPER UNDER ABSORBER	Cracked	495.00 FL	*210.80 FL
16	1		*FRONT BUMPER UNDER COVER	Cracked	896.00 FL	*300.30 FL
17	2		*FRONT FOG LAMP GARNISH	Cracked 1pc Only	560.80 FL	*180.80 FL
18	2		*FRONT FOG LAMP GARNISH MOULDING	Cracked 1pc Only	308.00 FL	*90.80 FL
19	1		*RADIATOR GRILLE	Cracked	1,518.70 FL	*540.80 FL
20	1		*RADIATOR GRILLE TOP MOULDING	Cracked	258.00 FL	*181.80 FL
21	2		*RADIATOR GRILLE SIDE MOULDING	Cracked	974.00 FL	*400.60 FL
22	1		*RADIATOR LOWER GRILLE BASE	Cracked	1,162.90 FL	*270.70 FL
23	1		*RADIATOR LOWER GRILLE MOULDING	Cracked	589.00 FL	*210.80 FL
24	1		*FRONT GRILLE LOGO	Scratched	1,090.00 FL	*200.80 FL
25	1		*RADAR SENSOR (FRONT)	Cracked	1,489.00 FL	*600.60 FL
26	2		*TOWING BRACKET COVER	Serviceable	320.40 FL	*- FL
27	1		*FRONT SUPPORT PANEL	Bent	845.00 FL	*480.70 FL
28	2		*FRONT SUPPORT PANEL SIDE ARCH	Crushed	308.00 FL	*170.60 FL
29	1		*FRONT SUPPORT PANEL TOP GARNISH	Crushed	380.60 FL	*280.50 FL
30	1		*CRUISE CONTROL DISTANCE SENSOR	Serviceable	817.90 FL	*- FL
31	1		*AIR TEMPERATURE SENSOR	Serviceable	390.10 FL	*- FL
32	1		*BONNET	Repair	2,587.00 FL	*- FL
33	1		*BONNET SEAL	Serviceable	180.70 FL	*- FL
34	1		*BONNET LOCK ASSY	Repair	548.00 FL	*- FL
35	2		*FENDER INNER SHIELD	Serviceable	1,033.20 FL	*- FL
36	2		*FENDER INNER TOP TRIM	Serviceable	716.00 FL	*- FL
37	2		*LED HEADLAMP WITH DRL	Cracked	5,690.00 FL	*3,050.60 FL
38	2		*HEADLAMP BRACKET	Crushed	359.80 FL	*200.60 FL
39	1		*A/C CONDENSER	Bent	1,954.50 FL	*1,100.60 FL
40	2		*A/C CONDENSER UPPER BRACKET	Serviceable	361.20 FL	*- FL
41	2		*A/C CONDENSER LOWER MOUNTING	Serviceable	150.00 FL	*- FL
42	1		*A/C CONDENSER DISCHARGE HOSE	Serviceable	545.30 FL	*- FL
43	1		*A/C CONDENSER SUCTION HOSE	Serviceable	648.80 FL	*- FL
44	1		*A/C CONDENSER RECEIVER HOSE	Serviceable	665.20 FL	*- FL
45	1		*RADIATOR ASSY	Serviceable	2,259.60 FL	*- FL
46	1		*RADIATOR FAN COWLING WITH MOTOR	Serviceable	1,845.00 FL	*- FL
47	1		*INTAKE AIR DUCT ASSY	Serviceable	689.00 FL	*- FL
48	4		*REAR PARKING SENSOR UNIT	Shorted 2pcs Only	1,700.00 FL	*500.00 FL
49	4		*REAR PARKING SENSOR HOLDER	Necessary	275.20 FL	*100.80 FL
50	4		*REAR PARKING SENSOR RETAINER CLAMP	Serviceable	128.00 FL	*- FL
51	1		*REAR PARKING SENSOR WIRE HARNESS	Cut	658.00 FL	*380.70 FL
52	1		*REAR BUMPER	Bent	1,548.00 FL	*730.80 FL
53	1		*REAR BUMPER CENTER GARNISH	Scratched	854.00 FL	*240.60 FL
54	2		*REAR BUMPER REFLECTOR	Serviceable	422.00 FL	*- FL
55	1		*REAR BUMPER CHROME MOULDING CENTER	Scratched	284.00 FL	*150.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	2		*REAR BUMPER CHROME MOULDING SIDE	Scratched	370.00 FL	*120.80 FL
57	1		*REAR BUMPER REINFORCEMENT	Bent	845.00 FL	*670.50 FL
58	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	308.00 FL	*160.80 FL
59	1		*REAR BUMPER REINFORCEMENT FOAM	Cracked	428.00 FL	*192.80 FL
60	1		*REAR BUMPER UNDER COVER	Bent	548.00 FL	*280.70 FL
61	1		*BLIND SPRO SENSOR	O/s Cracked	4,006.90 FL	*900.80 FL
62	2		*BLIND SPRO SENSOR BRACKET	Serviceable	116.00 FL	*- FL
63	1		*SMART ENTRY ANTENNA 1	Shorted	485.00 FL	*310.50 FL
64	1		*SMART ENTRY ANTENNA 2	Serviceable	428.00 FL	*- FL
65	1		*SMART ENTRY ANTENNA ECU	Scratched	689.00 FL	*380.80 FL
66	1		*SMART ENTRY ANTENNA BRACKET	Serviceable	97.60 FL	*- FL
67	1		*BOOT LID	Bent	3,281.20 FL	*820.10 FL
68	1		*BOOT LID OPENER SWITCH	Serviceable	319.60 FL	*- FL
69	1		*BOOT LID WEATHERSTRIP	Cracked	470.50 FL	*249.50 FL
70	1		*BOOT LID EMBLEM ES250	Necessary	154.00 FL	*68.70 FL
71	1		*BOOT LID EMBLEM LEXUS	Necessary	154.00 FL	*68.70 FL
72	1		*BOOT LID PULL DOWN MOTOR	Serviceable	1,295.50 FL	*- FL
73	2		*BOOT LID STOPPER	Serviceable	170.00 FL	*- FL
74	1		*BOOT LID LOCK ASSY	Jammed	2,056.50 FL	*350.80 FL
75	1		*BOOT LID STRIKER	Serviceable	185.90 FL	*- FL
76	1		*REAR MULTI-VIEW REVERSE CAMERA	Serviceable	842.00 FL	*- FL
77	1		*REAR END PANEL	Bent	2,003.50 FL	*586.50 FL
78	1		*REAR FLOOR PANEL	Bent	856.00 FL	*500.60 FL
79	1		*REAR END PANEL TOP GARNISH	Crushed	728.60 FL	*187.60 FL
80	1		*REAR FLOOR PANEL TOP BOARD	Bent	924.40 FL	*400.60 FL
81	1		*REAR FLOOR PANEL CARGO TRAY	Crushed	604.60 FL	*210.60 FL
82	1		*REAR FLOOR PANEL TOOL BOX	Cracked	684.00 FL	*240.60 FL
83	2		*REAR FENDER SIDE INNER TRIM	Serviceable	2,712.20 FL	*- FL
84	2		*REAR FENDER SIDE INNER TOP GARNISH	Serviceable	696.00 FL	*- FL
85	2		*BOOT LID LAMP	Serviceable	3,087.60 FL	*- FL
86	2		*TAILLAMP	Cracked	1,974.00 FL	*960.80 FL
87	1		*EXHAUST PIPE SILENCER	Repair	1,842.00 FL	*- FL
88	1		*EXHAUST PIPE HEAT SHIELD	Serviceable	146.60 FL	*- FL
89	2		*EXHAUST PIPE MOUNTING	Serviceable	170.60 FL	*- FL
90	1		*NUMBER PLATE WITH CASING F/R	Front Bent	400.00 FS	*70.00 FS
91	1		*SET FRONT BUMPER CLIPS	Necessary	75.00 FS	*25.00 FS
92	1		*SET RADIATOR GRILLE CLIPS	Serviceable	60.00 FS	*- FS
93	1		*SET SUPPORT PANEL TOP COVER CLIPS	Necessary	55.00 FS	*20.00 FS
94	1		*SUPPORT PANEL SEALANT	Serviceable	60.00 FS	*- FS
95	1		*SET FRONT FENDER INNER SHIELD CLIPS	Serviceable	75.00 FS	*- FS
96	6		*ENGINE COOLANT	Serviceable	720.00 FS	*- FS
97	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*25.00 FS
98	1		*SET REAR FENDER INNER SHIELD CLIPS	Serviceable	45.00 FS	*- FS
99	1		*BOOT LID JOINT SEALANT	Serviceable	90.00 FS	*- FS
100	1		*SET BOOT LID INNER TRIM CLIPS	Necessary	70.00 FS	*10.00 FS
101	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	45.00 FS	*15.00 FS
102	1		*REAR END PANEL JOINT SEALANT	Necessary	80.00 FS	*20.00 FS
103	1		*REAR FLOOR PANEL JOINT SEALANT	Necessary	80.00 FS	*20.00 FS
104	1		*REAR FLOOR PANEL JOINT INSULATOR	Serviceable	300.00 FS	*- FS
105	2		*SET REAR FENDER INNER TRIM CLIPS	Serviceable	130.00 FS	*- FS
106	1		*REAR END PANEL JOINT SEALANT	Repeated	90.00 FS	*- FS
107	1		*BOOT LID ANTENNA	Cracked	389.00 FL	*285.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	82,527.30	22,305.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	8,008.23	2,210.03
Total Parts (\$\$)	74,519.07	20,095.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OFF AND REPLACE FRONT SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS. REPAIR BOTH SIDE FENDER, BONNET.	New	1,400.00	700.00
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	New	1,600.00	600.00
3	DISMANTLE AND REPLACE A/C CONDENSER ASSY. REFILL, RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST.	New	200.00	80.00
4	REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST.	New	200.00	0.00
5	ADJUST AND FOCUS FRONT LED LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION.	New	120.00	40.00
6	REMOVE AND INSTALL ENGINE WIRE HARNESS. RESET ENGINE WARNING LIGHT SYSTEM WITH ON-BOARD DIAGNOSTIC COMPUTER.	New	200.00	80.00
7	REMOVE AND INSTALL FRONT PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY INPUT TESTING.	New	200.00	20.00
8	CUT OFF, REPLACE REAR END PANEL AND FLOOR PANEL. STRAIGHTEN, REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS. REPAIR FENDER BOTH SIDE.	New	2,200.00	1,300.00
9	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	New	1,600.00	1,000.00
10	DISMANTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS. REPAIR EXHAUST PIPE.	New	150.00	100.00
11	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS PERFORM DISTANCE SENSORY TESTING.	New	200.00	20.00
12	RENEW REAR FLOOR INSULATOR.	New	100.00	0.00
13	REMOVE AND REPLACE SMART KEYLESS ANTENNA AND BUZZER. RESET SMART ENTRY SYSTEM.	New	200.00	80.00
14	DISMANTLE AND INSTALL REAR SEATS, SPEAKER BOARD AND SEATS TRIMMING.	New	150.00	70.00
15	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUNCTION.	New	200.00	30.00
16	REMOVE AND INSTALL REAR MULTI-VIEW CAMERA ASSY. PERFORM AIMING AND ADJUST TO POSIITON.	New	200.00	30.00
17	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA.	New	100.00	40.00
18	REMOVE AND INSTALL FUEL TANK AND FUEL PIPING TO ENABLE REPAIRS.	New	300.00	0.00
19	TRANSFER BOOT LID ATTACHMENT AND MECHANISM INTO NEW POWER BOOT LID ASSY. RE-ALIGN TO POSITION.	New	200.00	0.00
20	DISMANTLE AND RE-INSTALL REAR INTERIOR COMPARTMENT TRIMMING.	New	300.00	0.00
21	APPLY ANTI-RUST.	New	200.00	40.00
Gross Labour Cost (\$)			10,020.00	4,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >