

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### **TAX INVOICE**

LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 INV No. AC2005267

INV Date 28/07/2020

Reference CC6/LPC20002873/Ada3n2

Code LPC2

#### PROFESSIONAL SERVICE FEE

Vehicle No. SMH 9397A

Insured Veh. GBC 1547T

Claim No. 20/20/VC05/023053

Policy No. Z20VC05004299

Accident Date 14/02/2020

Inspection Date 18/02/2020

| Description                    | Total  |
|--------------------------------|--------|
| Third Party Express Settlement | 400.00 |
| Subtotal                       | 400.00 |
| GST (7%)                       | 28.00  |
| Grand Total                    | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |   |                  |              |            |  |  |  |
|---|---|---|------------------|--------------|------------|--|--|--|
| LON   | ONPAC INSURANCE BHD Ref : CC6/LPC20002873/Ada3n2  |   |                  |              |            |  |  |  |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555         |   | Date: 28  | 3-07-2020<br>PC2 |              |            |  |  |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM   |   |                  |              |            |  |  |  |
|   | Insured Veh.  | GBC 1547T   | Veh. Insp        | ected        | SMH 9397A  |  |  |  |
|   | Policy No.  | Z20VC05004299   | Coverage         | e (\$)       | 0.00       |  |  |  |
|   | Claim No.   | 20/20/20/VC05/023053  | Excess (\$       | \$)          | 0.00       |  |  |  |
|   | Assign From   |   | Assign D         | ate          | 18/02/2020 |  |  |  |
| 2.  |   | Vehicle Partic  | ulars & Co       | ondition     |            |  |  |  |
|   | Make & Model  | HONDA SHUTTLE   | c.c              |              | 1496       |  |  |  |
|   | Engine No.  | HIDDEN  | Year of R        | eg.          | 2019       |  |  |  |
|   | Chassis No.   | GP71218057  | Colour           |              | BLACK      |  |  |  |
|   | Odometer  | 53642   | Steering         |              | IN ORDER   |  |  |  |
|   | Brakes  | IN ORDER  | Modificat        | ion          | SPORTS RIM |  |  |  |
|   | General   | GOOD  |                  |              |            |  |  |  |
| 3.  |   | Condition   | ons of Tyre      | es           |            |  |  |  |
|   |   | Size  | Make             |              | Balance    |  |  |  |
|   | R/H Front Tyre  | 195/55 R15  | CST TIRES        | 5            | 6 mm       |  |  |  |
|   | L/H Front Tyre  | 195/55 R15  | CST TIRES        |              | 6 mm       |  |  |  |
|   | R/H Rear Tyre   | 195/55 R15  | CST TIRES        |              | 6 mm       |  |  |  |
|   | L/H Rear Tyre   | 195/55 R15  | CST TIRES        |              | 6 mm       |  |  |  |
| 4.  | 1   | Description   | on of Dama       | ages         |            |  |  |  |
|   | THE VEHICLE SU  | STAINED DAMAGES AT THE FRO  | ONT N/S PO       | ORTION.      |            |  |  |  |
|   | DAMAGES SEE D   | ETAILS.   |                  |              |            |  |  |  |
| 5.  |   | General   | Information      | on           |            |  |  |  |
|   | Accident Date   | 14/02/2020  | Inspectio        | n Date       | 18/02/2020 |  |  |  |
|   | Survey held at  | MG SOLUTION PTE LTD   |                  |              |            |  |  |  |
|   |   | 23 KAKI BUKIT AVE 4<br>(SOUTH WING) #02-03B<br>VICOM INSPECTION CENTRE,<br>SINGAPORE 415933 |                  |              |            |  |  |  |
| 5a.   | •   |   | emarks           |              |            |  |  |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                  |              |            |  |  |  |
| 5b.   | <b>b.</b> Estimate Days of Repair   |   |                  |              |            |  |  |  |
|   | ESTIMATED NORI  | MAL PERIOD FOR REPAIR:  | 2                | Working Days |            |  |  |  |



LKK Auto Consumante 5 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 9397A

| Qty | Description of Parts   | Condition               | Estimate By<br>Workshop (\$)) | Our Adjusted<br>(\$) |
|-----|--|-------------------------|-------------------------------|----------------------|
|     | REPLACEMENT OF PARTS   |                         |                               |                      |
| 1   | FRONT BONNET   | NOT NECESSARY           | 1,150.00                      | -                    |
| 1   | FRONT BUMPER   | DEFORMED                | 1,250.00                      | 1,250.00             |
| 2   | FRONT BUMPER SIDE RETAINER @\$55.20  | N/S NECESSARY           | 110.40                        | 55.20                |
| 1   | FRONT HEAD LAMP HID LH   | CRACKED                 | 2,250.50                      | 2,250.50             |
| 1   | FRONT HEADLAMP TOP BRACKET LH  | NOT NECESSARY           | 62.50                         | -                    |
| 1   | FRONT HEADLAMP LOWER BRACKET LH  | NOT NECESSARY           | 55.40                         | -                    |
| 1   | FRONT FENDER LH  | TO REPAIR SEE<br>LABOUR | 580.00                        | -                    |
| 1   | FRONT FENDER INNER COWLING LH  | NOT NECESSARY           | 132.50                        | -                    |
| 1   | FRONT CENTRE GRILLE  | NOT NECESSARY           | 395.00                        | -                    |
|     | LESS 20% DISCOUNT  |                         | -1,197.26                     | -711.14              |
|     |  |                         | 4,789.04                      | 2,844.56             |
|     | SPECIAL NETT ITEMS   |                         |                               |                      |
| 1   | FRONT NUMBER PLATE (SN)  | NOT NECESSARY           | 50.00                         | -                    |
| 1   | SET FRONT BUMPER CLIP (SN)   | NECESSARY               | 20.00                         | 20.00                |
| 1   | SET FRONT CENTRE GRILLE CLIPS (SN)   | NOT NECESSARY           | 20.00                         | -                    |
|     |  |                         | 90.00                         | 20.00                |
|     | <u>LABOUR</u>  |                         |                               |                      |
|     | TO PANEL BEAT ,REMOVE AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH . |                         | 1,200.00                      | 200.00               |
|     | TO SPRAY PAINT AFFECTED AREA.  |                         | 1,000.00                      | 200.00               |
|     | TUFF COAT.   | NOT NECESSARY           | 100.00                        | -                    |
|     | WIRING CHECK.  |                         | 150.00                        | 30.00                |
|     | -  |                         | -                             | -                    |
|     | -  |                         | -                             | -                    |
|     | -  |                         | -                             | -                    |
|     |  |                         | 2,450.00                      | 430.00               |
|     | GRAND TOTAL  |                         | 7,329.04                      | 3,294.56             |

Report Ref No. CC6/LPC20002873/Ada3n2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS |  | 2,600.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION)      |  |          |

Report Ref No. CC6/LPC20002873/Ada3n2



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R


### PHOTOGRAPHS FOR VEHICLE NO. SMH 9397A

INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMH 9397A

### RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



