



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SKM 1361C

Qty	Description of Parts	Condition	Recommended (\$)
<u>REPLACEMENT OF PARTS</u>			
1	IU BRACKET (SN)	NECESSARY	23.40
1	3M SOLAR FILAM (SN)	NECESSARY	432.00
1	GLASS SUB-ASSY, WIND (SN)	SCRATCHED	1,186.80
2	DAM, WINDOW GLASS AD (SN)	NECESSARY	27.44
1	DAM, WINDOW GLASS AS (SN)	NECESSARY	15.30
1	W/SCREEN GLS DAM KIT, (SN)	NECESSARY	90.75
2	SIKA 182010 SIKA TACK GO! (BLA (SN)	NECESSARY	162.00
1	SIKA 207. G+P ADHESIVE PRIMER (SN)	NECESSARY	150.00
			2,087.69
<u>LABOUR</u>			
	RENEW FRONT SCREEN GLASS.		415.80
			415.80
GRAND TOTAL			2,503.49

RECOMMENDED COST OF REPAIRS			2,503.49
------------------------------------	--	--	-----------------

Report Ref No. CS1/MSG20002884/R1tf3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.