

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20002885/DES3Q2**Date:** 18/05/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900014440
Claimant Vehicle No :	SHC1663U	Insured Vehicle No :	SMH7204L
Date of Loss:	13/02/2020	Nature of Claim:	TP
		Claim No:	0461587053SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1663U	Engine No:	2ZRS066540
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU303565131
Reg. Date:	03/10/2017 (Man. Year: 2017)	Odometer:	484044 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 5 mm	Rear Left Side:	Davanti 5 mm
Front Right Side:	Davanti 5 mm	Rear Right Side:	Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,710.96	6,466.37	9,244.59	58.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,170.00	1,950.00	3,220.00	62.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,880.96	8,416.37	12,464.59	59.69
Approved Total (Overridden) (S\$)		6,700.00		

Adjuster Report

(S\$)	20,880.96	6,700.00	14,180.96	67.91
+ GST 7.00/7.00% (S\$)	1,461.67	469.00	992.67	67.91
Nett Amount (S\$)	22,342.63	7,169.00	15,173.63	67.91
+ Loss of Use (8.0 x S\$50.00/day) (S\$)		400.00		
+ Car Rental (8.0 x S\$125.40/day) (S\$)		1,003.20		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,579.65		

INSPECTION

Date of Assignment: 18/02/2020

Date Inspected: 18/02/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	458.60 FL	*458.60 FL
2	1		*REAR BUMPER SIDE RETAINER	Not Necessary	112.70 FL	*- FL
3	1		*REAR BUMPER UNDER SIDE COVER (LH)	Not Necessary	232.00 FL	*- FL
4	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*REAR BUMPER SIDE CLIP	Not Necessary	25.00 FL	*- FL
6	1		*ARM SUB-ASSY, REAR BUMPER, LH	Not Necessary	139.60 FL	*- FL
7	1		*RETAINER, REAR BUMPER, UPPER SIDE	Not Necessary	30.70 FL	*- FL
8	1		*RETAINER, REAR BUMPER, SIDE, LH	Not Necessary	94.80 FL	*- FL
9	1		*SEAL, REAR BUMPER SIDE. LH	Repair	148.40 FL	*- FL
10	1		*TAIL LAMP ASSY (UPPER)	Mtg Cracked	557.90 FL	*557.90 FL
11	1		*TAIL LAMP ASSY (LOWER)	Not Necessary	548.40 FL	*- FL
12	1		*TAIL LAMP QUARTER PANEL	Not Necessary	216.00 FL	*- FL
13	1		*TAIL LAMP SIDE COVER	Not Necessary	256.00 FL	*- FL
14	1		*REAR FENDER, LH	Dented	836.70 FL	*836.70 FL
15	1		*REAR FENDER INNER PANEL, LH	Not Necessary	728.00 FL	*- FL
16	1		*REAR FENDER OUTER PANEL. LH	Not Necessary	486.00 FL	*- FL
17	1		*REAR FENDER PANEL, ROOF SIDE OUTER, LH	Not Necessary	311.00 FL	*- FL
18	1		*REAR FENDER REINFORCEMENT, ROCKER, PANEL, LH	Not Necessary	552.30 FL	*- FL
19	1		*REAR FENDER EXTENSION, ROOF SIDE INNER FRT, LH	Not Necessary	265.10 FL	*- FL
20	1		*REAR FENDER SIDE PANEL	Not Necessary	165.00 FL	*- FL
21	1		*REAR FENDER SHIELD (LH)	Deformed	134.20 FL	*134.20 FL
22	1		*REAR FENDER TOP COVER (BLACK COLOR) (LH/RH)	Not Necessary	301.10 FL	*- FL
23	1		*REAR FENDER AIR DUCT	Not Necessary	165.10 FL	*- FL
24	1		*REAR DOOR RUBBER SEAL OUTER	Not Necessary	257.90 FL	*- FL
25	1		*PANEL SUB-ASSY, REAR DOOR, LH	Dented	1,258.30 FL	*1,258.30 FL
26	1		*REAR DOOR TRIMBOARD	Not Necessary	725.00 FL	*- FL
27	1		*REAR DOOR INNER LOCK	Not Necessary	644.70 FL	*- FL
28	1		*MOTOR, POWER WINDOW REGULATOR FRT, LH	Not Necessary	941.80 FL	*- FL
29	1		*REGULATOR, FRONT DOOR WINDOW REAR, LH	Not Necessary	228.40 FL	*- FL
30	1		*CENTRE ROCKER PANEL (GARNISH)	Bent	576.00 FL	*576.00 FL
31	1		*REAR TYRE (LH)	Not Necessary	216.00 FL	*- FL
32	1		*REAR TYRE RIM (LH)	Cut	1,555.00 FL	*1,555.00 FL
33	1		*REAR WHEEL HUB CAP (LH/RH)	No such part	177.70 FL	*- FL
34	1		*REAR WHEEL BEARING ING & HUB	Damaged	610.20 FL	*610.20 FL
35	1		*REAR CROSS MEMBER	Not Necessary	2,200.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR SHOCK ABSORBER	Distorted	118.30 FL	*118.30 FL
37	1		*REAR SHOCK ABSORBER MOUNTING	Not Necessary	125.30 FL	*- FL
38	1		*REAR LOWER ARM	Distorted	497.50 FL	*497.50 FL
39	1		*REAR UPPER ARM	Distorted	356.80 FL	*356.80 FL
40	1		*REAR KNUCKLE ARM	Distorted	810.60 FL	*810.60 FL
41	1		*REAR COIL SPRING	Not Necessary	191.40 FL	*- FL
42	1		*REAR BRAKE ABS SENSOR (WIRE)	Not Necessary	78.80 FL	*- FL
43	1		*REAR SATBILIZER BAR	Not Necessary	311.50 FL	*- FL
44	1		*REAR STABILIZER LINK	Not Necessary	151.60 FL	*- FL
45	1		*REAR TRAILING ARM	Distorted	314.20 FL	*314.20 FL
46	1		*REAR ASSIST ARM	Distorted	342.20 FL	*342.20 FL
47	1		*REAR DOOR COMFORT & APPS STICKER	Necessary	80.00 FS	*80.00 FS
48	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	19,606.20	8,578.50
- List Item Discount on L Items 20.00/25.00% (S\$)	3,895.24	2,112.13
Total Parts (S\$)	15,710.96	6,466.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	1,800.00	700.00
2	SPRAY PAINTING CHARGE.	New	1,600.00	700.00
3	WIRING CHARGE.	New	150.00	30.00
4	TUFF KOTE.	New	160.00	40.00
5	TOWING CHARGE.	New	50.00	0.00
6	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.	New	150.00	80.00
7	REMOVE / REFIX REAR WINDSCREEN GLASS.	New	120.00	0.00
8	REMOVE / REFIX REVERSE SENSOR.	New	120.00	40.00
9	REMOVE / REFIX UNDERCARRIAGE (RR).	New	200.00	150.00
10	REMOVE / REFIX FUEL TANK.	New	150.00	0.00
11	REMOVE / REFIX EXHAUST PIPE.	New	150.00	0.00
12	TRANSFER OF DOOR.	New	120.00	60.00
13	TO RESET AND PROGRAM ABS SYSTEM.	New	400.00	150.00
			Gross Labour Cost (S\$)	5,170.00
				1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >