

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20002889/KES3Q2**Date:** 23/09/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994157
Claimant Vehicle No :	SLM6373Z	Insured Vehicle No :	SKX2716Z
Date of Loss:	20/09/2019	Nature of Claim:	TP
		Claim No:	7333080044SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM6373Z		
Make & Model:	TOYOTA SIENTA, 1.5 G CVT (A)	Engine No:	2NR8642353
Reg. Date:	04/04/2017 (Man. Year: 2016)	Chassis No:	NSP1707041204
Colour:	Metallic Pearl White	Odometer:	63251 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	KAPSEN 8 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 8 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	850.10	603.37	246.73	29.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	600.00	250.00	29.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,700.10	1,203.37	496.73	29.22
+ GST 7.00/7.00% (S\$)	119.01	84.24	34.77	29.22

Nett Amount (S\$)	1,819.11	1,287.61	531.50	29.22
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		1,495.61		

INSPECTION

Date of Assignment: 19/02/2020

Date Inspected: 23/07/2020

Estimated Period of Repair: 2.0 days

Inspected At:

Cheng Hoe Motor Service (HQ)
BLK 1019, YISHUN IND. PARK A, #01-374
Singapore 768761**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Mtg Cracked	401.20 FL	*401.20 FL	
2	1		*REAR BUMPER CENTRE PAD	Dented	201.33 FL	*201.32 FL	
3	1		*REAR BUMPER RH SIDE PAD	Cracked	101.70 FL	*101.70 FL	
4	1		*REAR BUMPER RH REFLECTOR	Serviceable	62.30 FL	*- FL	
5	8		*REAR BUMPER CLIP	Necessary	31.12 FL	*31.12 FL	
6	1		*TAILGATE LOGO	Necessary	69.15 FL	*69.15 FL	
7	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS	
					Sub Total (\$)	1,066.80	804.49
					- List Item Discount on L Items 25.00/25.00% (\$)	216.70	201.12
					Total Parts (\$)	850.10	603.37

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER & ATTACHMENTS ,TAILLAMP ,KNOCKING & REPAIR TAILGATE & REALIGN THE SAME	New	350.00	200.00
2	PUTTY & RESPRAY REAR BUMPER ,TAILGATE & ALL AFFECTED AREAS	New	500.00	400.00
Gross Labour Cost (S\$)			850.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >