



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD			Ref: CC4/ASM20002895/Qpa3q2 Date: 11/01/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YL 8364M	Veh. Inspected	PA 737M	
Policy No.	P2031579	Coverage (\$)	0.00	
Claim No.	S0M02GLK	Excess (\$)	0.00	
Assign From		Assign Date	18/02/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	ISUZU LT434W	c.c	7790	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JALLT434MJ7000052	Colour	MULTI COLOUR	
Odometer	51413 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	5 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	5 mm	
R/H Rear Tyre	295/80 R22.5	BRIDGESTONE	5 mm	
L/H Rear Tyre	295/80 R22.5	BRIDGESTONE	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/02/2020	Inspection Date	19/02/2020	
Survey held at	LIANNEX CORPORATION (S) PTE LTD NO 18 SUNGEI KADUT WAY . SINGAPORE 728789			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>9 Working Days</b>	