

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002897/KEA3Q2

Date: 14/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800020283

Claimant
Vehicle No : SJT5522D **Insured Vehicle No :** SLW6695S

Date of Loss: 13/02/2020 Nature of Claim: TP Claim No: 3883248110SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT5522D	Engine No:	3ZZ4922383
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106152238
Reg. Date:	17/08/2009 (Man. Year: 2009)	Odometer:	173575 km
Colour:	Metallic Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,815.65	1,620.75	1,194.90	42.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,070.00	1,230.00	53.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,115.65	2,690.75	2,424.90	47.40
Approved Total (Overridden) (\$\$)		2,150.00		
Nett Amount (\$\$)	5,115.65	2,150.00	2,965.65	57.97
+ Loss of Use (3.0 x S\$60.00/day) (\$\$)		180.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,337.45		

INSPECTION

Date of Assignment: 18/02/2020

Date Inspected: 19/02/2020 Inspected At:

Lian Her Motors (HQ)
Block 5038 Ang Mo Kio Avenue 3,
#01-405 Ang Mo Kio Industrial Park 2
Singapore 569541

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT HEADLAMP ASSY	Mtg Cracked	1,100.20 FL	*963.80 FL
2	2		*FRONT FOG LAMP ASSY	Serviceable	370.40 FL	*- FL
3	1		*FRONT GRILLE	Dented / Distorted	305.10 FL	*257.60 FL
4	1		*FRONT GRILLE EMBLEM	Necessary	55.70 FL	*55.70 FL
5	1		*FRONT SUPPORT PANEL	Repair	653.20 FL	*- FL
6	1		*FRONT BUMPER	Buckled	498.10 FL	*498.10 FL
7	1		*FRONT BUMPER REINFORCEMENT	Repair	385.70 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINER	Distorted	110.20 FL	*110.20 FL
9	1		*FRONT BUMPER LOWER GRILLE	Cracked	175.60 FL	*175.60 FL
10	1		*FRONT NO PLATE	Dented	35.00 FS	*35.00 FS
11	20		*FRONT BUMPER CLIP	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,729.20	2,136.00
- List Item Discount on L Items 25.00/25.00% (S\$)	913.55	515.25
Total Parts (S\$)	2,815.65	1,620.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE/RENEW THE ABOVE PARTS ,KNOCK OUT & RESHAPE FRONT O/S FENDER INNER PANEL	New	1,000.00	450.00
2	TO PUTTY & SPRAY PAINT FRONT ACCIDENT AFFECTED PORTION	New	1,000.00	600.00
3	CHECK /RECONNECT WIRING	New	20.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	100.00	0.00
5	REMOVE/REFIT AIR CON CONDENSER & TO TOP UP GAS ELEMENT	New	180.00	0.00
Gross Labour Cost (\$\$)			2,300.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >