

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20002898/BEA3Q2

**Date:** 19/05/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070005305

**Claimant**  
**Vehicle No :** GV8824M **Insured Vehicle No :** SMR6174T

Date of Loss: 16/02/2020 Nature of Claim: TP Claim No: 2391050266SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GV8824M</b>		
Make & Model:	TOYOTA LITEACE, 2.2 D (A)	Engine No:	3C3963934
Reg. Date:	13/12/2002 (Man. Year: 2002)	Chassis No:	CR425003997
Colour:	White	Odometer:	374813 km
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	165 /13 8PR	Rear Tyre Size:	165 /13 8PR
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Kumho 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,649.13	3,478.92	3,170.21	47.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	2,250.00	1,530.00	40.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,429.13</b>	<b>5,728.92</b>	<b>4,700.21</b>	<b>45.07</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,429.13</b>	<b>4,600.00</b>	<b>5,829.13</b>	<b>55.89</b>
<b>+ Loss of Use (11.0 x S\$100.00/day) (S\$)</b>		1,100.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>+ Other Costs (S\$)</b>		110.00		
<b>Nett Liability (S\$)</b>		<b>5,817.45</b>		

### INSPECTION

Date of Assignment: 18/02/2020

Date Inspected: 18/02/2020 Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)  
160 SIN MING DRIVE, #01-14 SIN  
MING AUTOCITY  
Singapore 575722

Estimated Period of Repair: 8.0 days

**Adjuster:** Lim Teow Guan

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,485.30 FL	*899.50 FL
2	1		*TAILGATE INNER LOCK	Not Damaged	289.90 FL	*- FL
3	1		*TAILGATE LOCK ACTUATOR	Not Damaged	381.45 FL	*- FL
4	1		*TAILGATE LOCK STRIKER	Not Damaged	68.10 FL	*- FL
5	1		*TAILGATE WEATHERSTRIP	Not Damaged	282.90 FL	*- FL
6	1		*TAILGATE WINDSCREEN MOULDING	Necessary	182.25 FL	*75.30 FL
7	1		*REAR BUMPER	Dented	496.54 FL	*381.10 FL
8	1		*REAR BUMPER REFLECTOR RH	Broken	195.80 FL	*65.00 FL
9	2		*REAR BUMPER SIDE RETAINER	Necessary	244.20 FL	*244.20 FL
10	4		*REAR BUMPER LOWER BRACKET	No such part	337.00 FL	*- FL
11	1		*REAR END PANEL CENTRE	Dented	581.45 FL	*416.70 FL
12	1		*REAR END PANEL SIDE	Dented	287.72 FL	*266.70 FL
13	1		*REAR END PANEL TOP GARNISH	No such part	262.80 FL	*- FL
14	1		*SIDE PANEL (BODY)	Dented	1,084.50 FL	*1,084.50 FL
15	1		*REAR AIR VENTS RH	Broken	85.60 FL	*59.60 FL
16	1		*TAILLAMP RH	Broken	377.60 FL	*296.89 FL
17	1		*TAILLAMP LOWER PANEL RH	Broken	182.40 FL	*182.40 FL
18	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
19	1		*TAILGATE SEALANT	Necessary	80.00 FS	*30.00 FS
20	2		*TAILLAMP SEAL	Not Necessary	90.00 FS	*- FS
21	1		*STICKER 70KM/H	Necessary	25.00 FS	*25.00 FS
22	1		*STICKER 5 PAX	Necessary	25.00 FS	*25.00 FS
23	1		*STICKER	Not Necessary	30.00 FS	*- FS
24	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*40.00 FS
25	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
26	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	60.00 FS	*- FS
27	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
28	2		*REVERSE SENSOR	Cut	400.00 FS	*200.00 FS
29	1		*REAR END PANEL CENTRE SEALANT	Necessary	80.00 FS	*30.00 FS
30	1		*REAR END PANEL SIDE SEALANT	Necessary	80.00 FS	*30.00 FS
31	1		*SIDE PANEL (BODY) SEALANT	Necessary	120.00 FS	*50.00 FS
32	2		*TAILLAMP CLIPS	No such part	100.00 FS	*- FS
33	2		*TAILLAMP LOWER PANEL SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,355.51</b>	<b>4,471.89</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	<b>1,706.38</b>	<b>992.97</b>

<b>Total Parts (\$)</b>	<b>6,649.13</b>	<b>3,478.92</b>
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	R&R TAILGATE COMPONENT	New	150.00	150.00
2	R&R REVERSE SENSOR	New	100.00	60.00
3	R&R REAR WINDSCREEN	New	250.00	120.00
4	R&R SIDE PANEL GLASS	New	280.00	120.00
5	PANEL BEAT	New	1,600.00	1,000.00
6	SPRAY PAINTING	New	1,400.00	800.00
<b>Gross Labour Cost (\$)</b>			<b>3,780.00</b>	<b>2,250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >