

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20002904/AYD3E2

Date: 29/10/2020

REFERENCE

Insured/Claimant: SEE MUI KHENG JOANNA

Policy No: 1800106939

Date of Loss: 10/02/2020

Nature of Claim: OD

Claim No: 0845404912SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB5577S**

Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)

Engine No: CVK063501

Reg. Date: 06/09/2018 (Man. Year: 2018)

Chassis No: WAUZZZF53JA107430

Colour: Black

Odometer: 65797 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$150,000.00

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,882.00	11,796.00	7,086.00	37.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,192.00	12,542.00	9,650.00	43.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	41,074.00	24,338.00	16,736.00	40.75
- Excess (\$\$)	1,600.00	1,600.00	0.00	0.00
(\$\$)	39,474.00	22,738.00	16,736.00	42.40
+ GST 7.00/7.00% (\$\$)	2,763.18	1,591.66	1,171.52	42.40
Nett Amount (\$\$)	42,237.18	24,329.66	17,907.52	42.40

INSPECTION

Date of Assignment: 20/02/2020

Date Inspected: 19/02/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE PANEL - RH	Dented	2,354.00 FS	*1,883.20 FS
2	1		*SIDE WINDOW - RH	Necessary	676.00 FS	*540.40 FS
3	1		*WHEEL HOUSING LINER - RH	Not Necessary	259.00 FS	*- FS
4	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	86.00 FS	*- FS
5	1		*REAR BUMPER	Torn	2,385.00 FS	*1,908.00 FS
6	1		*REAR BUMPER FIXING PARTS	Not Necessary	156.00 FS	*- FS
7	1		*REAR BUMPER SECURING STRIP	Not Necessary	210.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	41.00 FS	*- FS
9	1		*CHROME TRIM	Not Necessary	958.00 FS	*- FS
10	1		*FRONT DOOR - RH	Dented	2,946.00 FS	*2,356.80 FS
11	1		*FRONT DOOR OUTER SEAL	Necessary	209.00 FS	*167.20 FS
12	1		*BONDING AGENT	Necessary	46.00 FS	*36.72 FS
13	1		*CLEANING SOLUTION	Necessary	64.00 FS	*51.20 FS
14	1		*DOOR ATTACHMENT PARTS	Not Necessary	122.00 FS	*- FS
15	1		*FRONT DOOR CATCH	Not Necessary	113.00 FS	*- FS
16	1		*DOOR HINGE HALF UPPER PART - RH	Not Necessary	42.00 FS	*- FS
17	1		*HINGE HALVES - RH LOWER	Not Necessary	43.00 FS	*- FS
18	1		*HINGE HALVES - RH LOWER	Not Necessary	43.00 FS	*- FS
19	1		*DOOR HINGE HALF LOWER PART - RH	Not Necessary	71.00 FS	*- FS
20	1		*DOOR HANDLE TRIM PLATE - RH	Not Necessary	83.00 FS	*- FS
21	1		*DOOR HANDLE TRIM - RH	Cut	128.00 FS	*102.40 FS
22	1		*REAR DOOR - RH	Dented	2,946.00 FS	*2,356.80 FS
23	1		*REAR DOOR OUTER SEAL	Necessary	209.00 FS	*167.20 FS
24	1		*BONDING AGENT	Necessary	46.00 FS	*36.72 FS
25	1		*CLEANING SOLUTION	Necessary	64.00 FS	*51.20 FS
26	1		*REAR DOOR CATCH	Necessary	113.00 FS	*90.40 FS
27	1		*DOOR HANDLE TRIM PLATE - DRIVER DOOR	Not Necessary	83.00 FS	*- FS
28	1		*DOOR HANDLE TRIM - RH	Not Necessary	128.00 FS	*- FS
29	1		*LOCK CYLINDER - DRIVER DOOR	Not Necessary	508.00 FS	*- FS
30	1		*EXTERIOR DOOR HANDLE - RH	Repair	40.00 FS	*- FS
31	1		*DOOR HANDLE SENSOR - RH	Not Necessary	215.00 FS	*- FS
32	1		*DOOR TRIM - RH	Necessary	150.00 FS	*119.60 FS
33	1		*SIDE MEMBER TRIM - RH	Repair	778.00 FS	*- FS
34	1		*SIDE MEMBER ATTACHMENT PARTS	Necessary	123.00 FS	*98.00 FS
35	1		*ADHESIVE TAPES	Necessary	200.00 FS	*159.60 FS
36	1		*REAR ALUMINIUM RIM - LH	Cut	964.00 FS	*770.80 FS
37	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
38	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
39	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
40	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
41	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
42	1		*SUNDRIES	Necessary	400.00 FS	*19.76 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **18,882.00** **11,796.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO RENEW 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	300.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
5	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	560.00	560.00
6	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	400.00	0.00
7	TO DISMANTLE REAR BUMPER, REAR LID, RHS REAR DOOR, RHS FRONT DOOR AND RHS SILL PANEL TRIM. CUT OUT AND WELD RHS REAR FENDER. TO RENEW RHS FRONT DOOR, RHS REAR DOOR, RHS SILL PANEL TRIM AND REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	8,800.00	4,000.00
8	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS FRONT DOOR, RHS REAR DOOR, DOOR HANDLES, DOOR HINGES, RHS SILL PANEL TRIM, RHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	8,500.00	4,050.00
9	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			22,192.00	12,542.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >