

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20002913/KPS3Q2

Date: 24/06/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MPC0000631_01
Claimant Vehicle No :	SMN3247H	Insured Vehicle No :	SKR4231Z
Date of Loss:	08/02/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0000365

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN3247H	Engine No:	LEB5607288
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71072761
Reg. Date:	31/07/2019 (Man. Year: 2018)	Odometer:	73573 km
Colour:	Metallic Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	West Lake 9 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	West Lake 9 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,942.20	1,924.40	1,017.80	34.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	1,120.00	1,110.00	49.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,172.20	3,044.40	2,127.80	41.14
+ GST 7.00/7.00% (S\$)	362.05	213.11	148.94	41.14
Nett Amount (S\$)	5,534.25	3,257.51	2,276.74	41.14
+ Car Rental (5.0 x S\$83.00/day) (S\$)		415.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,679.96		

INSPECTION

Date of Assignment:	13/02/2020	
Date Inspected:	25/02/2020 Inspected At:	Esteem Performance Pte Ltd (HQ)
		Blk 5033 Ang Mo Kio Ind Park 2, #01-259
		Singapore 569536
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2020)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN3247H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
2	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
3	1		*REVERSE SENSOR	Serviceable	200.00 FS	*- FS
4	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
5	1		*REAR NO .PLATE LAMP LH	Serviceable	38.50 FL	*- FL
6	1		*REAR NO .PLATE LAMP RH	Serviceable	38.50 FL	*- FL
7	1		*REAR BUMPER	Buckled	925.00 FL	*925.00 FL
8	10		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
9	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	34.90 FL	*- FL
10	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	34.90 FL	*- FL
11	1		*REAR BUMPER REFLECTOR LH	Serviceable	45.80 FL	*- FL
12	1		*REAR BUMPER REFLECTOR RH	Serviceable	45.80 FL	*- FL
13	1		*TAIL DOOR	Bent	1,100.00 FL	*1,100.00 FL
14	1		*TAIL DOOR LOCK	Repair	157.10 FL	*- FL
15	1		*TAIL DOOR EMBLEM	Necessary	35.50 FL	*35.50 FL
16	1		*WORDING FREED	Necessary	65.00 FL	*65.00 FL
17	1		*WORDING HYBRID	Necessary	75.00 FL	*75.00 FL
18	1		*TAIL DOOR TRIM	Serviceable	355.00 FL	*- FL
19	10		*TAIL DOOR TRIM CLIP	Not Necessary	35.00 FL	*- FL
20	1		*BOOT WEATHERSTRIP	Serviceable	168.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,604.00	2,395.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	661.80	471.10
Total Parts (\$\$)	2,942.20	1,924.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER ,TAILDOOR ,END PANEL)	New	800.00	400.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER ,TAILDOOR ,END PANEL)	New	800.00	440.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
5	TO TUFF COAT	New	100.00	30.00
6	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
7	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120.00	60.00
8	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	0.00
Gross Labour Cost (\$\$)			2,230.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >