



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2004914
INV Date 14/07/2020
Reference CC4/LPC20002928/Dea3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SHA 8694U
Insured Veh. YP 2716A
Claim No. 19/20/20/VC05/023037
Policy No. Z19VC05004042
Accident Date 11/02/2020
Inspection Date 18/02/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20002928/Dea3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 14-07-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 2716A	Veh. Inspected	SHA 8694U
Policy No.	Z19VC05004042	Coverage (\$)	0.00
Claim No.	19/20/20/VC05/023037	Excess (\$)	0.00
Assign From	GERALD	Assign Date	18/02/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVKU141035	Colour	YELLOW
Odometer	146043	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	5 mm
L/H Front Tyre	195/65 R15	DAVANTI	5 mm
R/H Rear Tyre	195/65 R15	DAVANTI	5 mm
L/H Rear Tyre	195/65 R15	DAVANTI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/02/2020	Inspection Date	18/02/2020
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8694U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	DENTED	2,253.80	2,253.80
1	BONNET RUBBER (RH)	NOT NECESSARY	12.40	-
1	BONNET HINGE (RH)	NOT NECESSARY	118.70	-
1	BONNET LOCK	NOT NECESSARY	127.30	-
1	BONNET ABSORBER	NOT NECESSARY	35.70	-
1	BONNET INSULATOR	NOT NECESSARY	230.10	-
1	BONNET SEAL	NOT NECESSARY	38.30	-
1	BONNET INSULATOR CLIPS	NOT NECESSARY	8.40	-
1	RADIATOR GRILLE	CRACKED	1,227.50	1,227.50
1	FRONT BUMPER COVER	TORN	418.30	418.30
1	FRONT BUMPER GRILLE (RH)	CUT	186.90	186.90
1	FRONT BUMPER TOWING COVER	TO REPAIR SEE LABOUR	29.00	-
2	FRONT BUMPER MOULDING CENTRE UPPER (LH/RH) @\$108.50	CUT (1 PC ONLY)	217.00	108.50
1	FRONT BUMPER LOWER STIFFNER	NOT NECESSARY	85.10	-
1	FRONT BUMPER LIP	NOT NECESSARY	135.10	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$35.00	NOT NECESSARY	70.00	-
2	FRONT BUMPER BRACKET (LH/RH) @\$28.00	O/S BROKEN / N/S NOT NECESSARY	56.00	28.00
2	FRONT BUMPER SIDE BRACKET SUPPORT @\$12.00	NOT NECESSARY	24.00	-
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRONT BUMPER STRIP ASSY	NOT NECESSARY	29.40	-
1	HEADLAMP SUPPORT PANEL ASSY	CRACKED / DISTORTED	949.30	949.30
2	HEADLAMP (LH/RH) @\$3987.30	O/S BROKEN / N/S CRACKED	7,974.60	2,397.60
2	HEADLAMP HALOGEN BULB (LH/RH) @\$14.40	NOT NECESSARY	28.80	-
1	DAY LIGHT ,LH	NOT NECESSARY	642.50	-
1	DAY LIGHT ,RH	CUT / MTG BROKEN	642.50	642.50
1	DAY LIGHT WIRE ,RH	NOT NECESSARY	585.50	-
1	BUZZER ASSY -PIEZO (RH)	NOT NECESSARY	388.00	-

Report Ref No. CC4/LPC20002928/Dea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER (RH)	DENTED	490.70	490.70
2	FRONT FENDER SHIELD (LH/RH) @\$114.70	O/S DEFORMED / N/S NOT NECESSARY	229.40	114.70
2	FRONT FENDER RETAINER @\$41.40	NOT NECESSARY	82.80	-
1	WIPER CONTAINER	DEFORMED	356.70	356.70
1	WIPER CONTAINER MOTOR	NOT NECESSARY	267.50	-
1	WIRING -FRONT	NOT NECESSARY	3,802.10	-
1	FRONT BUMPER GRILLE AIR DUCT (ADDITIONAL)	BROKEN	167.80	80.50
	LESS 20% DISCOUNT		-4,386.64	-1,855.40
			17,546.56	7,421.60
	<u>SPECIAL NETT ITEMS</u>			
1	EMBLEM -BLUE DRIVE (RH) (SN)	NECESSARY	26.60	26.60
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	FRONT NO PLATE TRIM COVER (SN)	NOT NECESSARY	30.00	-
			81.60	26.60
	<u>LABOUR</u>			
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF FRONT BUMPER TOWING COVER .		800.00	600.00
	SPRAY PAINTING CHARGE.		800.00	600.00
	WIRING CHARGE.		150.00	30.00
	TUFF KOTE.		150.00	30.00
	TOWING CHARGE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX RADIATOR.	NOT NECESSARY	90.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
			2,200.00	1,260.00
	GRAND TOTAL		19,828.16	8,708.20

RECOMMENDED COST OF REPAIRS			8,708.20
------------------------------------	--	--	-----------------

Report Ref No. CC4/LPC20002928/Dea3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.