Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20002937/KBA3Q2

Date: 09/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100494097

Claimant SHF620J Insured Vehicle No: SLK2259H

Vehicle No: Shrozuj insured vehicle No: SLK2259H

Date of Loss: 17/02/2020 Nature of Claim: TP Claim No: 8892712744SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHF620J

Make & Model:

RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR Engine No: M9R8839C001715

(A)

Reg. Date: 27/06/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC278507

Colour: Metallic White/Red Odometer: 638930 km

Engine Capacity: 1995 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Sailun 9 mm Rear Left Side: Sailun 9 mm
Front Right Side: Sailun 9 mm
Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,858.04	1,892.37	6,965.67	78.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,000.00	890.00	13,110.00	93.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,858.04	2,782.37	20,075.67	87.83
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	22,858.04	2,250.00	20,608.04	90.16
+ GST 7.00/7.00% (S\$)	1,600.06	157.50	1,442.56	90.16
Nett Amount (S\$)	24,458.10	2,407.50	22,050.60	90.16
+ Loss of Use (2.0 x S\$	50.00/day) (S\$)	100.00		
+ Car Rental (2.0 x S\$81.13/day) (S\$)		162.26		
+ Doc/S	earch Fee (S\$)	7.49		
Nett Liability (S\$)		2,677.25		
Global Sum S	2,600.00			

INSPECTION

Date of Assignment: 19/02/2020

Date Inspected: 19/02/2020 Inspected At: Trans-cab Auto Services Pte Ltd

No 2 Ang Mo Kio Street 63

Singapore 569111

Adjuster Report Page 2 of 4

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled	747.20 FL	*747.20 FL
2	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT RH	Distorted	101.40 FL	*101.40 FL
5	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- FL
7	1		*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	*- FL
8	1		*BUMPER FOGLAMP GRILLE RH	Serviceable	207.21 FL	*- FL
9	1		*BUMPER BEAM FRT	Repair	663.70 FL	*- FL
10	1		*HEADLAMP RH	Cut	743.60 FL	*743.60 FL
11	1		*FENDER PANEL FRT RH	Bent	437.10 FL	*437.10 FL
12	1		*WHEELARCH FRT RH	Serviceable	191.40 FL	*-FL
13	1		*FENDER BRACKET LOWER RH	Serviceable	11.80 FL	*- FL
14	1		*FENDER BRACKET FRT RH	Serviceable	106.40 FL	*- FL
15	1		*TOW COVER FRT	Serviceable	60.90 FL	*- FL
16	1		*RADIATOR GRILLE	Serviceable	969.90 FL	*-FL
17	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
18	1		*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	*- FL
19	1		*FRAME FULL SUPPORT PANEL	Serviceable	592.70 FL	*- FL
20	1		*FRAME FULL SUPPORT BRACKET	Repair	41.60 FL	*-FL
21	1		*BONNET	Repair	1,312.70 FL	*- FL
22	1		*WIPER RESERVOIR MOTOR	Serviceable	82.60 FL	*-FL
23	1		*WIPER RESERVOIR	Serviceable	179.60 FL	*- FL
24	1		*WIPER RESERVOIR NECK	Serviceable	29.30 FL	*-FL
25	1		*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
26	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*-FS
27	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*-FS
28	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*-FS
29	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*-FS
30	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*-FS
31	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*-FS
32	1		*WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*-FS
33	1		*FRONT RIGHT TYRE	Serviceable	300.00 FS	*-FS
34	1		*FRONT RIGHT TYRE RIM	Serviceable	380.00 FS	*-FS
35	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*-FS
36	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*-FS
37	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.			
			Liethern Discount on Life was	Sub Total (S\$)	9,716.05	2,095.30
- List Item Discount on L Items 10.00/10.00% (S\$) 858.01					202.93	
				Total Parts (S\$)	8,858.04	1,892.37
_						
	Report was unsubmitted during this print-out.					

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	abour Items						
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00			
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00			
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	400.00			
4	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00			
5	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00			
6	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00			
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00			
8	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00			
9	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00			
10	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00			
11	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00			
	Gross Labour Cost (S\$)		14,000.00	890.00			
	Report was unsubmitted durin	a this print-out.					

< END OF ESTIMATES >