



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2004928  
INV Date 14/07/2020  
Reference CC6/EQI20002941/Apa3q2  
Code EQI



### PROFESSIONAL SERVICE FEE

Vehicle No. SJQ 1197B  
Insured Veh. GBF 3508C  
Claim No. DM20HO00392-JG  
Policy No. DMCPHQ19-004178  
Accident Date 18/02/2020  
Inspection Date 20/02/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC6/EQI20002941/Apa3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 14-07-2020		
		Code : EQI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	GBF 3508C	<b>Veh. Inspected</b>	SJQ 1197B
	<b>Policy No.</b>	DMCPHQ19-004178	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	DM20HO00392-JG	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	20/02/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	TOYOTA C-HR HYBRID	<b>c.c</b>	1798
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
	<b>Chassis No.</b>	NMTKZ3BX80R022396	<b>Colour</b>	SILVER
	<b>Odometer</b>	95800	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	215/60 R17	MICHELIN	6 mm
	<b>L/H Front Tyre</b>	215/60 R17	MICHELIN	6 mm
	<b>R/H Rear Tyre</b>	215/60 R17	MICHELIN	6 mm
	<b>L/H Rear Tyre</b>	215/60 R17	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	18/02/2020	<b>Inspection Date</b>	20/02/2020
	<b>Survey held at</b>	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 1197B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	NOT NECESSARY	630.00	-
1	REAR BUMPER LOWER	NOT NECESSARY	507.50	-
10	REAR BUMPER CLIP @\$6.50	NOT NECESSARY	65.00	-
1	REAR R/H BUMPER SIDE RETAINER	NOT NECESSARY	105.00	-
1	REAR R/H FENDER	TO REPAIR SEE LABOUR	560.00	-
1	REAR R/H WHEEL ARCH PROTECTOR	CUT	262.50	262.50
1	REAR R/H DOOR	DISTORTED	1,470.00	1,184.90
2	REAR R/H DOOR HINGE @\$122.50	NOT NECESSARY	245.00	-
1	REAR R/H DOOR LOWER PROTECTOR	DEFORMED	262.50	262.50
1	REAR R/H DOOR LOCK	DAMAGED	980.00	398.00
1	REAR R/H DOOR WEATHERSTRIP	NOT NECESSARY	168.00	-
1	REAR R/H DOOR INNER TRIM BOARD	CRACKED	2,605.00	555.70
1	REAR R/H DOOR WINDOW MOTOR & REGULATOR ASSY	DAMAGED	463.00	243.00
1	REAR R/H TYRE	NOT NECESSARY	380.00	-
1	REAR R/H SHOCK ABSORBER	NOT NECESSARY	330.00	-
1	REAR R/H AXLE BEARING	NOT NECESSARY	857.50	-
1	REAR AXLE	NOT NECESSARY	2,550.00	-
1	R/H ROCKER PANEL	TO REPAIR SEE LABOUR	758.00	-
1	R/H ROCKER PANEL SKIRT	DEFORMED	390.00	390.00
12	R/H ROCKER PANEL SKIRT CLIP @\$6.50	NECESSARY	78.00	30.00
1	FRONT R/H DOOR LOWER PROTECTOR	CUT	254.90	254.90
	LESS 25% DISCOUNT		-	-895.38
			13,921.90	2,686.12
<b><u>SPECIAL NETT ITEMS</u></b>				
2	REAR R/H DOOR FRAME STICKER @\$76.10 (SN)	NECESSARY	152.20	60.00
1	REAR R/H RIM (SN)	CUT	950.00	500.00
			1,102.20	560.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE & REFIT REAR R/H DOOR ,LOCK ,GLASS ,WEATHERSTRIP,TRIM BOARD ,FRAME STICKER & WINDOW MOTOR & REGULATOR ASSY .		280.00	80.00
	TO REMOVE & REFIT REVERSE SENSOR .	NOT NECESSARY	100.00	-
	TO REMOVE & REFIT REAR AXLE ,BEARING & SHOCK ABSORBER .	NOT NECESSARY	450.00	-
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.	NOT NECESSARY	150.00	-
	TOWING FEE.	NOT NECESSARY	150.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR R/H FENDER AND R/H ROCKER PANEL.		1,200.00	300.00
	SPRAY PAINTING .		1,400.00	600.00
			3,830.00	1,010.00
	<b>GRAND TOTAL</b>		<b>18,854.10</b>	<b>4,256.12</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,400.00</b>

Report Ref No. CC6/EQI20002941/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJQ 1197B

INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJQ 1197B

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

