

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG20002947/AEA3Q2**Date:** 14/04/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800042839  
**Claimant**  
**Vehicle No :** GBB9384Z **Insured Vehicle No :** SLZ3559G  
Date of Loss: 08/02/2020 Nature of Claim: TP Claim No: 8750443294SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB9384Z**  
Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2002511  
Reg. Date: 31/08/2010 (Man. Year: 2010) Chassis No: JTFAT35Y90K201239  
Colour: Silver Odometer: 394492 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12  
Front Left Side: Condor 6 mm Rear Left Side: Condor 6 mm  
Front Right Side: Condor 6 mm Rear Right Side: Condor 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,021.22	1,438.32	582.90	28.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	630.00	530.00	45.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,181.22</b>	<b>2,068.32</b>	<b>1,112.90</b>	<b>34.98</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,650.00</b>		
<b>(S\$)</b>	3,181.22	1,650.00	1,531.22	48.13
<b>+ GST 7.00/7.00% (S\$)</b>	222.69	115.50	107.19	48.13
<b>Nett Amount (S\$)</b>	<b>3,403.91</b>	<b>1,765.50</b>	<b>1,638.41</b>	<b>48.13</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>2,172.95</b>		

INSPECTION

Date of Assignment: 20/02/2020  
Date Inspected: 20/02/2020 Inspected At: People's Vehicle Recovery Service (HQ)  
Blk 3023A Ubi Rd 1, #01-60  
Singapore 408717  
Estimated Period of Repair: 4.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE PANEL	Dented	1,950.00 FL	*1,265.00 FL
2	2		*TAIL LAMP	Cracked	456.80 FL	*456.80 FL
3	1		*STEP BRACKET REAR	Bent	89.30 FL	*89.30 FL
4	1		*NUMBER PLATE LAMP	Not Necessary	92.20 FL	*- FL
5	1		*NUMBER PLATE REAR	Bent	20.00 FS	*20.00 FS
6	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
7	1		*3 PAX STICKER	Necessary	15.00 FS	*15.00 FS
8	1		*EXPLOSIVES STICKER	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>2,668.30</b>	<b>1,891.10</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	647.08	452.78
<b>Total Parts (\$)</b>	<b>2,021.22</b>	<b>1,438.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REPLACE ACCIDENT DAMAGED PARTS	New	600.00	250.00
2	SPRAY PAINTING ACCIDENT EFFECT PARTS	New	500.00	350.00
3	CHECK ALL LIGHTING AFTER REPAIR	New	60.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,160.00</b>	<b>630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >