Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20002950/UPS3Q2

Date: 06/07/2020

**REFERENCE** 

India International Insurance Handling Insurer:

Pte Ltd

Policy No: D18MPC0001344\_01

Claimant Vehicle No:

Date of Loss:

SLF8105E

15/02/2020

**Insured Vehicle** No:

SKV1695S

Nature of Claim: TP Claim

MPC2020D0000383 No:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SLF8105E** Reg No:

Make & Model: NISSAN X-TRAIL, 2.0 CVT (A) Engine No: MR20889781B 10/09/2016 (Man. Year: 2016) Reg. Date: Chassis No: JN1JANT32Z0002435

Colour: Odometer: 85707 km Grey

1997 cc **Engine Capacity:** Market Value/New Car

Price:

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable): No

**CONDITION OF TYRES** 

Front Tyre Size: 225/60 R18 225/60 R18 Rear Tyre Size: Toyo 7 mm Front Left Side: Rear Left Side: Toyo 7 mm Front Right Side: Toyo 7 mm Rear Right Side: Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,395.20	4,644.78	750.42	13.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	770.00	1,050.00	57.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,215.20	5,414.78	1,800.42	24.95
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	7,215.20	4,300.00	2,915.20	40.40
+ GST 7.00/7.00% (S\$)	505.06	301.00	204.06	40.40
Nett Amount (S\$)	7,720.26	4,601.00	3,119.26	40.40
+ Loss of Use (3.0 x S	6100.00/day) (S\$)	300.00		
+ Doc	31.00			
Nett Liability (S\$)		4,932.00		
Global Sum	4,900.00			

**INSPECTION** 

Date of Assignment: 20/02/2020

Date Inspected: 20/02/2020 Inspected At: Focus Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #02-48/50 Autobay

Singapore 417883

Adjuster Report Page 2 of 4

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

#### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 23 Mar 2020)

Parts: N/A NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLF8105E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	. Particulars	Condition	Repairer's	Amount		
1	1		*FRONT FENDER -LH	Repair	641.70 FN	*- FN		
2	1		*FRONT FENDER PROTECTOR -LH	Cut / Deformed	208.50 FN	*208.50 FN		
3	1		*FRONT FENDER DUST COVER -LH	Torn	119.70 FN	*119.70 FN		
4	6		*FRONT FENDER DUST COVER CLIPS-LH	Necessary	33.00 FN	*33.00 FN		
5	1		*FRONT HEADLAMP -LH	Cracked	2,576.00 FN	*2,576.00 FN		
6	1		*FRONT HEADLAMP LOWER BRACKET-LH	Cracked	28.10 FN	*28.10 FN		
7	1		*FRONT BUMPER	Distorted	594.10 FN	*594.10 FN		
8	1		*FRONT BUMPER INNER SPONGE	Torn	326.50 FN	*326.50 FN		
9	1		*FRONT BUMPER REINFORCEMENT	Dented	507.00 FN	*507.00 FN		
10	1		*FRONT BUMPER TOWING COVER	Twisted	28.50 FN	*28.50 FN		
11	1		*FRONT BUMPER FOG LAMP COVER -LH	Twisted	135.80 FN	*135.80 FN		
12	1		*FRONT BUMPER FOG LAMP COVER CHROME -LH	Cracked	50.00 FN	*50.00 FN		
13	1		*FRONT BUMPER CENTRE MOULDING	Cracked	194.00 FN	*194.00 FN		
14	1		*FRONT RESOTAINER BOX	Not Necessary	192.10 FN	*- FN		
15	1		*FRONT BUMPER FOG LAMP -LH	Cracked	323.70 FS	*323.70 FS		
F=Franchise part. S=SpcNett. N=NettItemDisc.								
				Sub Total (S\$)	•	5,124.90		
- Nett Item Discount on N Items 10.00/10.00% (S\$)				563.50	480.12			
				Total Parts (S\$)	5,395.20	4,644.78		

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	<u>Labour Items</u>						
1	PANEL BEATING	New	900.00	350.00			
2	CHECK WIRING	New	60.00	20.00			
3	RUST PROOFING	New	60.00	0.00			
4	SPRAY PAINTING	New	800.00	400.00			
		Gross Labour Cost (S\$)	1,820.00	770.00			

Report was unsubmitted during this print-out.

< END OF ESTIMATES >