

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20002953/UPS3Q2

Date: 04/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100326886

Claimant
Vehicle No : XE1195D **Insured Vehicle No :** GBC5557M

Date of Loss: 02/07/2019 Nature of Claim: TP Claim No: 7727062324SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE1195D**
 Make & Model: MITSUBISHI FUSO, 12.0 D FV51SS3VDEA (M) Engine No: OM457LA457972C0308894
 Reg. Date: 20/11/2015 (Man. Year: 2015) Chassis No: FV51SSA10118
 Colour: Red Odometer: 145897 km
 Engine Capacity: 11967 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D/D)
 Front Left Side: Austone 6 mm Rear Left Side: Austone 6/6/6 mm
 Front Right Side: Austone 6 mm Rear Right Side: Austone 6/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,060.00	1,374.69	1,685.31	55.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	630.00	550.00	80.00	12.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,690.00	1,924.69	1,765.31	47.84
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	3,690.00	1,500.00	2,190.00	59.35
+ Loss of Use (3.0 x S\$150.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,952.00		
Global Sum Settlement (S\$)		1,950.00		

INSPECTION

Date of Assignment: 20/02/2020

Date Inspected: 20/02/2020 Inspected At:

Liu's Brother Auto Engineering
 Workshop (kaki Bukit) (HQ)
 Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay
 @ Kaki Bt Singapore 417883, Kaki
 Bukit
 Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH TAIL LAMP	Cracked	450.00 F	*366.25 FL
2	1		*REAR RH TAIL LAMP BRACKET	Repair	300.00 F	*- FL
3	1		*REAR RH SAFETY BAR	Bent / Dented	1,800.00 FS	*1,100.00 FS
4	1		*REAR RH SAFETY BAR STRIP STICKER	Not fitted	120.00 FS	*- FS
5	2		*REAR RH NUMBER PLATE LAMPS	Not Necessary	390.00 F	*- F
					Sub Total (S\$)	3,060.00
					- List Item Discount on L Items 0.00/25.00% (S\$)	91.56
					Total Parts (S\$)	1,374.69

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	30.00	20.00
2	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	300.00	250.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED ARE	New	300.00	280.00
Gross Labour Cost (\$\$)			630.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >