

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INV No.

### **TAX INVOICE**

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877

INV Date Reference 28/08/2020 CC4/FCI20002954/Kda3q2

Code FCI2

AC2005939

### **PROFESSIONAL SERVICE FEE**

Vehicle No. SKN 7818H

Insured Veh. SH 7259H

Claim No. D20001084MFSH

Policy No. D-20094922MFSH

Accident Date 13/02/2020

Inspection Date 20/02/2020

| Description         | Total  |
|---------------------|--------|
| Survey Inspection   | 439.00 |
| Resurvey Inspection |        |
| Digital Photographs |        |
| Transportation      |        |
| Subtotal            | 439.00 |
| GST (7%)            | 30.73  |
| Grand Total         | 469.73 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|   | Affiliated to Federation Internationale Des Experts En Automobile   |   |                    |                    |  |  |  |  |
|---|---|---|--------------------|--------------------|--|--|--|--|
| MS F  | S FIRST CAPITAL INSURANCE LTD Ref: CC4/FCl20002954/Kda3q2   |   |                    |                    |  |  |  |  |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877 |   | Date: 28-08-2020 Code: FCI2   |                    |                    |  |  |  |  |
| 1.  | 1. Policy Particulars :- THIRD PARTY CLAIM  |   |                    |                    |  |  |  |  |
|   | Insured Veh.  | SH 7259H  | Veh. Inspected     | SKN 7818H          |  |  |  |  |
|   | Policy No.  | D-20094922MFSH  | Coverage (\$)      | 0.00               |  |  |  |  |
|   | Claim No.   | D20001084MFSH   | Excess (\$)        | 0.00               |  |  |  |  |
|   | Assign From   | JASON TEA   | Assign Date        | 19/02/2020         |  |  |  |  |
| 2.  |   | Vehicle Partic  | culars & Condition |                    |  |  |  |  |
|   | Make & Model  | CITROEN CROSSBACK (A)   | c.c                | 1560               |  |  |  |  |
|   | Engine No.  | HIDDEN  | Year of Reg.       | 2017               |  |  |  |  |
|   | Chassis No.   | VF7NXBHZTGY533216   | Colour             | METALLIC BLACK     |  |  |  |  |
|   | Odometer  | 52610   | Steering           | IN ORDER           |  |  |  |  |
|   | Brakes  | IN ORDER  | Modification       | STANDARD ALLOY RIM |  |  |  |  |
|   | General   | GOOD  |                    |                    |  |  |  |  |
| 3.  | _   | Conditi   | ons of Tyres       | _                  |  |  |  |  |
|   |   | Size  | Make               | Balance            |  |  |  |  |
|   | R/H Front Tyre  | 215/55 R17  | KUMHO              | 9 mm               |  |  |  |  |
|   | L/H Front Tyre  | 215/55 R17  | KUMHO              | 9 mm               |  |  |  |  |
|   | R/H Rear Tyre   | 215/55 R17  | KUMHO              | 9 mm               |  |  |  |  |
|   | L/H Rear Tyre   | 215/55 R17  | KUMHO              | 9 mm               |  |  |  |  |
| 4.  |   | · · · · · · · · · · · · · · · · · · ·                                 | on of Damages      |                    |  |  |  |  |
|   | THE VEHICLE SU  | STAINED DAMAGES AT THE O/S  | FRONT BODY.        |                    |  |  |  |  |
|   | DAMAGES SEE D   | ETAILS.   |                    |                    |  |  |  |  |
| 5.  |   | Genera  | Information        |                    |  |  |  |  |
|   | Accident Date   | 13/02/2020  | Inspection Date    | 20/02/2020         |  |  |  |  |
|   | Survey held at  | POON SIANG SEOW   |                    |                    |  |  |  |  |
|   |   | No.160 SIN MING DRIVE<br>#05-13 SIN MING AUTOCITY<br>SINGAPORE 575722 |                    |                    |  |  |  |  |
| 5a.   |   | Ro  | emarks             |                    |  |  |  |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                    |                    |  |  |  |  |
| 5b.   | b. Estimate Days of Repair  |   |                    |                    |  |  |  |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days  |   |                    |                    |  |  |  |  |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 7818H

| Qty | Description of Parts  | Condition               | Estimate By<br>Workshop (\$)) | Our Adjusted<br>(\$) |
|-----|---|-------------------------|-------------------------------|----------------------|
|     | REPLACEMENT OF PARTS  |                         |                               |                      |
| 1   | FRONT DOOR RIGHT  | BENT                    | 4,958.00                      | 4,958.00             |
| 2   | FRONT DOOR HINGE  | TO REPAIR SEE<br>LABOUR | 240.00                        | -                    |
| 1   | FRONT DOOR RUBBER   | NECESSARY               | 480.00                        | 480.00               |
| 1   | FRONT FENDER  | BENT                    | 2,985.00                      | 2,985.00             |
| 1   | FRONT FENDER ARC GARNISH                                    | BENT                    | 2,180.00                      | 2,180.00             |
| 1   | ROCKER PANEL GARNISH  | DENTED / CUT            | 650.00                        | 650.00               |
| 1   | HEAD LAMP RIGHT   | SERVICEABLE             | 3,500.00                      | -                    |
|     | LESS 10% DISCOUNT   |                         | -                             | -1,125.30            |
|     |   |                         | 14,993.00                     | 10,127.70            |
|     | SPECIAL NETT ITEMS  |                         |                               |                      |
| 1   | FRONT WHEEL RIM (LOCAL PURCHASE)(SN)                        | SCRATCHED               | 3,480.00                      | 280.00               |
|     |   |                         | 3,480.00                      | 280.00               |
|     | LABOUR  |                         |                               |                      |
|     | RUST PROOFING .   |                         | 100.00                        | 60.00                |
|     | PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT DOOR HINGE . |                         | 980.00                        | 500.00               |
|     | SPRAY PAINTING .  |                         | 900.00                        | 500.00               |
|     |   |                         | 1,980.00                      | 1,060.00             |
|     | GRAND TOTAL   |                         | 20,453.00                     | 11,467.70            |
|     |   |                         |                               |                      |

| RECOMMENDED COST OF LUMP SUM REPAIRS |  | 9.150.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION)      |  | 2,100100 |

Report Ref No. CC4/FCI20002954/Kda3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SKN 7818H



















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R











51 Uki Ave 1 #01-25 Pays Uki Industrial Park, Singspore 408933 TBL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKN 7818H

RE-INSPECTION





