

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20002957/UPS3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0004012
Claimant Vehicle No :	FBP6327K	Insured Vehicle No :	GBF2488H
Date of Loss:	09/02/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0000367

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP6327K	Engine No:	LTA2002067
Make & Model:	YAMAHA XMAX 300, 292cc	Chassis No:	MH3SH0841KK006066
Reg. Date:	14/05/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Orange		
Engine Capacity:	292 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R15	Rear Tyre Size:	140/70 R14
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,276.30	9,154.27	2,122.03	18.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,349.00	1,747.00	1,602.00	47.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	14,625.30	10,901.27	3,724.03	25.46
+ GST 7.00/7.00% (\$\$)	1,023.77	763.09	260.68	25.46
Nett Amount (\$\$)	15,649.07	11,664.36	3,984.71	25.46
+ Loss of Use (8.0 x S\$20.00/day) (\$\$)		160.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		11,826.36		
Global Sum Settlement (\$\$)		11,800.00		

INSPECTION

Date of Assignment:	20/02/2020		
Date Inspected:	20/02/2020	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ)
			No. 6 Defu Lane 4
			Singapore 539410
Estimated Period of Repair:	7.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$14,000.00(est) less LTA Rebate: \$2,775.00(est) = Nett Value :\$11,225.00(est)

Please note that third party vehicle COE expiry date is May 2029.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Mar 2021)	
Parts:	N/A	YAMAHA XMAX 300 292cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP6327K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ARM REAR ASSY	Cracked /Damaged	223.00 F	*223.00 FL
2	1		*AXLE DRIVE	Twisted	63.00 F	*63.00 FL
3	1		*BALANCER HANDLE	Scratched	7.00 F	*7.00 FL
4	1		*BALANCER WHEEL (20G)	Scratched	9.00 F	*9.00 FL
5	1		*BASE PLATE (GIVI) BOX REAR	Bent	125.00 F	*125.00 FL
6	1		*BEARING	Necessary	9.00 F	*9.00 FL
7	2		*BEARING	Necessary	118.00 F	*118.00 FL
8	1		*BEARING		17.00 F	*17.00 FL
9	1		*BEARING 6002	Necessary	20.00 F	*20.00 FL
10	1		*BEARING 6205	Necessary	37.00 F	*37.00 FL
11	3		*BEARING 6303	Necessary	30.00 F	*30.00 FL
12	1		*BEARING 6304	Necessary	31.00 F	*31.00 FL
13	2		*BEARING PLATE CONNECTING ROD	Necessary	20.00 F	*20.00 FL
14	2		*BEARING PLANE CONNECTING ROD	Necessary	20.00 F	*20.00 FL
15	2		*BEARING PLANE CRANK	Necessary	24.00 F	*24.00 FL
16	2		*BEARING PLANE CRANK	Necessary	24.00 F	*24.00 FL
17	2		*BEARING PLANE CRANK	Necessary	24.00 F	*24.00 FL
18	2		*BEARING PLANE CRANK	Necessary	28.00 F	*28.00 FL
19	2		*BEARING PLANE CRANK	Necessary	28.00 F	*28.00 FL
20	2		*BEARING PLANE CRANK	Necessary	28.00 F	*28.00 FL
21	3		*BOLT	Necessary	15.00 F	*15.00 FL
22	6		*BOLT	Necessary	12.00 F	*12.00 FL
23	2		*BOLT	Necessary	10.00 F	*10.00 FL
24	1		*BOLT FLANGE	Necessary	2.00 F	*2.00 FL
25	1		*BOX REAR (GIVI) V56N MAXIA 4	Broken	884.00 F	*884.00 FL
26	1		*BRACKET ENGINE COMP	Bent	178.00 F	*178.00 FL
27	1		*BRACKET FIBRE (FOR 6 LED)	Bent	142.00 F	*142.00 FL
28	1		*BRACKET REAR BOX (KAPPA)	Bent	187.00 F	*187.00 FL
29	1		*BUSH SHOCK ABSORBER	Necessary	12.00 F	*12.00 FL
30	1		*CALIPER ASSY, REAR	Damaged / Jammed	297.00 F	*297.00 FL
31	1		*CAMERA (V-SYS) M6 (NON-WIFI VERSION) (NEW)	Bent	405.00 F	*405.00 FL
32	1		*CAP PROTECTOR EXHAUST	Broken	38.00 F	*38.00 FL
33	1		*CASE ,CHAIN TENSIONER	Necessary	5.00 F	*5.00 FL
34	1		*CHAIN TIMING	Necessary	24.00 F	*24.00 FL
35	2		*CLAMP	Necessary	6.00 F	*6.00 FL
36	2		*COLLAR ,UNION	Necessary	46.00 F	*46.00 FL
37	1		*COVER 5	Cut	10.00 F	*10.00 FL
38	1		*COVER AIR FILTER	Cut	45.00 F	*45.00 FL
39	1		*COVER BATTERY	Scratched	20.00 F	*20.00 FL
40	1		*COVER CAP PROTECTOR EXHAUST INNER	Damaged	51.00 F	*51.00 FL
41	1		*COVER COWLING LH	Cut	31.00 F	*31.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*COVER CRANKCASE OUTER	Cut	23.00 F	*23.00 FL
43	1		*COVER FRONT	Scratched	105.00 F	*105.00 FL
44	1		*COVER LOWER FIRING LH	Scratched	38.00 F	*38.00 FL
45	1		*COVER METER	Cracked	45.00 F	*45.00 FL
46	1		*COVER TAIL CENTER	Broken	27.00 F	*27.00 FL
47	1		*COVER TAIL LH	Broken	42.00 F	*42.00 FL
48	1		*COVER TAIL LOWER LH	Broken	28.00 F	*28.00 FL
49	1		*COVER TAIL LOWER RH	Scratched	14.00 F	*14.00 FL
50	1		*COVER TAIL RH (MATT BLACK)	Broken	38.00 F	*38.00 FL
51	1		*COVER ,REAR FENDER	Damaged	19.00 F	*19.00 FL
52	1		*CRANKCASE ASSY	Broken	370.00 F	*370.00 FL
53	1		*DAMPER 5	Necessary	38.00 F	*38.00 FL
54	1		*DAMPER PLATE	Necessary	3.00 F	*3.00 FL
55	1		*DAMPER PLATE	Necessary	17.00 F	*17.00 FL
56	1		*DAMPER PLATE	Necessary	9.00 F	*9.00 FL
57	1		*EMBLEM COVER AIR FILTER	Damaged	6.00 F	*6.00 FL
58	1		*EMBLEM	Necessary	9.00 F	*9.00 FL
59	1		*EMBLEM	Necessary	54.00 F	*54.00 FL
60	1		*EMBLEM (YAMAHA) LOGO	Necessary	19.00 F	*19.00 FL
61	1		*FENDER FRONT	Cut	24.00 F	*24.00 FL
62	1		*FILTER OIL	Necessary	14.00 F	*14.00 FL
63	1		*FOOTBOARD LH	Cut	31.00 F	*31.00 FL
64	1		*GASKET	Not Necessary	2.00 F	*- FL
65	1		*GASKET	Not Necessary	5.00 F	*- FL
66	1		*GASKET CRANKCASE COVER	Necessary	19.00 F	*19.00 FL
67	1		*GASKET EXHAUST PIPE	Necessary	9.00 F	*9.00 FL
68	1		*GASKET MUFFLER	Necessary	7.00 F	*7.00 FL
69	1		*GASKET ,BREATHER COVER	Necessary	7.00 F	*7.00 FL
70	1		*GASKET ,CRANKCASE	Necessary	3.00 F	*3.00 FL
71	1		*GASKET ,CYLINDER	Necessary	6.00 F	*6.00 FL
72	1		*GASKET ,CYLINDER HEAD	Necessary	16.00 F	*16.00 FL
73	1		*GASKET ,HEAD COVER 1	Necessary	13.00 F	*13.00 FL
74	1		*GUIDE STOPPER 1	Necessary	38.00 F	*38.00 FL
75	1		*GUIDE STOPPER 2	Necessary	68.00 F	*68.00 FL
76	1		*HANDLE BAR	Bent	54.00 F	*54.00 FL
77	1		*HANDLE REAR	Bent	90.00 F	*90.00 FL
78	2		*HOLDER	Twisted	76.00 F	*76.00 FL
79	1		*LEVER BRAKE LH	Cut	27.00 F	*27.00 FL
80	1		*LIGHT BOX REAR (GIVI) E160	Cracked	147.00 F	*147.00 FL
81	2		*LIGHT LED (JL) 6 LED AMBER & WHITE -CLEAR LENS	Not Necessary	932.00 F	*- FL
82	1		*LIGHT LED (JL) LED AMBER LENS	Cracked	373.00 F	*373.00 FL
83	1		*LIGHT LICENCE ASSY	Broken	37.00 F	*37.00 FL
84	1		*LIGHT TAIL UNIT ASSY	Broken	178.00 F	*178.00 FL
85	1		*LIGHT TAIL UNIT ASSY	Broken	178.00 F	*178.00 FL
86	1		*MID BOLT	Necessary	5.00 F	*5.00 FL
87	1		*MID WASHER PLATE	Necessary	3.00 F	*3.00 FL
88	1		*MIRROR LH	Scratched	42.00 F	*42.00 FL
89	1		*MUDGUARD REAR	Broken	23.00 F	*23.00 FL
90	1		*MUFFLER ASSY	Bent	962.00 F	*962.00 FL
91	1		*NOZZLE 3	Necessary	5.00 F	*5.00 FL
92	4		*NUT (WINDSCREEN)	Necessary	20.00 F	*20.00 FL
93	2		*OIL ENGINE (YAMAHA) 20W -40 (4ST) S.S	Necessary	24.00 F	*24.00 FL
94	1		*OIL GEAR (UNITED) GL-5	Necessary	3.30 F	*3.30 FL
95	1		*O-RING	Necessary	2.00 F	*2.00 FL
96	1		*O-RING	Necessary	2.00 F	*2.00 FL
97	1		*O-RING	Necessary	2.00 F	*2.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	2		*O-RING	Necessary	4.00 F	*4.00 FL
99	1		*O-RING	Necessary	2.00 F	*2.00 FL
100	1		*O-RING	Necessary	5.00 F	*5.00 FL
101	1		*O-RING	Necessary	13.00 F	*13.00 FL
102	4		*O-RING(GEAR STARTER 3)	Necessary	24.00 F	*24.00 FL
103	1		*O-RING THERMOSTAT	Necessary	3.00 F	*3.00 FL
104	1		*O-RING VALVE	Necessary	3.00 F	*3.00 FL
105	2		*PAD ,ADJUSTING (1.60)	Necessary	12.00 F	*12.00 FL
106	2		*PAD ,ADJUSTING (1.65)	Necessary	12.00 F	*12.00 FL
107	2		*PAD ,ADJUSTING (1.75)	Necessary	12.00 F	*12.00 FL
108	2		*PAD ,ADJUSTING (1.80)	Necessary	12.00 F	*12.00 FL
109	1		*PIN PISTON	Necessary	16.00 F	*16.00 FL
110	1		*PISTON (STD)	Necessary	75.00 F	*75.00 FL
111	1		*PISTON RING SET (STD)	Necessary	42.00 F	*42.00 FL
112	1		*PLATE DISC BRAKE REAR	Bent	75.00 F	*75.00 FL
113	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Bent	27.00 F	*27.00 FL
114	1		*PROTECTOR EXHAUST	Damaged	45.00 F	*45.00 FL
115	1		*REAR BLINKER (ORANGE)	Scratched	3.00 F	*3.00 FL
116	1		*REFLECTOR ASSY REAR	Cracked	5.00 F	*5.00 FL
117	1		*REFLECTOR, FRONT	Cracked	5.00 F	*5.00 FL
118	1		*RIM SPORT REAR	Cracked	342.00 F	*342.00 FL
119	4		*RIVET	Necessary	8.00 F	*8.00 FL
120	2		*RIVET	Necessary	10.00 F	*10.00 FL
121	1		*ROTOR SENSOR	Damaged	26.00 F	*26.00 FL
122	4		*SCREW (VISOR)	Necessary	20.00 F	*20.00 FL
123	1		*SCREW PLUG	Necessary	2.00 F	*2.00 FL
124	1		*SEAL	Necessary	5.00 F	*5.00 FL
125	1		*SEAL OIL	Necessary	9.00 F	*9.00 FL
126	1		*SEAL OIL	Necessary	14.00 F	*14.00 FL
127	1		*SEAL OIL	Necessary	9.00 F	*9.00 FL
128	1		*SEAL OIL PUMP	Necessary	45.00 F	*45.00 FL
129	4		*SEAL VALVE	Necessary	28.00 F	*28.00 FL
130	1		*SEAT DOUBLE ASSY	Damaged / Twisted	444.00 F	*444.00 FL
131	1		*SEAT PROTECTOR EXHAUST	Damaged	38.00 F	*38.00 FL
132	1		*SEAT UNDER BOX	Cracked	194.00 F	*194.00 FL
133	1		*SHAFY ASSY	Twisted	61.00 F	*61.00 FL
134	1		*SHAFY PIVOT	Necessary	23.00 F	*23.00 FL
135	1		*STAND MAIN	Bent	135.00 F	*135.00 FL
136	1		*STAND SIDE	Scratched	31.00 F	*31.00 FL
137	1		*STARTER ONE -WAY ASSY	Damaged	82.00 F	*82.00 FL
138	1		*STAY 1	Bent	133.00 F	*133.00 FL
139	1		*STAY WINDSHIELD	Bent	38.00 F	*38.00 FL
140	1		*STAY WINDSHIELD 2	Bent	38.00 F	*38.00 FL
141	1		*TYRE 140/70-14 (SHINKO) SR568	Cut	140.00 F	*140.00 FL
142	1		*UPPER COVER METER	Cracked	38.00 F	*38.00 FL
143	1		*VALVE RELIEF ASSY	Damaged	31.00 F	*31.00 FL
144	1		*VALVE RIM	Necessary	7.00 F	*7.00 FL
145	2		*WASHER BOLT (MASTER CYLINDER PUMP)	Necessary	6.00 F	*6.00 FL
146	1		*WINDSHIELD	Scratched	299.00 F	*299.00 FL
147	1		*STICKER (ORANGEFORCE) BOX REAR NEW	Necessary	28.00 FS	*28.00 FS
148	1		*STICKER NUMBER PLATE FRONT (BLACK)	Necessary	19.00 FS	*19.00 FS
149	1		*STICKER (ORANGEFORCE) COVER SIDE LH/RH NEW	Necessary	70.00 FS	*70.00 FS
150	1		*STICKER (ORANGEFORCE) WINDSHIELD NEW	Necessary	28.00 FS	*28.00 FS
151	2		*BEARING PLANE CONNECTING ROD	Necessary	20.00 F	*20.00 FL
152	1		*TENSIONER ASSY ,CAM CHAIN	Twisted	97.00 F	*97.00 FL
153	1		*BALANCER ASSY	Damaged	229.00 F	*229.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
154	1		*BEARING 6204 (NSK)	Necessary	14.00 F	*14.00 FL
155	1		*BODY FRONT UNDER 1	Cracked	38.00 F	*38.00 FL
156	6		*BOLT CONNECTING ROD	Necessary	24.00 F	*24.00 FL
157	1		*CARD MICRO SD (SANDISK) 32GB VIDEO	Not Necessary	30.00 F	*- FL
158	1		*CHAIN	Not Necessary	90.00 F	*- FL
159	2		*CLIP COVER (PLASTIC)	Necessary	12.00 F	*12.00 FL
160	1		*COVER LIGHT BOX V56N	Broken	78.00 F	*78.00 FL
161	4		*GASKET	Repeated	24.00 F	*- FL
162	1		*GASKET CYLINDER	Repeated	8.00 F	*- FL
163	1		*GASKET CYLINDER HEAD	Repeated	30.00 F	*- FL
164	2		*GROMMET	Necessary	12.00 F	*12.00 FL
165	1		*LEG SHIELD 1	Cracked	45.00 F	*45.00 FL
166	6		*NUT	Necessary	36.00 F	*36.00 FL
167	1		*BEARING 6002-2NS (NACHI)	Necessary	13.00 F	*13.00 FL
168	2		*COOLANT (MOBIL) ANTIFREEZE	Necessary	24.00 F	*24.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,276.30	10,155.30
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,001.03
Total Parts (\$\$)	11,276.30	9,154.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR-FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED	New	2,268.00	935.00
2	MISCELLANEOUS FEE (CRANKCASE INSPECTION)	New	75.00	35.00
3	MISCELLANEOUS FEES (VITAS)	New	84.00	35.00
4	SPRAY PAINT REAR GIVI BOX	New	154.00	154.00
5	SPRAY PAINT WHOLE BODY	New	532.00	532.00
6	TRANSPORT CHARGES	New	56.00	56.00
7	LABOUR	New	180.00	0.00
Gross Labour Cost (S\$)			3,349.00	1,747.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >