

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002960/UDS3Q2

Date: 03/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800127526

Claimant
Vehicle No : SLZ4047K **Insured Vehicle No :** SMF2221E

Date of Loss: 18/02/2020 Nature of Claim: TP Claim No: 1516727152SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ4047K		
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Engine No:	LEB6550037
Reg. Date:	30/04/2018 (Man. Year: 2018)	Chassis No:	GP71208205
Colour:	Silver	Odometer:	150649 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,080.76	4,311.36	4,769.40	52.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,020.00	1,940.00	1,080.00	35.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,100.76	6,251.36	5,849.40	48.34
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	12,100.76	5,000.00	7,100.76	58.68
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,707.45		

INSPECTION

Date of Assignment: 20/02/2020

Date Inspected: 20/02/2020 Inspected At:

ASIA MOTORSPORTS SOLUTION
PTE LTD
37A EVERITT ROAD
SINGAPORE 428586

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,425.00 FL	*1,231.10 FL
2	1		*TAILGATE CENTRE CHROME GARNISH	Not Necessary	425.00 FL	*- FL
3	1		*SET TAILGATE CENTRE CHROME GARNISH CLIPS	Not Necessary	40.00 FL	*- FL
4	1		*TAILGATE INNER LOCK	Twisted	278.00 FL	*278.00 FL
5	1		*TAILGATE INNER LOCK CATCH	Not Necessary	98.00 FL	*- FL
6	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	547.00 FL	*366.50 FL
7	1		*TAILGATE INNER TRIM HANDLE (GARNISH)	Not Necessary	122.00 FL	*- FL
8	2		*TAILGATE HINGES (NPA)	Not Necessary	0.00 FL	*- FL
9	2		*TAILGATE DAMPER	Not Necessary	596.40 FL	*- FL
10	2		*TAILGATE RUBBER STOPPER	Not Necessary	11.60 FL	*- FL
11	1		*TAILGATE HONDA BADGE	Necessary	92.00 FL	*45.00 FL
12	1		*TAILGATE SHUTTLE EMBLEM	Necessary	98.00 FL	*74.10 FL
13	1		*TAILGATE HYBRID EMBLEM	Necessary	78.00 FL	*78.00 FL
14	1		*REAR FLOOR PANEL TOP BOARD	Cracked	990.40 FL	*586.20 FL
15	1		*TAILGATE WIPER MOTOR (NPA)	Not Necessary	0.00 FL	*- FL
16	2		*RHS & LHS TAILLAMP	Not Necessary	1,744.80 FL	*- FL
17	1		*REAR WINDSCREEN INNER EDGE SEAL	Necessary	172.00 FL	*172.00 FL
18	1		*REAR BUMPER	Distorted	1,242.00 FL	*986.40 FL
19	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	144.00 FL	*- FL
20	2		*REAR BUMPER REFLECTORS	Not Necessary	249.00 FL	*- FL
21	1		*REAR BUMPER REFLECTOR COVERS	N/S Twisted	196.00 FL	*98.00 FL
22	1		*REAR BUMPER INNER SPONGE	Torn	42.00 FL	*42.00 FL
23	1		*REAR BUMPER TOW COVER	Not Necessary	72.00 FL	*- FL
24	1		*REAR END PANEL	Badly Dented	762.00 FL	*546.10 FL
25	1		*REAR END PANEL TOP GARNISH	Twisted	298.00 FL	*226.80 FL
26	1		*REAR BOOT EDGE WEATHERSTRIP	Twisted	184.00 FL	*184.00 FL
27	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*40.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
29	1		*REVERSE CAMERA	Serviceable	480.00 FS	*- FS
30	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
31	1		*REAR LICENCE PLATE W/HOLDER	Serviceable	75.00 FS	*- FS
32	1		*REAR LICENCE PLATE LAMPS (NPA)	Not Necessary	0.00 FS	*- FS
33	1		*TAILGATE TOP SPOILER (NPA)	Not Necessary	0.00 FS	*- FS
34	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	60.00 FS	*50.00 FS
35	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,062.20 5,294.20
- List Item Discount on L Items 20.00/20.00% (\$\$) 1,981.44 982.84

Total Parts (\$\$) 9,080.76 4,311.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS	New	1,400.00	800.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	800.00	780.00
3	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	150.00	30.00
4	TO REMOVE AND REFIX /REPLACE REAR TRIMS ,GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR	New	180.00	80.00
5	TO REMOVE AND REPLACE REVERSE SENSORS & REVERSE CAMERA AND CHECK FOR PROPER FUNCTION	New	200.00	50.00
6	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN	New	140.00	120.00
7	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	150.00	80.00
Gross Labour Cost (\$\$)			3,020.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >