

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/III20002961/GGS3Q2

**Date:** 30/06/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SFV7771A	<b>Insured Vehicle No :</b>	SHC8134J
Date of Loss: 19/02/2020	Nature of Claim: TP	Claim No: MCT20020397

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFV7771A		
Make & Model:	BMW 218I, 1.5 Active Tourer Business (F45) (A)	Engine No:	F3671318B38B15A
Reg. Date:	25/02/2016 (Man. Year: 2015)	Chassis No:	WBA2F12030V312498
Colour:	White	Odometer:	54400 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,974.05	4,304.95	669.10	13.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,841.50	6,521.20	1,320.30	16.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,815.55</b>	<b>10,826.15</b>	<b>1,989.40</b>	<b>15.52</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>897.09</b>	<b>757.83</b>	<b>139.26</b>	<b>15.52</b>
<b>Nett Amount (S\$)</b>	<b>13,712.64</b>	<b>11,583.98</b>	<b>2,128.66</b>	<b>15.52</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		<b>300.00</b>		
		<b>11,883.98</b>		

#### INSPECTION

Date of Assignment:	02/03/2020	
Date Inspected:	02/03/2020	Inspected At: Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259 Singapore 569536
Estimated Period of Repair:	5.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 02 Jun 2020)
<b>Parts:</b> M1-MPV	BMW 218I 1.5 Active Tourer Business (F45) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFV7771A)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*HEXAGON SCREW WITH NUT	Necessary	6.85 FS	*6.85 FS
3	1		*ALLOY RIM M DOUBLE SPOKE 461 7.5X18	Cut	1,024.65 FS	*1,024.65 FS
4	1		*FRT RH FENDER	Buckled	597.25 FS	*597.25 FS
5	1		*SIDE PANEL BRACKET FRT RH 3	Not Necessary	35.10 FS	*- FS
6	1		*FRT RH 2 SIDE PANEL BRACKET	Not Necessary	35.10 FS	*- FS
7	1		*FRT RH 2 SIDE PANEL BRACKET	Not Necessary	35.10 FS	*- FS
8	10		*EXPANDING RIVET	Not Necessary	5.00 FS	*- FS
9	8		*BUMPER RIVET	Not Necessary	4.00 FS	*- FS
10	1		*EMBLEM (M)	Necessary	82.35 FS	*82.35 FS
11	6		*RIVET	Not Necessary	3.00 FS	*- FS
12	1		*COVER WHEEL HOUSING FRT RH	Not Necessary	79.75 FS	*- FS
13	1		*FRT RH WHEEL ARCH COVER FRT SECTION	Not Necessary	105.40 FS	*- FS
14	1		*RH SILL STRIP PRIMED (M)	Not Necessary	334.45 FS	*- FS
15	1		*SUPPORTING LEDGE RH	Damaged	18.95 FS	*18.95 FS
16	1		*RH TENSION STRUT W	Bent	271.15 FS	*271.15 FS
17	1		*RH WISHBONE	Bent	271.15 FS	*271.15 FS
18	3		*COMBINATION NUT M1	Bent	17.40 FS	*17.40 FS
19	1		*RH TIE ROD	Bent	296.65 FS	*296.65 FS
20	1		*FRT SPRING STRUT	Bent	346.85 FS	*346.85 FS
21	1		*WHEEL HUB WITH BEA	Bent	484.55 FS	*484.55 FS
22	1		*FRT RH CARRIER	Bent	463.45 FS	*463.45 FS
23	1		*SPHERICAL COLLAR S (8 PCS)	Bent	64.40 FS	*32.20 FS
24	1		*FRT GUIDE SUPPORT	Bent	239.00 FS	*239.00 FS
25	1		*HEX NUT WITH FLANG	Bent	2.50 FS	*2.50 FS
<b>Total Parts (S\$)</b>					<b>4,974.05</b>	<b>4,304.95</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT RIGHT UNDERCARRIAGE PARTS	New	1,327.50	1,327.50
2	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION 2ND ROUND	New	531.00	451.00
3	REPLACING FRONT RIGHT SIDE FENDER INCLUDE REMOVE ATTACHMENT ETC INCLUDE REPAIR ON ACCIDENT DAMAGE AREA	New	2,550.00	1,700.00
4	SPRAY PAINTING RIGHT FRONT DOOR RIGHT FRONT SIDE FENDER AND RIGHT LOWER SIDE SKIRTING	New	2,513.00	2,261.70
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
6	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING RIGHT FRONT	New	94.00	80.00
7	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
8	TO CONDUCT CHECKS ON ALL DOORS AND BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	150.00
			<b>Gross Labour Cost (\$)</b>	<b>7,841.50</b>
				<b>6,521.20</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >