



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 7658L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT SPORT RIM (CONSISTENT)	TO REPAIR SEE LABOUR	250.00	-
1	FRONT FORK COMPLETE (CONSISTENT)	TO REPAIR SEE LABOUR	225.00	-
1	METER COMPLETE (CONSISTENT)	CRACKED	290.00	290.00
1	HANDLE BAR (CONSISTENT)	SERVICEABLE	65.00	-
1	BRAKE LEVER (CONSISTENT)	SCRATCHED	20.00	20.00
1	HANDLE GRIP (CONSISTENT)	SCRATCHED	20.00	20.00
1	MIRROR (CONSISTENT)	BROKEN	45.00	45.00
1	EXHAUST PIPE (CONSISTENT)	BROKEN	850.00	850.00
1	REAR FOOTREST BRACKET RH (CONSISTENT)	BROKEN	75.00	75.00
1	BODY COVER COMPLETE (CONSISTENT)	CRACKED	580.00	580.00
1	FRONT FOOTREST (CONSISTENT)	BENT	48.00	48.00
1	GEAR LEVER (CONSISTENT)	BENT	35.00	35.00
1	BRAKE LEVER (CONSISTENT)	REPEATED	20.00	-
1	MAGENTO COVER (CONSISTENT)	SCRATCHED	145.00	145.00
1	FRONT SIDE LIGHT LH (CONSISTENT)	SCRATCHED	55.00	55.00
1	HEAD LAMP COMPLETE (CONSISTENT)	SERVICEABLE	225.00	-
1	REAR FOOTREST (CONSISTENT)	BROKEN	45.00	45.00
1	THROTTLE CABLE (CONSISTENT)	BENT	55.00	55.00
1	STEERING CORN (CONSISTENT)	CRACKED	75.00	75.00
	LESS 10% DISCOUNT		-312.30	-233.80
			2,810.70	2,104.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	MAGNETO GASKET (CONSISTENT) (SN)	NECESSARY	12.00	12.00
1	ENGINE OIL (CONSISTENT) (SN)	NECESSARY	20.00	20.00
1	IU (CONSISTENT) (SN)	SCRATCHED	165.00	165.00
1	GIVI E33 BOX (CONSISTENT) (SN)	SCRATCHED	140.00	140.00
1	NUMBER PLATE (CONSISTENT) (SN)	SCRATCHED	15.00	15.00
			352.00	352.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TRANSPORT.		30.00	30.00
	ALIGNMENT FRONT BODY.		250.00	200.00
	LABOR.INCLUSIVE OF THE REPAIR OF FRONT SPORT RIM AND FRONT FORK COMPLETE .		250.00	200.00
			530.00	430.00
<b>GRAND TOTAL</b>			<b>3,692.70</b>	<b>2,886.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,000.00</b>

Report Ref No. CC4/ASM20002963/R1pa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.