

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20002969/EBA3Q2

Date: 23/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700070092-02

Claimant
Vehicle No : SLE8282G **Insured Vehicle No :** SLT9061S

Date of Loss: 17/02/2020 **Nature of Claim:** TP **Claim No:** 4089100385SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE8282G	Engine No:	CHH301126
Make & Model:	SKODA SUPERB, 2.0 (A)	Chassis No:	TMBBD7NP4K7034111
Reg. Date:	28/06/2019 (Man. Year: 2018)	Odometer:	8346 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,200.24	2,075.34	3,124.90	60.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	3,200.00	4,120.00	56.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	12,520.24	5,275.34	7,244.90	57.87
+ GST 7.00/7.00% (\$\$)	876.42	369.27	507.15	57.87
Nett Amount (\$\$)	13,396.66	5,644.61	7,752.05	57.87
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (\$\$)		642.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		6,288.61		

INSPECTION

Date of Assignment: 21/02/2020

Date Inspected: 21/02/2020 Inspected At: Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HALOGEN TW	Not Necessary	3,085.00 FS	*- FS
2	1		*COVER FOR (FRONT BUMPER)	Cut	1,760.00 FS	*1,760.00 FS
3	1		*GUIDE PIEC (BUMPER GUIDE RHS)	Not Necessary	39.90 FS	*- FS
4	1		*SENSOR BRA	Necessary	45.00 FS	*45.00 FS
5	1		*SENSOR BRA	Necessary	45.00 FS	*45.00 FS
6	1		*SENSOR BRA	Necessary	45.00 FS	*45.00 FS
7	1		*SENSOR BRA	Necessary	45.00 FS	*45.00 FS
8	1		*BONDING AGENT FOR PLASTIC	Necessary	59.40 FS	*59.40 FS
9	1		*2K-PLASTIC ADHESIVE	Necessary	75.94 FS	*75.94 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **5,200.24** **2,075.34**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	3,360.00	840.00
2	SPRAY PAINTING	New	3,200.00	1,600.00
3	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
4	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
Gross Labour Cost (\$\$)			7,320.00	3,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >