

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20002970/GKA3Q2

**Date:** 09/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900010515

**Claimant**  
**Vehicle No :** SLM5006R **Insured Vehicle No :** SMH6109K

Date of Loss: 15/02/2020 Nature of Claim: TP Claim No: 3199702538SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLM5006R</b>	Engine No:	CYV500240
Make & Model:	VOLKSWAGEN GOLF, 1.2 (A7) TSI (A)	Chassis No:	WVWZZZAUZHW093769
Reg. Date:	31/03/2017 (Man. Year: 2016)	Odometer:	57871 km
Colour:	Blue		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,260.01	80.00	2,180.01	96.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	2,120.00	3,280.00	60.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>7,660.01</b>	<b>2,200.00</b>	<b>5,460.01</b>	<b>71.28</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	536.20	154.00	382.20	71.28
<b>Nett Amount (\$\$)</b>	<b>8,196.21</b>	<b>2,354.00</b>	<b>5,842.21</b>	<b>71.28</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (\$\$)</b>		180.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>2,536.00</b>		

### INSPECTION

Date of Assignment: 27/02/2020

Date Inspected: 27/02/2020 Inspected At:

1 KAMPONG AMPAT OFF  
MACPHERSON  
Repairer: Volkswagen Group  
Singapore Pte Ltd

Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DIFFUSOR SATIN BLACK	Not Necessary	311.13 FS	*- FS
2	4		*RIVET	Not Necessary	4.36 FS	*- FS
3	1		*BUMPER REINFORCEMENT	Not Necessary	604.40 FS	*- FS
4	1		*ATTACHMENT STRIP RR CTR BRACKET	Not Necessary	63.22 FS	*- FS
5	1		*GUIDE PIECE LHR SIDE BRACKET	Not Necessary	36.38 FS	*- FS
6	1		*GUIDE PIECE RHR SIDE BRACKET	Not Necessary	36.38 FS	*- FS
7	1		*NUMBER PLATE	Scratched	80.00 FS	*80.00 FS
8	1		*COVER FOR BUMPER PRIMED REAR BUMPER	Repair	1,124.14 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)**      **2,260.01**      **80.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	LABOUR	New	2,520.00	840.00
3	SPRAY PAINTING	New	2,400.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,400.00</b>	<b>2,120.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >