

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20002971/GEA3Q2

Date: 30/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800103751

Claimant
Vehicle No : SMR9034U **Insured Vehicle No :** SMD7163S

Date of Loss: 19/02/2020 Nature of Claim: TP Claim No: 8209004315SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR9034U		
Make & Model:	BMW 320I, 2.0 (A)	Engine No:	F2783495B48B20A
Reg. Date:	31/01/2020 (Man. Year: 2019)	Chassis No:	WBA5F32080FH74738
Colour:	White	Odometer:	1021 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,834.60	2,158.50	676.10	23.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,487.00	4,790.00	697.00	12.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	8,321.60	6,948.50	1,373.10	16.50
+ GST 7.00/7.00% (\$\$)	582.51	486.40	96.11	16.50
Nett Amount (\$\$)	8,904.11	7,434.90	1,469.21	16.50
+ Loss of Use (3.0 x S\$100.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		7,736.90		

INSPECTION

Date of Assignment: 02/03/2020

Date Inspected: 02/03/2020 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER CARRIER	Bent	479.65 FS	*479.65 FS
3	1		*ADAPTER	Not Necessary	50.20 FS	*- FS
4	1		*REAR BUMPER LH TRIM PANEL (LUXURY)	Cracked	77.20 FS	*77.20 FS
5	1		*REAR BUMPER LH SIDE GUIDE	Not Necessary	58.25 FS	*- FS
6	1		*REAR BUMPER RH SIDE GUIDE	Not Necessary	58.25 FS	*- FS
7	1		*REAR BUMPER LH TRIM PANEL REAR TOP	Bent	95.35 FS	*95.35 FS
8	1		*REAR BUMPER LH BOTTOM TRIM PANEL (L)	Bent	96.00 FS	*96.00 FS
9	1		*REAR BUMPER PANEL PRIMED (BASIS PDC)	Cracked	1,274.95 FS	*1,274.95 FS
10	1		*SET MOUNTING PDC/PMA SENSOR REAR	Not Necessary	69.35 FS	*- FS
11	1		*EXPANDING RIVET D=8MM (15 PCS)	Necessary	16.50 FS	*16.50 FS
12	1		*REAR LH REAR REFLECTOR	Necessary	38.85 FS	*38.85 FS
13	1		*DECOUPLING RING	Not Necessary	5.10 FS	*- FS
14	1		*ULTRASONIC SENSOR MINERAL WHITE WA9	Not Necessary	381.90 FS	*- FS
15	1		*(DG/SL) ADHESIVE SET K6	Not Necessary	53.05 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,834.60** **2,158.50**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT TAIL PANEL AND DENTED AREA CAUSED BY THE ACCIDENT	New	2,125.00	1,700.00
2	TO RESPRAY REAR BUMPER AND TAIL PANEL	New	1,781.00	1,603.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	231.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
6	TO PULL ,STRAIGHTEN ,MAKE GOOD LEFT TRUNK FLOOR PANEL AND KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	425.00	425.00
7	TO RESPRAY TRUNK FLOOR PANEL	New	531.00	531.00
Gross Labour Cost (\$\$)			5,487.00	4,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >