



Your Ref : SNM20D200911

Date: 23<sup>rd</sup> March 2020

Our Ref : CS4/CTI20002982/R1vf3s2

**M/s China Taiping Insurance (Singapore) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE XD 1749L  
ACCIDENT ON 18/02/2020**

Instruction was received to inspect the vehicle Reg. No. XD 1749L. The inspection was conducted on 21/02/2020 at the premises of M/s Sng Ah Tee Motor & Panel Service Pte Ltd, Blk 3 Pioneer Road North #01-18 Singapore 628457.

The following vehicle information was recorded:

Registration Number	: XD 1749L
Make/Model	: Isuzu CYZ52L
Year of Registration	: 2007
Body Colour	: White
Chassis Number	: JALCYZ52L77000086
Engine Capacity	: 15681 cc

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$ 60,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 30,817.00)
Nett Liability	<u>S\$ 29,183.00</u>

Vehicle Inspected By:

MRB

MOHD. RASUL BIN MOHD YUNUS  
AMSOE, AMIRTE, AMSAE-A, M. MATAI  
Automotive Assessor

K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.