

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20002985/EQF3E2

**Date:** 07/09/2020

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN30674019011

**Claimant Vehicle No :** SLD9152Y

**Insured Vehicle No :** YP5615M

Date of Loss: 19/02/2020

Nature of Claim: TP

Claim No: SNM20D200923C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD9152Y**

Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)

Engine No: HRA2274537A

Reg. Date: 30/06/2016 (Man. Year: 2016)

Chassis No: SJNFEAJ11U1653595

Colour: Purple

Odometer: 59011 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,624.40	2,020.88	603.52	23.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,186.00	1,435.00	751.00	34.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,810.40</b>	<b>3,455.88</b>	<b>1,354.52</b>	<b>28.16</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>336.73</b>	<b>241.91</b>	<b>94.82</b>	<b>28.16</b>
<b>Nett Amount (S\$)</b>	<b>5,147.13</b>	<b>3,697.79</b>	<b>1,449.34</b>	<b>28.16</b>

### INSPECTION

Date of Assignment: 21/02/2020

Date Inspected: 25/02/2020 Inspected At:

TC AutoClinic Pte Ltd (Leng Kee)  
25 Leng Kee Road  
Singapore 159097

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 07 Sep 2020)
<b>Parts:</b>	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLD9152Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR UPPER PANEL	Not Necessary	482.60 FN	*- FN
2	1		*RIGHT REFLECTOR	Not Necessary	61.90 FN	*- FN
3	1		*LEFT REFLECTOR	Not Necessary	61.90 FN	*- FN
4	1		*REINFORCEMENT	Bent	691.50 FN	*691.50 FN
5	1		*BUMPER RIGHT BRACKET	Not Necessary	38.90 FN	*- FN
6	1		*BUMPER LEFT BRACKET	Not Necessary	38.90 FN	*- FN
7	1		*ENERGY ABSORBER	Broken	141.40 FN	*141.40 FN
8	1		*BUMPER RIGHT RETAINER	Not Necessary	25.70 FN	*- FN
9	1		*BUMPER LEFT RETAINER	Not Necessary	25.70 FN	*- FN
10	4		*CLIP	Necessary	5.20 FN	*5.20 FN
11	1		*TOW HOOK COVER	Not Necessary	18.80 FN	*- FN
12	1		*REAR BUMPER	Broken	796.70 FN	*796.70 FN
13	1		*REVERSE SENSOR (J11 & T32)	Shorted	360.00 FS	*360.00 FS
14	1		*ORNAMENT-BACK D	Necessary	94.40 FN	*94.40 FN
15	1		*EMBLEM-REAR	Necessary	64.90 FN	*64.90 FN
16	1		*STAY ASSY-REAR	Bent	141.00 FN	*141.00 FN
17	1		*STAY ASSY-REAR	Bent	141.00 FN	*141.00 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>3,190.50</b>	<b>2,436.10</b>
<b>- Nett Item Discount on N Items 20.00/20.00% (S\$)</b>	566.10	415.22
<b>Total Parts (S\$)</b>	<b>2,624.40</b>	<b>2,020.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	COMPLETE WAXING OF VEHICLE	New	71.00	0.00
2	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	New	55.00	55.00
3	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	100.00	0.00
4	REPLACE REAR BUMPER, TOW HOOK COVER, ENERGY ABSORBER REAR UPPER PANEL ETC. REPAIR PANEL	New	840.00	780.00
5	RESPRAY REAR BUMPER IN 2 COLORS, REAR UPPER PANEL	New	1,000.00	600.00
6	QC, RETUNE & CONSULT CHECK (NPA)	New	0.00	0.00
7	COMPLIMENTARY WASH & VACUUM (NPA)	New	0.00	0.00
8	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	120.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,186.00</b>	<b>1,435.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >