

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002993/FYF3E2

Date: 05/05/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00000481900

Claimant Vehicle
No : SG1017JInsured Vehicle
No : SMJ8368E

Date of Loss: 07/02/2020

Nature of Claim: TP

Claim
No: SNM20D200709C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SG1017J**Make & Model: MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO
ABS (A)

Engine No: 902926C1105589

Reg. Date: 08/06/2016 (Man. Year: 2015)

Chassis No: WEB62808323130482

Colour: Green

Odometer: 277282 km

Engine Capacity: 6374 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6/6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,119.63	6,861.53	258.10	3.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.80	3,000.00	1,000.80	25.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,120.43	9,861.53	1,258.90	11.32
+ GST 7.00/7.00% (S\$)	778.43	690.31	88.12	11.32
Nett Amount (S\$)	11,898.86	10,551.84	1,347.02	11.32

INSPECTION

Date of Assignment: 21/02/2020

Date Inspected: 24/02/2020

Inspected At:

Go-ahead Singapore (HQ)

2 LOYANG WAY

Singapore 508776

Estimated Period of Repair: 5.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 May 2020)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 L AT TURBO ABS (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG1017J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRACKET	Bent	30.00 FS	*30.00 FS
2	1		*SUPPORT	Dented	1,731.67 FS	*1,731.67 FS
3	1		*FLAP WITH MERCEDES STAR	Cracked	1,270.67 FS	*1,270.67 FS
4	1		*MERCEDES LOGO	Scratched	93.47 FS	*93.47 FS
5	1		*FLAP BRACKET	Damaged	351.05 FS	*351.05 FS
6	1		*FRONT BUMPER	Broken	912.95 FS	*912.95 FS
7	2		*HINGE	Bent	38.42 FS	*38.42 FS
8	1		*FASTENER (2PCS)	Necessary	49.33 FS	*49.33 FS
9	1		*FASTENER BUMPER	Necessary	15.17 FS	*15.17 FS
10	1		*CITARO WORDING	Necessary	160.83 FS	*160.83 FS
11	1		*LOCK (2PCS)	Bent	35.47 FS	*35.47 FS
12	1		*FRONT RHS BUMPER	Cracked	1,005.83 FS	*1,005.83 FS
13	1		*BASE BRACKET	Bent	250.88 FS	*250.88 FS
14	1		*STAND BRACKET	Not Necessary	215.17 FS	*- FS
15	1		*HINGE (2PCS)	Dented	42.93 FS	*42.93 FS
16	1		*LOCK	Bent	53.47 FS	*53.47 FS
17	1		*HEAD LAMP	Broken	690.50 FS	*690.50 FS
18	1		*INDICATOR LAMP	Not Necessary	42.93 FS	*- FS
19	1		*TEST CONNECTION	Bent	39.33 FS	*39.33 FS
20	1		*TEST CONNECTION NUT	Necessary	4.90 FS	*4.90 FS
21	1		*CARPLATE NUMBER SG1017J (WHITE)	Necessary	83.33 FS	*83.33 FS
22	1		*GO-AHEAD FRONT STICKER	Necessary	1.33 FS	*1.33 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **7,119.63** **6,861.53**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOTAL COST OF LABOUR + SPRAY PAINTING	New	4,000.80	3,000.00
		Gross Labour Cost (S\$)	4,000.80	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >