

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20002994/KBA3Q2

**Date:** 26/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

### Claimant

**Vehicle No :** SHD5002X

**Insured Vehicle No :** GZ9890T

**Date of Loss:** 16/02/2020

**Nature of Claim:** TP

**Claim No:** 7254572125SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** SHD5002X

**Make & Model:** RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)

**Engine No:** M9R8839C003253

**Reg. Date:** 10/07/2017 (Man. Year: 2016)

**Chassis No:** VF1ABL15AUC283470

**Colour:** Metallic White/Red

**Odometer:** 327405 km

**Engine Capacity:** 1995 cc

**Market Value/New Car**

**Price:** N/A

**Sum Insured (S\$):** Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable):

Yes

**Footbrake (Serviceable):**

Yes

**Handbrake (Serviceable):**

Yes

**Engine Modification:**

No

**Pre-accident Condition:**

### CONDITION OF TYRES

**Front Tyre Size:** 215/60 R16

**Rear Tyre Size:**

215/60 R16

**Front Left Side:** Sailun 7 mm

**Rear Left Side:**

Giti 6 mm

**Front Right Side:** Sailun 7 mm

**Rear Right Side:**

Giti 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,488.32	1,934.26	5,554.06	74.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,170.00	490.00	13,680.00	96.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>21,658.32</b>	<b>2,424.26</b>	<b>19,234.06</b>	<b>88.81</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,516.08</b>	<b>169.70</b>	<b>1,346.38</b>	<b>88.81</b>
<b>Nett Amount (S\$)</b>	<b>23,174.40</b>	<b>2,593.96</b>	<b>20,580.44</b>	<b>88.81</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$101.27/day) (S\$)</b>		202.54		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>2,903.99</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,800.00</b>		

### INSPECTION

**Date of Assignment:** 20/02/2020

**Date Inspected:** 20/02/2020 **Inspected At:**

Trans-cab Auto Services Pte Ltd  
No 2 Ang Mo Kio Street 63  
Singapore 569111

**Estimated Period of Repair:** 2.0 days

---

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled/Dented	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented/Cut	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
7	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
8	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
9	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
10	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
11	1		*BUMPER BEAM BRACKET RH REAR	Repair	100.90 FL	*- FL
12	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
14	1		*TAILLAMP RH	Serviceable	313.10 FL	*- FL
15	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
16	1		*BOOT REAR	Repair	1,677.20 FL	*- FL
17	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
18	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
19	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
20	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
21	1		*BOOT BADGE RENAULT	Not Necessary	82.40 FL	*- FL
22	1		*BOOT BADGE	Not Necessary	95.80 FL	*- FL
23	1		*EXHAUST CAP REAR	Serviceable	125.40 FL	*- FL
24	1		*SET PARKING AID	Shorted	700.00 FS	*400.00 FS
25	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
26	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
27	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
28	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
29	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
30	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
31	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
32	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
33	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
34	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS
35	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
36	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
37	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
38	1		*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,193.56</b>	<b>2,086.40</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	705.24	152.14
<b>Total Parts (\$\$)</b>	<b>7,488.32</b>	<b>1,934.26</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
2	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
5	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
6	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	6,000.00	200.00
9	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
11	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	220.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
<b>Gross Labour Cost (\$\$)</b>			<b>14,170.00</b>	<b>490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >