

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 7237A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,250.60	-
10	REAR BUMPER CLIPS @\$3.50	NOT NECESSARY	35.00	-
1	REAR BUMPER CHROME GARNISH	SCRATCHED	108.30	108.30
2	REAR BUMPER REFLECTOR LH/RH @\$55.00	NOT NECESSARY	110.00	-
1	END PANEL	TO REPAIR SEE LABOUR	560.80	-
1	END PANEL TOP GARNISH	NOT NECESSARY	155.50	-
1	TAILGATE	BUCKLED	1,293.00	1,220.00
1	TAILGATE 'LOGO' EMBLEM	NECESSARY	38.00	38.00
1	TAILGATE 'SHUTTLE' EMBLEM	NECESSARY	55.00	55.00
2	INNER TAILLAMP LH /RH @\$520.00	SERVICEABLE	1,040.00	-
1	TAILHATE CHROME GARNISH	SCRATCHED	83.10	83.10
2	REAR NUMBER PLATE LAMP @\$35.20	NOT NECESSARY	70.40	-
1	TAILGATE LOCK	JAMMED	187.50	157.00
1	TAILGATE LOCK STRICKER	NOT NECESSARY	34.70	-
	LESS 20% DISCOUNT		-1,004.38	-332.28
			4,017.52	1,329.12
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE WITH COVER (SN)	SCRATCHED	50.00	50.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	118.50	118.50
			168.50	168.50
	LABOUR			
	TO PANEL BEAT ON NECESSARY DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPR AND END PANEL .		780.00	550.00
	TO SAND DOWN ,PUTTY AND SPRAY PAINT ON NECESSARY DAMAGED PARTS.		580.00	550.00
	TO CHECK WIRING.		50.00	50.00
	TO REMOVE & REFIT REAR WINDSCREEN TO FACILITATE REPAIR.		120.00	120.00
			1,530.00	1,270.00

Report Ref No. CC4/FCI20002997/Fda3q2



Page No.:2 of 2

GRAND TOTAL	5,716.02	2,767.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		2,200.00

Report Ref No. CC4/FCI20002997/Fda3q2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor