

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20002998/UBA3Q2
Date: 14/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	HJA3132	Insured Vehicle No :	SLW5497D
Date of Loss:	19/02/2020	Nature of Claim:	TP
		Claim No:	9146748984SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	HJA3132	Engine No:	1TR7605235
Make & Model:	TOYOTA INNOVA, 2.0 (A)	Chassis No:	PN111NV4008412781
Reg. Date:	27/12/2013 (Man. Year: 2013)	Odometer:	444949 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Dayton 6 mm	Rear Left Side:	Dayton 6 mm
Front Right Side:	Dayton 6 mm	Rear Right Side:	Dayton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,006.50	2,916.15	9,090.35	75.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	1,170.00	1,890.00	61.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,066.50	4,086.15	10,980.35	72.88
Approved Total (Overridden) (S\$)		3,250.00		

(S\$)	15,066.50	3,250.00	11,816.50	78.43
+ GST 7.00/7.00% (S\$)	1,054.66	227.50	827.16	78.43
Nett Amount (S\$)	16,121.16	3,477.50	12,643.66	78.43
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
(S\$)		3,977.50		
Liabe Amount (50.00%) (S\$)		1,988.75		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		2,110.75		
Global Sum Settlement (S\$)		2,100.00		

INSPECTION

Date of Assignment: 21/02/2020

Date Inspected: 21/02/2020

Inspected At:

Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CUT)	Not Consistent With The Impact	922.10 F	*- FL
2	1		*FRONT BUMPER SIDE RETAINER N/S	Not Necessary	66.50 F	*- FL
3	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 F	*- FL
4	1		*HEADLAMP N/S (SCRATCHED)	Not Consistent With The Impact	788.10 F	*- FL
5	1		*FRONT FENDER N/S	Not Necessary	615.00 F	*- FL
6	1		*FRONT DOOR N/S	Repair	1,450.00 F	*- FL
7	1		*FRONT DOOR INNER RUBBER N/S	Not Necessary	288.00 F	*- FL
8	1		*FRONT DOOR INNER LOCK N/S	Not Necessary	399.00 F	*- FL
9	2		*FRONT DOOR HINGES	Not Necessary	210.00 F	*- FL
10	1		*REAR DOOR N/S	Dented / Bent	1,350.00 F	*1,350.00 FL
11	1		*REAR DOOR INNER RUBBER N/S	Not Necessary	295.00 F	*- FL
12	1		*REAR DOOR INNER LOCK N/S	Not Necessary	395.00 F	*- FL
13	2		*REAR DOOR HINGES	Not Necessary	210.00 F	*- FL
14	1		*REAR DOOR INNER TRIM BOARD	Deformed / Torn	688.10 F	*688.10 FL
15	1		*REAR DOOR GLASS REGULATOR N/S	Bent	299.10 F	*299.10 FL
16	1		*REAR DOOR GLASS REGULATOR MOTOR N/S	Jammed	450.00 F	*450.00 FL
17	1		*REAR BUMPER	Deformed	971.00 F	*971.00 FL
18	1		*REAR BUMPER SIDE RETAINER N/S	Not Necessary	66.50 F	*- FL
19	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
20	1		*FRONT FOG LAMP N/S	Not Necessary	388.00 F	*- FL
21	1		*CENTRE GRILLE N/S	Repair	645.10 F	*- FL
22	1		*SET FRONT DOOR STICKER N/S	Not Necessary	280.00 FS	*- FS
23	1		*FRONT DOOR VISOR N/S	Not Necessary	100.00 FS	*- FS
24	1		*SET REAR DOOR STICKER N/S	Not Necessary	280.00 FS	*- FS
25	1		*REAR DOOR VISOR N/S	Necessary	100.00 FS	*60.00 FS
26	1		*REAR SPORT RIM N/S	Repair	650.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,006.50	3,868.20
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	952.05
Total Parts (\$)	12,006.50	2,916.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	20.00
2	TO SPRAY RUST PROOFING	New	100.00	30.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
4	TO TRANSFER N/S DOOR MECHANISM	New	180.00	60.00
5	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,080.00	400.00
6	TO PUTTY & SPRAY PAINTING	New	1,500.00	600.00
Gross Labour Cost (\$\$)			3,060.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >