Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20003027/ABA3Q2

Date: 09/07/2020

**REFERENCE** 

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00000580-02

Claimant

SMF2098U Insured Vehicle No: SDT67E Vehicle No:

Date of Loss: 20/02/2020 TP Nature of Claim: Claim No: 1202000009670

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SMF2098U Reg No:

Make & Model: MERCEDES-BENZ CLA200, 1.6 (R18) (A) Engine No: 27091030377321 Chassis No: Reg. Date: 08/05/2014 (Man. Year: 2014) WDD1173432N084142

Colour: Odometer: 122626 km Black

**Engine Capacity:** 1595 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

**CONDITION OF TYRES** 

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18 Front Left Side: Rear Left Side: Dayton 6 mm Dayton 6 mm Front Right Side: Dayton 6 mm Rear Right Side: Dayton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,950.00	5,840.10	3,109.90	34.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,870.00	890.00	980.00	52.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,820.00	6,730.10	4,089.90	37.80
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	10,820.00	5,300.00	5,520.00	51.02
+ Loss of Use (6.0 x S\$8	30.00/day) (S\$)	480.00		
Net	tt Liability (S\$)	5,780.00		
Global Sum S	ettlement (S\$)	5,700.00		

**INSPECTION** 

21/02/2020 Date of Assignment:

Date Inspected: 21/02/2020 Inspected At: Advance Auto Garage (HQ)

23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE

Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: CHUA ZHEN LI Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### REPAIR DETAILS

Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 23 Mar 2020)

Parts: 143 MERCEDES-BENZ CLA200 1.6 (R18) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMF2098U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,554.00 F	*1,554.00 FL
2	1		*FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1		*FRONT BUMPER SIDE HOLDER	N/S Damaged	170.00 F	*85.00 FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	185.00 F	*-FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	541.00 F	*-FL
6	1		*FRONT BUMPER NOZZLE PUMP	Not Necessary	298.00 F	*-FL
7	1		*FRONT BUMPER NOZZLE PUMP COVER	Missing	88.00 F	*88.00 FL
8	1		*FRONT BUMPER LOWER GRILLE	Deformed	192.00 F	*192.00 FL
9	1		*FRONT BUMPER SIDE GRILLE LH	Deformed	85.00 F	*85.00 FL
10	1		*FRONT BUMPER UNDERCOVER	Torn	329.00 F	*329.00 FL
11	1		*FRONT BUMPER UNDERCOVER CLIPS	Necessary	30.00 F	*30.00 FL
12	2		*FRONT BUMPER SENSOR	Not Necessary	520.00 F	*-FL
13	1		*FRONT GRILLE	Not Necessary	692.00 F	*- FL
14	1		*FRONT GRILLE LOGO	Not Necessary	120.00 F	*- FL
15	1		*FRONT GRILLE CLIPS	Not Necessary	20.00 F	*-FL
16	1		*HEADLAMP LH	Cut	2,813.00 F	*2,813.00 FL
17	1		*FRONT LH FENDER	Buckled	1,030.00 F	*1,030.00 FL
18	1		*FRONT LH FENDER INNER SHIELD	Torn	203.00 F	*203.00 FL
19	1		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	30.00 F	*30.00 FL
F=Fra	anchise	part. L=ListIt	emDisc.			
				Sub Total (S\$)	8,950.00	6,489.00
	- List Item Discount on L Items 0.00/10.00% (S\$)				0.00	648.90
				Total Parts (S\$)	8,950.00	5,840.10

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	750.00	400.00
3	WIRING	New	50.00	30.00
4	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
5	TO REMOVE FRONT BUMPER SENSOR	New	120.00	60.00
		Gross Labour Cost (S\$)	1,870.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >