

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG20003028/EYD3E2**Date:** 21/07/2020**REFERENCE**

Insured/Claimant:	ZOU ZHIYI	Policy No:	1900014440	
Date of Loss:	13/02/2020	Nature of Claim:	OD	Claim No: 0461587053SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH7204L		
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Engine No:	CVK075726
Reg. Date:	30/01/2019 (Man. Year: 2018)	Chassis No:	WAUZZZF44KN006687
Colour:	Grey	Odometer:	16017 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$128,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,965.88	12,861.84	11,104.04	46.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,672.00	4,972.00	6,700.00	57.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	35,637.88	17,833.84	17,804.04	49.96
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	34,837.88	17,033.84	17,804.04	51.11
+ GST 7.00/7.00% (\$\$)	2,438.65	1,192.37	1,246.28	51.11
Nett Amount (\$\$)	37,276.53	18,226.21	19,050.32	51.11

INSPECTION

Date of Assignment:	24/02/2020	
Date Inspected:	21/02/2020	Inspected At: 281 Alexandra Road
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	7.0 days	

Adjuster: CHEN TSUE YEE**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	2,068.00 FS	*1,654.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	553.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Necessary	67.00 FS	*52.96 FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Broken	185.00 FS	*147.60 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	198.00 FS	*158.00 FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	59.00 FS	*- FS
7	1		*RADIATOR GRILLE	Broken	1,254.00 FS	*1,003.20 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	127.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Bent	757.00 FS	*605.20 FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	117.00 FS	*93.60 FS
11	1		*FRONT BUMPER COVER	Cracked	120.00 FS	*96.00 FS
12	1		*FRONT BUMPER GUIDE SECTION - LH	Deformed	34.00 FS	*27.12 FS
13	1		*FRONT BUMPER BRACKET - LH	Not Necessary	214.00 FS	*- FS
14	1		*SIGN CAUTION STICKER	Necessary	13.00 FS	*10.24 FS
15	1		*AIRCON STICKER	Necessary	7.00 FS	*5.36 FS
16	1		*FRONT LOCK CARRIER BRACKET	Cracked	129.00 FS	*103.20 FS
17	2		*FRONT BUMPER SUPPORT - LH / RH	Necessary	54.00 FS	*42.24 FS
18	2		*FRONT SENSOR INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
19	4		*FRONT SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
20	1		*FRONT FAN FARE - LH	Not Necessary	38.00 FS	*- FS
21	1		*FRONT FAN FARE BRACKET - LH	Not Necessary	27.00 FS	*- FS
22	1		*FRONT FENDER - LH	Dented	722.00 FS	*577.60 FS
23	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	190.00 FS	*- FS
24	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	47.00 FS	*- FS
25	1		*FRONT FENDER BRACKET - LH	Necessary	33.00 FS	*26.24 FS
26	1		*FRONT FENDER BRACKET DEFORMATION - LH	Necessary	46.00 FS	*36.80 FS
27	1		*FRONT FENDER REAR BRACKET - LH	Not Necessary	30.00 FS	*- FS
28	1		*FRONT FENDER BRACE - LH	Not Necessary	112.00 FS	*- FS
29	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	226.00 FS	*- FS
30	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PART - LH	Not Necessary	219.00 FS	*- FS
31	1		*FRONT WHEEL SPOILER - LH	Cracked	69.00 FS	*55.04 FS
32	1		*FRONT SPOILER - LH	Not Necessary	33.00 FS	*- FS
33	1		*FRONT STONE CHIP GUARD - LH	Not Necessary	48.00 FS	*- FS
34	1		*BONNET	Dented	2,634.00 FS	*2,107.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*BONNET ATTACHMENT PARTS	Not Necessary	388.00 FS	*- FS
36	2		*BONNET LID HINGE - LH / RH	Not Necessary	574.00 FS	*- FS
37	1		*IMPACT PROTECTION - CENTER	Necessary	26.00 FS	*20.56 FS
38	1		*IMPACT PROTECTION - LH	Necessary	26.00 FS	*20.80 FS
39	1		*IMPACT PROTECTION - RH	Necessary	26.00 FS	*20.56 FS
40	1		*FRONT FENDER PROTECTION FILM - LH	Necessary	21.00 FS	*16.72 FS
41	2		*BONNET GAS FILLED STRUT	Not Necessary	224.00 FS	*- FS
42	1		*BONNET STRIKER - LH	Not Necessary	47.00 FS	*- FS
43	1		*BONNET LID LOCK CABLE	Not Necessary	202.00 FS	*- FS
44	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	54.00 FS	*- FS
45	2		*BONNET STRIKER - LH / RH	Not Necessary	94.00 FS	*- FS
46	2		*BONNET LID LOCK	Not Necessary	403.00 FS	*- FS
47	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	54.00 FS	*- FS
48	1		*BONNET BOWDEN CABLE COVER	Not Necessary	9.00 FS	*- FS
49	1		*BONNET RELEASE CABLE	Not Necessary	54.00 FS	*- FS
50	1		*BONNET RELEASE LEVER	Not Necessary	13.00 FS	*- FS
51	1		*LED HEADLIGHT - LH	Cut	7,321.00 FS	*5,856.80 FS
52	1		*LED HEADLIGHT LIFT CYLINDER - LH	Not Necessary	198.00 FS	*- FS
53	1		*LIFT CYLINDER BRACKET - LH	Not Necessary	6.00 FS	*- FS
54	1		*CORRUGATED PIPE	Not Necessary	88.00 FS	*- FS
55	1		*LOCK CARRIER MOUNTING	Not Necessary	956.00 FS	*- FS
56	1		*A/C CONDENSER WITH DRYER	Not Necessary	586.00 FS	*- FS
57	1		*REFRIGERANT LINE FOR A/C	Not Necessary	157.00 FS	*- FS
58	1		*REFRIGERANT LINE FOR DISCHARGE	Not Necessary	320.00 FS	*- FS
59	1		*CHARGE AIR COOLER	Not Necessary	552.00 FS	*- FS
60	1		*CHARGE AIR COOLER PRESSURE PIPE - LH	Not Necessary	402.00 FS	*- FS
61	4		*COOLANT FOR RADIATOR	Not Necessary	169.00 FS	*- FS
62	1		*RADIATOR AIR GUIDE - LH	Cracked	27.00 FS	*21.04 FS
63	1		*RADIATOR INNER AIR DUCT - LH	Cracked	12.00 FS	*8.88 FS
64	1		*RADIATOR AIR GUIDE - LH INNER	Not Necessary	15.00 FS	*- FS
65	1		*RADIATOR AIR GUIDE - LH LOWER	Not Necessary	21.00 FS	*- FS
66	1		*FRONT NO PLATE	Dented	40.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
67	1		*SUNDRIES	Necessary	400.00 FS	*17.60 FS
68	1		*FRONT FENDER TOP COVER LEDGE UPPER LHS	Cracked	23.20 FS	*23.20 FS
69	1		*EXTERNAL TEMPERATURE SENSOR BRACKET	Necessary	13.68 FS	*13.68 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					23,965.88	12,861.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	0.00
3	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	350.00	350.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,250.00	1,750.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, HINGES AND LHS FRONT DOOR	New	4,200.00	2,200.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			11,672.00	4,972.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >