

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20003034/DSF3E2

Date: 16/07/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80467466QMX

Claimant Vehicle No : SHA2135G

Insured Vehicle No : SLX9783X

Date of Loss: 17/02/2020

Nature of Claim: TP

Claim No: 620139

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA2135G

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDGU690493

Reg. Date: 24/11/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMHU096560

Colour: Blue

Odometer: 332845 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: DURATURN 5 mm

Rear Left Side: DURATURN 5 mm

Front Right Side: DURATURN 5 mm

Rear Right Side: DURATURN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,391.16	4,099.40	9,291.76	69.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	1,580.00	3,120.00	66.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,091.16	5,679.40	12,411.76	68.61
Approved Total (Overridden) (\$\$)		4,500.00		
(\$\$)	18,091.16	4,500.00	13,591.16	75.13
+ GST 7.00/7.00% (\$\$)	1,266.38	315.00	951.38	75.13
Nett Amount (\$\$)	19,357.54	4,815.00	14,542.54	75.13

INSPECTION

Date of Assignment: 24/02/2020

Date Inspected: 25/02/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jul 2020)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA2135G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent / Mtg Broken	1,106.00 FL	*553.00 FL
2	1		*REAR BUMPER CLIP	Necessary	19.00 FL	*19.00 FL
3	1		*REAR BUMPER REFLECTOR LAMP (I40)	Not Necessary	32.00 FL	*- FL
4	1		*TAIL LAMP (RH)	Cut	697.80 FL	*697.80 FL
5	1		*TAIL LAMP QUARTER PANEL (RH)	Not Necessary	453.00 FL	*- FL
6	1		*REAR PANEL	Not Necessary	526.70 FL	*- FL
7	1		*ROCKER PANEL OUTER GARNISH	Not Necessary	403.00 FL	*- FL
8	1		*REAR FENDER	Dented	3,789.44 FS	*1,010.00 FS
9	1		*REAR FENDER AIR-DUCT	Not Necessary	51.60 FL	*- FL
10	1		*REAR FENDER MUDFLAP (RH)	Not Necessary	13.50 FL	*- FL
11	1		*REAR WINDSCREEN MOULDING	Necessary	51.80 FL	*51.80 FL
12	1		*REAR DOOR (RH)	Not Necessary	2,201.10 FL	*- FL
13	1		*REAR DOOR RUBBER (RH)	Not Necessary	105.40 FL	*- FL
14	1		*REAR DOOR LOCK ASSY	Not Necessary	268.20 FL	*- FL
15	1		*REAR TYRE (RH)	Not Necessary	216.00 FL	*- FL
16	1		*REAR TYRE RIM (RH)	Not Necessary	650.60 FL	*- FL
17	1		*REAR TYRE WHEEL CAP	Cut	214.20 FL	*107.10 FL
18	1		*REAR WHEEL BEARING ING & HUB	Damaged	724.00 FL	*401.40 FL
19	1		*REAR TRAILING ARM (RH)	Distorted	384.00 FL	*192.00 FL
20	1		*REAR ASSIST (RH)	Distorted	219.40 FL	*145.70 FL
21	1		*REAR SHOCK ABSORBER (RH)	Distorted	552.60 FL	*276.30 FL
22	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	162.60 FL	*- FL
23	1		*REAR CROSS MEMBER	Not Necessary	1,021.50 FL	*- FL
24	1		*STABILIZER BAR	Not Necessary	199.60 FL	*- FL
25	1		*STABILIZER LINK	Not Necessary	85.90 FL	*- FL
26	1		*REAR UPPER ARM (RH)	Distorted	335.75 FL	*335.75 FL
27	1		*REAR LOWER ARM (RH)	Distorted	353.80 FL	*353.80 FL
28	1		*REAR KNUCKLE ARM (RH)	Distorted	545.60 FL	*545.60 FL
29	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Not Necessary	80.00 FS	*- FS
30	1		*REAR DOOR ADVERTISEMENT LOGO (RH)	Not Necessary	100.00 FS	*- FS
31	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
32	1		*REAR FENDER ADVERTISEMENT STICKER (RH)	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 15,710.09 4,835.25
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,318.93 735.85

Total Parts (\$\$) 13,391.16 4,099.40

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,600.00	600.00
2	SPRAY PAINTING CHARGE	New	1,600.00	500.00
3	WIRING CHARGE	New	120.00	30.00
4	TUFF KOTE	New	180.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE / REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE / REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
10	REMOVE / REFIX FUEL TANK	New	80.00	0.00
11	REMOVE / REFIX EXHAUST PIPE	New	80.00	0.00
12	TRANSFER OF DOOR MECHANISM	New	80.00	0.00
13	FRONT / FOUR WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (S\$)			4,700.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >