



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS3/ASM18015651/Bvd3e2-1

C/O : SEAH ONG & PARTNERS LLP
36 ROBINSON ROAD #12-03 CITY HOUSE
SINGAPORE 068877

Date : 02-03-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SLB 8766T	Veh. Inspected	SJA 2718B
Policy No.	GA341526/1	Coverage (\$)	0.00
Claim No.	18.25893 PD-O	Excess (\$)	0.00
Assign From	XIN YI	Assign Date	28/12/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	ZNE100386290	Colour	SILVER
Odometer	347257	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	ROADSTONE	8 mm
L/H Front Tyre	195/65 R15	ROADSTONE	8 mm
R/H Rear Tyre	195/65 R15	ROADSTONE	8 mm
L/H Rear Tyre	195/65 R15	ROADSTONE	8 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	26/08/2018	Inspection Date	26/02/2020
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-----------------------