

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 6987G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NOT NECESSARY	161.10	-
1	TAILGATE (CONSISTENT)	TO REPAIR SEE LABOUR	1,493.10	-
1	TAILGATE REAR LOGO (CONSISTENT)	NECESSARY	68.50	68.50
1	TAILGATE WEATHERSTRIP (CONSISTENT)	TWISTED	366.50	299.10
1	TAILGATE INNER LOCK (CONSISTENT)	NOT NECESSARY	381.10	-
1	REAR BUMPER (CONSISTENT)	DISTORTED	566.50	525.10
1	REAR BUMPER REFLECTOR N/S (CONSISTENT)	BROKEN	85.50	85.50
1	REAR BUMPER BRACKET N/S (CONSISTENT)	BENT	105.00	105.00
1	REAR BUMPER SIDE RETAINER N/S (CONSISTENT)	CRACKED	75.20	65.50
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR END PANEL (CONSISTENT)	BADLY DENTED	899.10	629.10
1	REAR END PANEL TOP GARNISH (CONSISTENT)	TWISTED	341.10	341.10
1	TAILLAMP N/S (CONSISTENT)	CRACKED	488.20	408.20
1	TAILLAMP HOUSING PANEL N/S (CONSISTENT)	DENTED / BENT	605.00	450.50
1	REAR FENDER N/S (CONSISTENT)	BUCKLED	1,299.10	1,299.10
1	REAR FENDER INNER TRIM BOARD N/S (CONSISTENT)	DEFORMED / TORN	681.10	488.10
1	REAR FENDER UNDERSHIELD N/S (CONSISTENT)	NOT NECESSARY	182.50	-
1	REAR AIR VENT N/S (CONSISTENT)	CRACKED	155.20	155.20
1	REAR FENDER GLASS N/S (CONSISTENT)	NOT NECESSARY	680.10	-
1	REAR FLOOR PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,140.20	-
1	REAR FLOOR SIDE MEMBER N/S (CONSISTENT)	TO REPAIR SEE LABOUR	545.10	-
1	REAR FLOOR SIDE INNER BRACKET N/S (CONSISTENT)	BENT	142.80	142.80
	LESS 50% DISCOUNT		-	-2,556.40
			10,512.00	2,556.40
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	280.00	200.00

Report Ref No. CC4/ASM20003061/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET REAR FLOOR PANEL INSULATOR (SN) (CONSISTENT)	NECESSARY	200.00	150.00
1	REAR FENDER GLASS SEALANT N/S (SN) (CONSISTENT)	NECESSARY	50.00	40.00
			630.00	440.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO TRANSFER TAILGATE MECHANISM .	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .		120.00	80.00
	TO DISMANTLE & REFIX REAR FENDER GLASS N/S .		150.00	100.00
	TO SPRAY RUST PROOFING.		120.00	60.00
	TO DISMANTLE & REFIX PETROL TANK .		100.00	60.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE,REAR FLOOR PANEL AND REAR FLOOR SIDE MEMBER N/S .		1,800.00	1,200.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,000.00
			4,880.00	2,580.00
	GRAND TOTAL		16,022.00	5,576.40

RECOMMENDED COST OF LUMP SUM REPAIRS		5,550.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM20003061/Upa3q2

CHUA KANG SENG

Licensed Appraiser