Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003066/FES3N2

Date: 20/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100487205

Claimant
Vehicle No: SKU1163R

Insured Vehicle No: SLH1299P

Date of Loss: 20/02/2020 Nature of Claim: TP Claim No: 1519838616SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKU1163R

Make & Model: TOYOTA ALPHARD, 2.5 CVT ELEGANCE S/R (A) Engine No: 2ARH518382

Reg. Date: 30/06/2015 (Man. Year: 2015) Chassis No: JTNGF3DH808000226

Colour: White Odometer: 216681 km

Engine Capacity: 2494 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
Front Left Side: Goodyear 7 mm Rear Left Side: Goodyear 7 mm
Front Right Side: Goodyear 7 mm
Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,594.02	3,851.25	6,742.77	63.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	940.00	1,240.00	56.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,774.02	4,791.25	7,982.77	62.49
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	12,774.02	3,800.00	8,974.02	70.25
+ GST 7.00/7.00% (S\$)	894.18	266.00	628.18	70.25
Nett Amount (S\$)	13,668.20	4,066.00	9,602.20	70.25
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
Ne	4,366.00			

INSPECTION

Date of Assignment: 21/02/2020

Date Inspected: 21/02/2020 Inspected At: Automobile Integrated Management

Pte Ltd (HQ)

23 Kaki Bukit Ave 4 #04-01, Kaki Bukit

(South Wing) Singapore 415933

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: PARASURAM SHANMUGAM Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Cracked	1,806.45 FL	*1,580.00 FL	
2	1		*FRONT BUMPER FOG LAMP -RH	Not Necessary	395.45 FL	*- FL	
3	1		*FRONT BUMPER FOG LAMP COVER -RH	Not Necessary	148.35 FL	*- FL	
4	1		*FRONT BUMPER PDC SENSOR -RH	Not Necessary	391.65 FL	*- FL	
5	2		*FRONT BUMPER SIDE RETAINERS -L/R	Not Necessary	168.90 FL	*- FL	
6	1		*FRONT FENDER -RH	Not Necessary	1,082.60 FL	*- FL	
7	1		*FRONT HEADLAMP -RH	Scratched	3,682.50 FL	*2,022.00 FL	
8	1		*FRONT SHOCK ABSORBER -RH	Not Necessary	581.90 FL	*- FL	
9	1		*FRONT SHOCK ABSORBER TOP MOUNT	Not Necessary	221.50 FL	*- FL	
10	1		*FRONT LOWER ARM	Bent	760.90 FL	*513.00 FL	
11	1		*FRONT LOWER ARM BALL JOINT	Not Necessary	216.20 FL	*- FL	
12	1		*FRONT KNUCKLE ARM	Not Necessary	631.50 FL	*- FL	
13	1		*FRONT WHEEL HUB	Not Necessary	480.60 FL	*- FL	
14	1		*FRONT WHEEL BEARING	Necessary	215.60 FL	*160.00 FL	
15	1		*FRONT ANTI ROLL BAR	Not Necessary	341.60 FL	*- FL	
16	1		*FRONT ANTI ROLL BAR LINK	Not Necessary	186.10 FL	*- FL	
17	1		*WASHER TANK	Not Necessary	286.90 FL	*- FL	
18	1		*FRONT SPORT WHEEL	Scratched	1,200.00 FS	*600.00 FS	
19	1		*FRONT TYRE	Not Necessary	650.00 FS	*- FS	
20	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS	
F=Fra	nchise	part. S=SpcI	Nett. L=ListItemDisc.	e e			
				Sub Total (S\$)	13,493.70	4,920.00	
	- List Item Discount on L Items 25.00/25.00% (S\$)		2,899.68	1,068.75			
				Total Parts (S\$)	10,594.02	3,851.25	
Г	Report was unsubmitted during this print-out.						
Ь	Report was anothering the print out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	50.00				
2	TO REMOVE,REFIX FRONT UNDERCARRIAGE	New	350.00	0.00				
3	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00				
4	TO RESPRAY UNDERCOATING	New	60.00	60.00				
5	TO RESPRAY PAINTING AND ETC	New	800.00	350.00				
6	PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS	New	800.00	400.00				
	Gross Labour Cost (S\$)		2,180.00	940.00				
	Report was unsubmitted duri	ng this print-out.						

< END OF ESTIMATES >