

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20003073/R1VF3E2

Date: 28/01/2021

REFERENCE

Insured/Claimant: ADF WATERPROOF PTE. LTD. Policy No: DMCVSN3079901900

Date of Loss: 11/02/2020

Nature of Claim: OD

Claim No: SNM20D200813/YP44T/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP44T	Engine No:	4P10B81197
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21 (M)	Chassis No:	FEB21EA10438
Reg. Date:	12/11/2015 (Man. Year: 2015)	Odometer:	306436 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	S\$44,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,614.00	31,706.00	6,908.00	17.89
Miscellaneous Items	255.00	255.00	0.00	0.00
Labour	2,137.80	2,358.40	-220.60	-10.32
Paintwork Labour	839.52	853.70	-14.18	-1.69
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,846.32	35,173.10	6,673.22	15.95
Approved Total (Overridden) (S\$)		28,100.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	41,846.32	27,600.00	14,246.32	34.04
+ GST 7.00/7.00% (S\$)	2,929.24	1,932.00	997.24	34.04
Nett Amount (S\$)	44,775.56	29,532.00	15,243.56	34.04

INSPECTION

Date of Assignment:	24/02/2020	Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	24/02/2020	Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	20.0 days		

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Jan 2021)	
Parts:	N/A	mitsubishi canter 3.0 d feb21 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP44T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL SPARE PART		38,614.00 F	*24,150.00 F
2	1		*R/F WHEELARCH PANEL	Bent	-	*150.00 F
3	1		*R/F OUT WHEEL BRG	Necessary	-	*40.00 F
4	1		*DRAG LINK	Bent	-	*300.00 F
5	1		*STEERING WHEEL TRIM	Deformed	-	*190.00 F
6	1		*CLUTCH MASTER CYL	Distorted	-	*105.00 F
7	1		*R/F BUMPER INN BRKT	Necessary	-	*60.00 F
8	1		*STEERING COUPLING	Bent	-	*95.00 F
9	1		*FUSE BOX ASSY	Cracked	-	*2,000.00 F
10	1		*L/F TYRE (\$180.00) (70%)	Cut	-	*126.00 FS
11	1		*R/F TYRE	Punctured	-	*180.00 FS
12	1		*REAR BUMPER STEP	Broken	-	*400.00 FS
13	3		*RR DECK WOODEN BEAM	Cracked	-	*1,350.00 FS
14	2		*RR CANOPY RUN CHANNL	Cracked	-	*760.00 FS
15	1		*RR DECK FLOOR PANEL	Bent	-	*1,300.00 FS
16	1		*LIFT UP RR DECK	Bent	-	*500.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	38,614.00	31,706.00
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	TOTAL SPECIAL NETT ITEM	255.00	255.00
Sub Total (S\$)			255.00	255.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINTWORK LABOUR	New	839.52	853.70
<u>Labour Items</u>				
2	TOTAL OF LABOUR	New	2,137.80	2,108.40
3	REFILL AIRCON GAS	New	-	50.00
4	TO DO DIAGNOSE & RESET FAULT	New	-	200.00
Gross Labour Cost (S\$)			2,977.32	3,212.10

Report was unsubmitted during this print-out.

< END OF ESTIMATES >