

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003074/KES3Q2

Date: 16/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900117187

Claimant
Vehicle No : SGU6403M **Insured Vehicle No :** SMM6906A

Date of Loss: 20/02/2020 Nature of Claim: TP Claim No: 1855809400SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGU6403M		
Make & Model:	MERCEDES-BENZ E200, 1.8 NGT (A)	Engine No:	27194130777402
Reg. Date:	20/07/2006 (Man. Year: 2006)	Chassis No:	WDB2110422A980640
Colour:	Metallic Silver	Odometer:	24636 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Firenza 8 mm	Rear Left Side:	Firenza 8 mm
Front Right Side:	Firenza 8 mm	Rear Right Side:	Firenza 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,816.10	15,462.50	1,353.60	8.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,090.00	4,720.00	370.00	7.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,906.10	20,182.50	1,723.60	7.87
Approved Total (Overridden) (\$\$)		16,100.00		
(\$\$)	21,906.10	16,100.00	5,806.10	26.50
+ GST 7.00/7.00% (\$\$)	1,533.43	1,127.00	406.43	26.50
Nett Amount (\$\$)	23,439.53	17,227.00	6,212.53	26.50
+ Car Rental (16.0 x S\$100.00/day) (\$\$)		1,600.00		
+ Doc/Search Fee (\$\$)		8.00		
Nett Liability (\$\$)		18,835.00		

INSPECTION

Date of Assignment: 21/02/2020

Date Inspected: 21/02/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 18.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent /Cracked	1,372.00 FN	*1,372.00 FN
2	1		*REAR BUMPER REINFORCEMENT	Bent	630.00 FN	*630.00 FN
3	1		*REAR BUMPER CENTRE MOULDING	Necessary	198.00 FN	*198.00 FN
4	2		*REAR BUMPER SIDE MOULDINGS	Necessary	280.00 FN	*280.00 FN
5	1		*REAR BUMPER CENTRE INNER GARNISH	Cracked	245.00 FN	*245.00 FN
6	2		*TAILLAMPS	O/S Cracked / N/S Broken	920.00 FN	*920.00 FN
7	1		*REAR CENTRE PANEL	Bent	795.00 FN	*795.00 FN
8	1		*REAR CENTRE PANEL INNER TOP GARNISH	Distorted	155.00 FN	*155.00 FN
9	1		*REAR LH FENDER	Buckled	2,477.00 FN	*2,477.00 FN
10	1		*REAR LH FENDER AIR SCROP GRILLE	Serviceable	47.00 FN	*- FN
11	2		*REAR FENDER INNER RAIL GARNISHES	Cracked	70.00 FN	*70.00 FN
12	6		*REAR FENDER INNER RAIL GARNISH CLIPS	Necessary	54.00 FN	*54.00 FN
13	1		*FRONT BUMPER	Cracked	1,283.00 FN	*1,283.00 FN
14	1		*FRONT BUMPER RH PROTECTOR	Dented	285.00 FN	*285.00 FN
15	1		*FRONT RH FENDER	Bent	786.00 FN	*786.00 FN
16	1		*FRONT RH FENDER PROTECTOR	Necessary	82.00 FN	*82.00 FN
17	1		*FRONT RH FENDER EMBLEM (ELEGANCE)	Necessary	68.00 FN	*68.00 FN
18	1		*FRONT RH DOOR PROTECTOR	Serviceable	290.00 FN	*- FN
19	1		*REAR RH DOOR PROTECTOR	Serviceable	220.00 FN	*- FN
20	1		*RH HEADLAMP	Mtg Cracked	965.00 FN	*965.00 FN
21	1		*RH HEADLAMP BRACKET	Repair	146.00 FN	*- FN
22	2		*FRONT SEAT HEADREST	Serviceable	444.00 FN	*- FN
23	1		*REAR WINDSCREEN GLASS MOULDING	Mldg Necessary	1,315.00 FN	*1,315.00 FN
24	1		*REAR BOOT	Buckled	2,410.00 FN	*2,410.00 FN
25	1		*REAR BOOT INNER RUBBER (50%)	Deformed	226.80 FS	*126.00 FS
26	1		*REAR BOOT LOGO	Necessary	52.00 FN	*52.00 FN
27	1		*REAR BOOT EMBLEM (E200)	Necessary	84.00 FN	*84.00 FN
28	1		*REAR BOOT NUMBER PLATE GARNISH	Cracked	620.00 FN	*620.00 FN
29	1		*REAR BOOT THIRD BRAKE LIGHT	Cracked	310.00 FN	*310.00 FN
30	1		*REAR BOOT INNER LOCK	Dented	322.00 FN	*322.00 FN
31	1		*REAR BOOT LH HINGE	Bent	152.00 FN	*152.00 FN
32	1		*REAR SPARE TYRE COMPARTMENT TRAY	Deformed	755.00 FN	*755.00 FN
33	1		*REAR TOOL BOX	Serviceable	245.00 FN	*- FN
34	1		*SET REVERSE SENSOR	Dented	280.00 FS	*280.00 FS
35	1		*ROLL REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$) 18,623.80 17,131.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$) 1,807.70 1,668.50

Total Parts (\$\$) 16,816.10 15,462.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	50.00	50.00
2	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
3	REMOVE & REFIX FRT & REAR BUMPER ASSY ,HEADLAMP & TAILLAMPS ,REAR BOOT ,THIRD BRAKE LIGHT ,FRT RH FENDER ,CUT ,WELD & RENEW REAR PANEL ,REAR LH FENDER ,LH TAILLAMP PANEL ,KNOCK & REPAIR RH HEADLAMP PANEL & SPARE TYRE COMPARTMENT & REALIGN THE SAME	New	1,900.00	1,700.00
4	REMOVE & REFIX SEAT ,CARPET ,TOP ROOF LINING ,ETC	New	120.00	120.00
5	REMOVE & REFIX C& G GAS TANK & RESET SYSTEM	New	350.00	280.00
6	PUTTY & RESPRAY ON REAR & FRT BUMPER ,REAR LH FENDER ,REAR BOOT ,REAR COMPARTMENT ,REAR PANEL ,FRT & REAR RH DOOR ,FRT RH FENDER & ALL AFFECTED AREAS	New	2,100.00	2,000.00
7	TO MOUNT ON CAR-O-LINER TO REALIGN CHASSIS	New	250.00	250.00
8	REMOVE & REFIX FRT SEAT HEADRESTS & RESET SYSTEM	New	120.00	120.00
9	RUSTPROOFING	New	80.00	80.00
Gross Labour Cost (S\$)			5,090.00	4,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >