

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20003075/R1QF3E2

Date: 12/10/2020

REFERENCE

Insured/Claimant: DOUBLE-TRANS PTE LTD	Policy No: DMCVSNA00005742000	
Date of Loss: 09/02/2020	Nature of Claim: OD	Claim No: SNM20D200929/GBH6672E/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH6672E		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEA01BR1SDEB (M)	Engine No:	4P10D28181
Reg. Date:	20/08/2018 (Man. Year: 2018)	Chassis No:	FEA01BA25064
Colour:	White	Odometer:	47577 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R14C	Rear Tyre Size:	185/75 R15 (D)
Front Left Side:	Triangle 7 mm	Rear Left Side:	Triangle 7/7 mm
Front Right Side:	Triangle 7 mm	Rear Right Side:	Triangle 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,797.00	25,564.00	8,233.00	24.36
Miscellaneous Items	3,371.00	2,971.00	400.00	11.87
Labour	1,239.00	1,415.40	-176.40	-14.24
Paintwork Labour	786.77	1,852.65	-1,065.88	-135.48
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,193.77	31,803.05	7,390.72	18.86
Approved Total (Overridden) (S\$)		25,400.00		
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	39,193.77	23,900.00	15,293.77	39.02
+ GST 7.00/7.00% (S\$)	2,743.56	1,673.00	1,070.56	39.02
Nett Amount (S\$)	41,937.33	25,573.00	16,364.33	39.02

INSPECTION

Date of Assignment:	24/02/2020 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	25/02/2020 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457

Estimated Period of Repair: 22.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Oct 2020)		
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEA01BR1SDEB (M) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for GBH6672E)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL SPARE PART		33,797.00 F	*25,564.00 F
						F=Franchise part.
Total Parts (S\$)					33,797.00	25,564.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	TOTAL OF EXTRA	3,371.00	2,971.00
Sub Total (\$\$)			3,371.00	2,971.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINTWORK LABOUR	New	786.77	1,852.65
<u>Labour Items</u>				
2	TOTAL OF LABOUR	New	1,239.00	1,415.40
Gross Labour Cost (\$\$)			2,025.77	3,268.05

Report was unsubmitted during this print-out.

< END OF ESTIMATES >