

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Feb 2020 Edit Reg		24 Feb 2020 00:00 Edit Adj Rpt	S\$14,000.00 Edit Estimates	S\$14,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: WU HSIU CHU , Co. Reg. No.: -									
Main Claimant: NG SER MIANG , ID: S0074251A									
Vehicle Reg. No.: SJE2218G		Date of Loss: 20/02/2020 00:00 - :59 [98 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6970938662SG		Policy/Cover Note No.: 1800044446 (Comprehensive)							
Vehicle Reg. No. (Insured): SCX9168D		Policy No. (Claimant):							
		Excess:							
Repairer: King's Auto Spray Paint Pte Ltd (HQ) BLK 160 SIN MING DRIVE #05-10 SIN MING AUTOCARE, 575722 Sin Ming - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/03/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (25/02/2020): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJE2218G (6970938662SG)
 [SCX9168D]
 TP
 NG SER MIANG
 Feb 20 2020 12:00AM
 [WU HSIU CHU]
 King's Auto Spray Paint Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		☐	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	24/03/20 09:13	General View														Load JPG	☒	
2	24/03/20 09:13	General View														Load JPG	☒	
3	24/03/20 09:13	General View														Load JPG	☒	
4	24/03/20 09:13	General View														Load JPG	☒	
5	24/03/20 09:13	General View														Load JPG	☒	
6	24/03/20 09:13	General View														Load JPG	☒	
7	24/03/20 09:13	General View														Load JPG	☒	
8	24/03/20 09:13	General View														Load JPG	☒	
9	24/03/20 09:13	General View														Load JPG	☒	
10	24/03/20 09:13	General View														Load JPG	☒	
11	24/03/20 09:13	General View														Load JPG	☒	
12	24/03/20 09:13	General View														Load JPG	☒	
13	24/03/20 09:13	General View														Load JPG	☒	
14	24/03/20 09:13	General View														Load JPG	☒	
15	24/03/20 09:13	General View														Load JPG	☒	
16	24/03/20 09:13	General View														Load JPG	☒	
17	24/03/20 09:13	General View														Load JPG	☒	
18	24/03/20 09:13	General View														Load JPG	☒	
19	24/03/20 09:13	General View														Load JPG	☒	
20	24/03/20 09:13	General View														Load JPG	☒	
21	24/03/20 09:13	General View														Load JPG	☒	
22	24/03/20 09:13	General View														Load JPG	☒	
23	24/03/20 09:13	General View														Load JPG	☒	
24	24/03/20 09:13	General View														Load JPG	☒	
25	24/03/20 09:13	General View														Load JPG	☒	
26	24/03/20 09:13	General View														Load JPG	☒	
27	24/03/20 09:13	General View														Load JPG	☒	
28	24/03/20 09:13	General View														Load JPG	☒	
29	24/03/20 09:19	Reinspection Photo														Load JPG	☒	
30	24/03/20 09:19	Reinspection Photo														Load JPG	☒	
31	24/03/20 09:19	Reinspection Photo														Load JPG	☒	
32	24/03/20 09:19	Reinspection Photo														Load JPG	☒	
33	24/03/20 09:19	Reinspection Photo														Load JPG	☒	
34	24/03/20 09:19	Reinspection Photo														Load JPG	☒	
35	24/03/20 09:19	Reinspection Photo														Load JPG	☒	
36	24/03/20 09:19	After Repair Photo														Load JPG	☒	
37	24/03/20 09:19	After Repair Photo														Load JPG	☒	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	24/03/20 09:19	After Repair Photo		Load JPG	☒
39	24/03/20 09:19	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/02/20 10:18	TP GIA REPORT AND POLICE REPORT		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	25/02/20 09:57	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20003083/KVD3E2

Date: 02/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800044446
Claimant Vehicle No : SJE2218G **Insured Vehicle No :** SCX9168D
Date of Loss: 20/02/2020 **Nature of Claim:** TP **Claim No:** 6970938662SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJE2218G**
 Make & Model: BMW 730LI, 3.0 AT ABS D/AB 2WD 4DR NAV HID Engine No: 13657919N52B30AF
 SR (A)
 Reg. Date: 13/12/2011 (Man. Year: 2011) Chassis No: WBAKB22070C951299
 Colour: Metallic Grey Odometer: 54934 km
 Engine Capacity: 2996 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/50 R18 Rear Tyre Size: 245/50 R18
 Front Left Side: Hankook 7 mm Rear Left Side: Hankook 7 mm
 Front Right Side: Hankook 7 mm Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,484.18	20,472.75	17,011.43	45.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,600.00	2,050.00	2,550.00	55.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,084.18	22,522.75	19,561.43	46.48
Approved Total (Overridden) (S\$)		14,000.00		
Nett Amount (S\$)	42,084.18	14,000.00	28,084.18	66.73

INSPECTION

Date of Assignment: 24/02/2020
 Date Inspected: 25/02/2020 Inspected At: King's Auto Spray Paint Pte Ltd (HQ)
 BLK 160 SIN MING DRIVE #05-10 SIN
 MING AUTOCARE
 Singapore 575722
 Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,765.90 FL	*1,765.90 FL
2	2		*FRONT BUMPER MLDG	Necessary	97.90 FL	*97.90 FL
3	2		*FRONT BUMPER NOZZLE	Serviceable	369.40 FL	*- FL
4	1		*FRONT BUMPER NOZZLE COVER	N/S Missing	104.40 FL	*52.20 FL
5	1		*FRONT BUMPER SENSOR (4PCS)	Scratched / Missing(2Pcs Only)	1,032.00 FL	*476.10 FL
6	1		*FRONT BUMPER TOWING COVER	Serviceable	52.20 FL	*- FL
7	1		*FRONT BUMPER LOWER GRILLE CENTER	Serviceable	179.20 FL	*- FL
8	2		*FRONT BUMPER SPORT LAMP	Serviceable	566.60 FL	*- FL
9	1		*FRONT SPORT LAMP GRILLE SIDE	N/S Missing	79.20 FL	*39.60 FL
10	1		*FRONT BUMPER LOWER CROSSMEMBER INNER	Serviceable	1,939.55 FL	*- FL
11	1		*FRONT CROSSMEMBER SIDE HOSE	Serviceable	76.10 FL	*- FL
12	1		*FRONT CROSSMEMBER INNER GARNISH CENTER	Serviceable	274.55 FL	*- FL
13	1		*FRONT NUMBER PLATE GARNISH	Serviceable	69.60 FL	*- FL
14	2		*FRONT BUMPER GRILLE	Serviceable	364.40 FL	*- FL
15	1		*FRONT REINFORCEMENT	Repair	835.15 FL	*- FL
16	2		*FRONT BUMPER BRACKETS SIDE	Distorted	36.00 FL	*36.00 FL
17	1		*FRONT BUMPER SPONGE INNER	Serviceable	96.40 FL	*- FL
18	2		*FRONT HEAD LAMP	O/S Mtg Cracked / N/S Cut	5,751.80 FL	*5,751.80 FL
19	1		*FRONT FENDER O/S	Bent	1,436.65 FL	*1,436.65 FL
20	1		*FRONT FENDER SPLASH SHIELD	Distorted	352.45 FL	*352.45 FL
21	10		*FRONT SPLASH SHIELD CLIPS	Necessary	50.00 FL	*50.00 FL
22	1		*FRONT SPORT RIM	Dented	966.50 FL	*966.50 FL
23	1		*FRONT STEERING RACK & PINION	Bent / Jammed	6,811.55 FL	*6,811.55 FL
24	1		*FRONT LOWER ARM	Distorted	515.15 FL	*515.15 FL
25	1		*FRONT LOWER ARM	Bent	618.20 FL	*618.20 FL
26	1		*FRONT KNUCKLE ARM	Bent	662.70 FL	*662.70 FL
27	1		*FRONT STAY BAR	Serviceable	487.65 FL	*- FL
28	1		*FRONT SHOCK ABSORBERS	Bent	1,385.65 FL	*1,385.65 FL
29	1		*FRONT WHEEL BEARING	Necessary	484.55 FL	*484.55 FL
30	1		*FRONT UPPER ARM	Serviceable	566.70 FL	*- FL
31	1		*FRONT STAY LINK	Serviceable	115.50 FL	*- FL
32	2		*FRONT HEAD LAMP LOWER BRACKETS	Serviceable	523.30 FL	*- FL
33	1		*FRONT SUPPORT PANEL	Serviceable	417.25 FL	*- FL
34	1		*FRONT FENDER TOP GARNISH	Serviceable	105.60 FL	*- FL
35	1		*FRONT L/H LOWER ARM	Serviceable	515.15 FL	*- FL
36	1		*FRONT L/H LOWER ARM	Serviceable	618.20 FL	*- FL
37	1		*FRONT KNUCKLE ARM	Serviceable	662.70 FL	*- FL
38	1		*FRONT SHOCK ABSORBER	Serviceable	1,385.65 FL	*- FL
39	1		*FRONT UPPER ARM	Serviceable	566.70 FL	*- FL
40	1		*FRONT STAY LINK	Serviceable	115.50 FL	*- FL
41	1		*FRONT WHEEL BEARING	Serviceable	484.55 FL	*- FL
42	1		*REAR SHOCK ABSORBER	Serviceable	3,266.20 FL	*- FL
43	1		*REAR SHOCK ABSORBER PUMP	Serviceable	2,090.55 FL	*- FL
44	1		*FRONT NUMBER PLATE	Dented	50.00 FS	*45.00 FS
45	1		*FRONT BRAKE ROTOR	Serviceable	509.45 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					39,454.40	21,547.90
- List Item Discount on L Items 5.00/5.00% (S\$)					1,970.22	1,075.15
Total Parts (S\$)					37,484.18	20,472.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	150.00	80.00
2	DISMANTLE & REPLACE O/S & L/H FRONT UNDERCARRIAGE }	New	680.00	400.00
3	DISMANTLE & REFIX STEERING RACK & PINION }	New	250.00	0.00
4	CHECK & ALIGN WHEEL ALIGNMENT - COMPUTERISE	New	90.00	60.00
5	CHECK WIRING	New	50.00	30.00
6	TO RESET SENSOR	New	200.00	120.00
7	TO DISMANTLE & REPLACE REAR SHOCK ABSORBER & PUMP	New	380.00	0.00
8	TO RENEW THE ABOVEMENTIONED PARTS KNOCKING, CUTTING, WELDING & STRAIGHTEN DAMAGED PARTS	New	1,600.00	700.00
9	RESPRAY PAINTING	New	1,200.00	660.00
Gross Labour Cost (\$\$)			4,600.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >