

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INV No.

### **TAX INVOICE**

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877

INV Date 14/09/2020

 $Reference \qquad CC4/FCI20003085/Kda3q2$ 

AC2006316

Code FCI2

### **PROFESSIONAL SERVICE FEE**

Vehicle No. SLW 6757Y
Insured Veh. SHC 7597M

Claim No. D20000640MFSH/1

Policy No. D-20094921MFSH

 Accident Date
 24/01/2020

 Inspection Date
 26/02/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
MS F	MS FIRST CAPITAL INSURANCE LTD Ref : CC4/FCl20003085/Kda3q2					
	OBINSON ROAD 11 CITY HOUSES	INGAPORE 068877	Date: 14-09-2020 Code: FCI2			
1.		Policy Particulars	:- THIRD PARTY CLAIM			
	Insured Veh.	SHC 7597M	Veh. Inspected	SLW 6757Y		
	Policy No.	D-20094921MFSH	Coverage (\$)	0.00		
	Claim No.	D20000640MFSH/1	Excess (\$)	0.00		
	Assign From	MERINA CHIA	Assign Date	21/02/2020		
2.		Vehicle Partic	culars & Condition			
	Make & Model	MERCEDES BENZ E220D (A)	c.c	1950		
	Engine No.	HIDDEN	Year of Reg.	2016		
	Chassis No.	WDD2130042A061017	Colour	METALLIC BLACK		
	Odometer	191680	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	GOOD				
3.		Condition	ons of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	225/55 R17	KAPSEN	6 mm		
	L/H Front Tyre	225/55 R17	KAPSEN	6 mm		
	R/H Rear Tyre	225/55 R17	KAPSEN	6 mm		
	L/H Rear Tyre	225/55 R17	KAPSEN	6 mm		
4.		•	on of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE O/S	FRONT PORTION.			
	DAMAGES SEE D	ETAILS.				
5.		General	Information			
	Accident Date	24/01/2020	Inspection Date	26/02/2020		
	Survey held at	LIM TAN MOTOR PTE LTD				
		BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721				
5a.		Re	emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Days			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 6757Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	TO PUTTY & SPRAY PAINT.		700.00	600.00
	LABOUR CHARGES.		350.00	200.00
			1,050.00	800.00
	GRAND TOTAL		1,050.00	800.00

RECOMMENDED COST OF REPAIRS			800.00
-----------------------------	--	--	--------

Report Ref No. CC4/FCI20003085/Kda3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION

# PHOTOGRAPHS FOR VEHICLE NO. SLW 6757Y















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No; 199607198R GST Reg. No; 19-9607198-R



