

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20003088/AES3Q2

Date: 14/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700037047

Claimant
Vehicle No : YP6793A **Insured Vehicle No :** SBH1266C

Date of Loss: 20/02/2020 Nature of Claim: TP Claim No: 7620058964SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP6793A		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Engine No:	4P10B99823
Reg. Date:	14/06/2017 (Man. Year: 2016)	Chassis No:	FEB21EA21340
Colour:	White	Odometer:	132766 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85R15	Rear Tyre Size:	195/85R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Kenda 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Kenda 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,054.83	10,409.05	4,645.78	30.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,830.00	3,340.00	1,490.00	30.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,884.83	13,749.05	6,135.78	30.86
Approved Total (Overridden) (S\$)		11,000.00		
Nett Amount (S\$)	19,884.83	11,000.00	8,884.83	44.68
+ Loss of Use (9.0 x S\$150.00/day) (S\$)		1,350.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		12,357.45		

INSPECTION

Date of Assignment: 21/02/2020

Date Inspected: 21/02/2020 Inspected At:

Hua Meng Spray Painting Workshop
(HQ)
No 1 Kaki Bukit Avenue 6, #01-61
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Dented	1,234.20 FL	*1,234.20 FL
2	1		*FRONT WIPER PANEL GARNISH	Cracked	600.00 FS	*500.00 FS
3	1		*FRONT PANEL FUSO EMBLEM	Necessary	161.70 FL	*161.70 FL
4	1		*FRONT GRILLE	Cracked	1,093.73 FS	*950.00 FS
5	1		*FRONT GRILLE MITSUBISHI EMBLEM	Necessary	85.80 FL	*85.80 FL
6	1		*SET FRONT PANEL CLIPS	Necessary	66.00 FL	*30.00 FL
7	1		*FRONT WINDSCREEN RUBBER	Necessary	569.80 FL	*375.60 FL
8	1		*FRONT RH CONNER PANEL	Cracked	650.00 FL	*650.00 FL
9	1		*FRONT RH SIGNAL LAMP	Cracked	297.00 FL	*297.00 FL
10	1		*FRONT RH HEADLAMP	Cracked	558.00 FL	*558.00 FL
11	1		*FRONT RH HEADLAMP SIDE GARNISH	Missing	394.90 FL	*98.00 FL
12	1		*FRONT RH SIDE MIRROR BRACKET	Not Necessary	507.10 FL	*- FL
13	1		*FRONT RH SIDE MIRROR TOP COVER	Damaged	34.10 FL	*34.10 FL
14	1		*FRONT RH SIDE MIRROR TOP GARNISH	Not Necessary	34.10 FL	*- FL
15	1		*FRONT BUMPER	Bent	1,350.00 FS	*1,200.00 FS
16	1		*FRONT BUMPER BRACKET	O/S Bent	409.20 FL	*204.60 FL
17	1		*FRONT BUMPER RH SIDE LAMP	Cracked	256.30 FL	*256.30 FL
18	1		*FRONT BUMPER CENTRE LOWER GRILLE	Not Necessary	95.00 FL	*- FL
19	1		*FRONT RH DOOR PILLAR	Dented	1,628.00 FL	*1,482.00 FL
20	1		*FRONT RH DOOR	Dented	2,200.00 FL	*2,001.40 FL
21	1		*FRONT RH DOOR TOP HINGE	Not Necessary	178.20 FL	*- FL
22	1		*FRONT RH DOOR LOWER HINGE	Bent	178.20 FL	*178.20 FL
23	1		*FRONT RH DOOR STOPPER	Not Necessary	94.60 FL	*- FL
24	1		*FRONT RH DOOR GLASS OUTER TOP SIDE MOULDING	Not Necessary	148.50 FL	*- FL
25	1		*FRONT RH DOOR WEATHER STRIP	Cut	466.40 FL	*466.40 FL
26	1		*FRONT RH DOOR LOWER GARNISH	Cracked	159.50 FL	*159.50 FL
27	1		*FRONT RH DOOR LOWER GARNISH RUBBER	Not Necessary	60.50 FL	*- FL
28	1		*FRONT RH DOOR INNER LOCK	Damaged	763.40 FL	*485.00 FL
29	1		*FRONT RH DOOR INNER BOARD	Cracked	665.50 FL	*586.00 FL
30	1		*FRONT RH DOOR INNER BOARD POWER WINDOW SWITCH	Not Necessary	531.30 FL	*- FL
31	1		*FRONT RH DOOR INNER HANDLE	Deformed	121.00 FL	*121.00 FL
32	1		*FRONT RH DOOR POWER WINDOW MOTOR }	Not Necessary	1,518.00 FL	*- FL
33	1		*FRONT RH DOOR POWER WINDOW REGULATOR }	Not Necessary	0.00 FL	*- FL
34	1		*FRONT RH STEP PANEL	Damaged	750.00 FL	*574.00 FL
35	1		*FRONT RH DOOR INNER LOWER AIR VENT	Cracked	55.00 FL	*55.00 FL
36	1		*FRONT RH DOOR SUN VISOR	Necessary	78.75 FS	*60.00 FS
37	1		*FRONT RH ARCH PANEL	Repair	528.00 FL	*- FL
38	1		*FRONT ARCH PANEL GARNISH	Deformed	171.60 FL	*171.60 FL
39	1		*FRONT RH BODY RUBBER	Not Necessary	338.90 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 19,032.28 12,975.40
- List Item Discount on L Items 25.00/25.00% (S\$) 3,977.45 2,566.35

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					15,054.83	10,409.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	50.00
2	TO SUPPLY FRONT WINDSCREEN SEALANT	New	50.00	50.00
3	REMOVE & REINSTALL AIR CON FILL IN GAS	New	150.00	0.00
4	REMOVE & REINSTALL DESKBOARD	New	400.00	220.00
5	REMOVE & REINSTALL DOOR FITTINGS	New	100.00	100.00
6	REMOVE & REINSTALL FRONT WINDSCREEN	New	150.00	120.00
7	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	2,000.00	1,600.00
8	RESPRAY PAINTING	New	1,600.00	1,000.00
9	TUFF KOTE	New	100.00	100.00
10	TOWING FEE	New	200.00	100.00
Gross Labour Cost (\$)			4,830.00	3,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >