

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

FEB 21

TRADEWIN LOGISTICS PTE LTD
111A JLN KEMBANGAN
S 419150

TP ALG
Ashes.

Date :28.02.2020
Vehicle No :YP 6793 A
Make/Model :MITSUBISHI FUSO
Accident date :20.02.2020

No	DESCRIPTION	Qty	Amount (\$)
<u>List Items</u>			
1	Front panel <i>Dented.</i>	1	\$ 1234.20 ✓
2	Front wiper panel garnish <i>cracked.</i>	1	\$ 800.00 500(SN)
3	Front panel Fuso emblem <i>Neu</i>	1	\$ 161.70 ✓
4	Front grille <i>cracked</i>	1	\$ 1458.30 950(SN)
5	Front grille <i>Mitsubishi</i> emblem <i>Neu</i>	1	\$ 85.80 ✓
6	Front grille clips (1 set) <i>neu</i>	1	\$ 66.00 30
7	Front windscreen rubber <i>neu</i>	1	\$ 569.80 375.60
8	Front RH conner panel <i>cracked</i>	1	\$ 650.00 ✓
9	Front RH signal lamp <i>cracked</i>	1	\$ 297.00 ✓
10	Front RH headlamp <i>cracked</i>	1	\$ 558.00 ✓
11	Front RH headlamp side garnish <i>Missing</i>	1	\$ 394.90 98.
12	Front RH side mirror bracket <i>neu</i>	1	\$ 507.10 ✓
13	Front RH side mirror top cover <i>Dented</i>	1	\$ 34.10 ✓
14	Front RH side mirror top garnish <i>neu</i>	1	\$ 34.10 ✓
15	Front bumper <i>Best.</i>	1	\$ 1800.00 1200(SN)
16	Front bumper bracket @ \$204.60 <i>RH Best</i>	2	\$ 409.20 204.60
17	Front bumper RH side lamp <i>cracked</i>	1	\$ 256.30 ✓
18	Front bumper centre lower grille <i>neu neu</i>	1	\$ 95.00 ✓
19	Front RH door pillar <i>Dented</i>	1	\$ 1628.00 1482
20	Front RH door <i>Dented.</i>	1	\$ 2200.00 2001.40
21	Front RH door top hinge <i>neu neu</i>	1	\$ 178.20 ✓
22	Front RH door lower hinge <i>Best</i>	1	\$ 178.20 ✓
23	Front RH door stopper <i>neu neu</i>	1	\$ 94.60 ✓
24	Front RH door glass outer top side moulding <i>neu neu</i>	1	\$ 148.50 ✓
25	Front RH door weather strip <i>cut</i>	1	\$ 466.40 ✓
26	Front RH door lower garnish <i>cracked</i>	1	\$ 159.50 ✓
27	Front RH door lower garnish rubber <i>neu neu</i>	1	\$ 60.50 ✓
28	Front RH door inner lock <i>Dented</i>	1	\$ 763.40 485
29	Front RH door inner board <i>cracked</i>	1	\$ 665.50 586
30	Front RH door inner board power window switch <i>neu neu</i>	1	\$ 531.30 ✓
31	Front RH door inner handle <i>deformed</i>	1	\$ 121.00 ✓

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TRADEWIN LOGISTICS PTE LTD
111A JLN KEMBANGAN
S 419150

Date : 28.02.2020
Vehicle No : YP 6793 A
Make/Model : MITSUBISHI FUSO
Accident date : 20.02.2020

No	DESCRIPTION	Qty	Amount (\$)
32	Front RH door power window motor <i>all new</i>	1	\$ 1518.00 *
33	Front RH door power window regulator	1	\$ }
34	Front RH step panel <i>Damage</i>	1	\$ 750.00 <i>X: 574</i>
35	Front RH door inner lower air vent <i>cracked</i>	1	\$ 55.00
36	Front RH door sun <i>rise</i> visor <i>new</i>	1	\$ 105.00 <i>60(SN)</i>
37	Front RH arch panel <i>Regis</i>	1	\$ 528.00
38	Front arch panel garnish <i>Debond</i>	1	\$ 171.60 ✓
39	Front RH body rubber <i>all new</i>	1	\$ 338.90 *
			\$ 20073.10
		Less 25% Disc	\$ 5018.28
		Total	\$ 15054.83

Labour Cost

- 1 To check wiring
- 2 To supply front windscreen sealant
- 3 Remove & reinstall air con fill in gas
- 4 Remove & reinstall deskboard
- 5 Remove & reinstall door *glass fittings*.
- 6 Remove & reinstall front windscreen
- 7 Remove, replace & repair consistent to the accident
- 8 Respray painting
- 9 Tuff kote

10 Towing fee.

200
100

\$ 80.00	30
\$ 50.00	✓
\$ 150.00	✓
\$ 400.00	220
\$ 100.00	✓
\$ 150.00	120
\$ 2000.00	1600
\$ 1600.00	1000
\$ 100.00	✓
Total	\$ 4630.00
Grand Total	\$ 19684.83

total. 13749.05

1/s 11K.

09 Days

11K

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: