

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003092/GDA3Q2

Date: 07/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900023135

Claimant
Vehicle No : SMH8518A **Insured Vehicle No :** FBJ9402M

Date of Loss: 21/02/2020 Nature of Claim: TP Claim No: 7533360859SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH8518A		
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Engine No:	R16B25502725
Reg. Date:	12/02/2019 (Man. Year: 2018)	Chassis No:	MRHFC5650JT002312
Colour:	Silver	Odometer:	26595 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,019.30	1,212.16	3,807.14	75.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,600.00	1,330.00	45.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	7,949.30	2,812.16	5,137.14	64.62
+ Car Rental (6.0 x S\$120.00/day + 7.00% GST) (S\$)		770.40		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,590.01		

INSPECTION

Date of Assignment: 24/02/2020

Date Inspected: 25/02/2020 Inspected At:

Poon Siang Seow (HQ)
160 Sin Ming Drive, #05-13 Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	671.50 F	*617.20 FL
2	1		*REAR BUMPER RETAINER	N/S Not Necessary /O/SDeformed	102.00 F	*51.00 FL
3	1		*REAR BUMPER REFLECTOR COVER	Broken	118.20 F	*66.00 FL
4	1		*REAR BUMPER SENSOR RIGHT	Damaged	250.80 F	*145.80 FL
5	1		*TAIL BOOT	Repair	531.20 F	*- FL
6	1		*TAIL BOOT GARISH	Repair	345.00 F	*- FL
7	1		*TAIL BOOT LOGO	Necessary	35.00 F	*15.00 FL
8	1		*TAIL BOOT BADGE CIVIC	Necessary	23.20 F	*11.80 FL
9	1		*TAIL BOOT BADGE VTICVT	Necessary	35.00 F	*11.80 FL
10	1		*TAIL BOOT REFLECTOR	Cracked	218.20 F	*122.30 FL
11	1		*REAR PANEL	Not Necessary	368.80 F	*- FL
12	1		*TAIL LAMP	Cracked	281.00 F	*281.00 FL
13	1		*TAIL LAMP PENAL	Buckled	128.30 F	*128.30 FL
14	1		*REAR FENDER	Repair	711.90 F	*- FL
15	1		*REAR W/S MOULDING	Not Necessary	232.00 F	*- FL
16	1		*WHEEL RIM	Repair	902.20 F	*- FL
17	1		*AIR GRILLE	Cracked	65.00 F	*65.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,019.30	1,515.20
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	303.04

Total Parts (\$\$)	5,019.30	1,212.16
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RUST PROOFING	New	100.00	40.00
2	TO REMOVE AND REFIT REAR W/S GLASS AND CUSHION	New	350.00	60.00
3	PANEL BEATING	New	1,500.00	700.00
4	SPRAY PAINTING	New	980.00	800.00
Gross Labour Cost (\$\$)			2,930.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >