

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 6926H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DEFORMED / TORN	860.00	698.60
2	REAR BUMPER RETAINER @\$48.20 (CONSISTENT)	NOT NECESSARY	96.40	-
2	REAR BUMPER BRACKET @\$45.60 (CONSISTENT)	NOT NECESSARY	91.20	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	286.20	-
1	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	60.00	50.00
1	BOOTLID (CONSISTENT)	DENTED / BENT	852.00	695.70
1	BOOTLID BADGE (CONSISTENT)	NECESSARY	98.00	38.50
1	BOOTLID BADGE (TYPE R) (CONSISTENT)	NECESSARY	82.00	82.00
2	BOOTLID LAMP @\$336.20 (CONSISTENT)	NOT NECESSARY	672.40	-
1	BOOTLID LAMP CLIPS (CONSISTENT)	NOT NECESSARY	30.00	-
1	BOOTLID INNER LOCK (CONSISTENT)	TWISTED	213.60	213.60
1	BOOTLID CATCH (CONSISTENT)	NOT NECESSARY	65.00	-
1	BOOTLID WEATHERSTRIP (CONSISTENT)	TWISTED	275.00	188.20
2	REAR TAILLAMP @\$513.70 (CONSISTENT)	O/S CRACKED	1,027.40	328.50
1	REAR END PANEL (CONSISTENT)	BADLY DENTED	567.40	387.30
1	REAR END PANEL TOP GARNISH (CONSISTENT)	TWISTED	195.20	195.20
1	REAR END PANEL TOP GARNISH CLIPS (CONSISTENT)	NOT NECESSARY	60.00	-
2	REAR FENDER @\$876.30 (CONSISTENT)	NOT NECESSARY	1,752.60	-
2	REAR FENDER INNER SHIELD @\$394.20 (CONSISTENT)	NOT NECESSARY	788.40	-
1	REAR FENDER INNER SHIELD CLIPS (CONSISTENT)	NOT NECESSARY	60.00	-
2	REAR EXHAUST PIPE MOUNTING @\$48.40 (CONSISTENT)	NOT NECESSARY	96.80	-
1	REAR EXHAUST HEAT SHIELD (CONSISTENT)	NOT NECESSARY	145.00	-
1	SPARE TYRE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	997.40	-
1	SPARE TYRE TOP TRIM (CONSISTENT)	NOT NECESSARY	195.80	-
1	SPARE TYRE TOP BOARD (CONSISTENT)	NOT NECESSARY	256.30	-
	LESS 20% DISCOUNT		-1,964.82	-575.52
			7,859.28	2,302.08
	SPECIAL NETT ITEMS			
1	REAR BUMPER DIFFUSER (ACCESSORIES) (SN) (CONSI	DEFORMED / TORN	1,250.00	600.00

Report Ref No. CC4/ASM20003099/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

4,100.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR EXHAUST END PIPE (ACCESSORIES) (SN) (CONSISTENT)	SERVICEABLE	1,750.00	-
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	250.00	200.00
1	REAR WINDSCREEN GLASS INNER SEAL (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
1	REAR WINDSCREEN GLASS SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR NUMBER PLATE WITH GARNISH (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR EXHAUST GUM (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
1	REAR EDN PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
			3,730.00	840.00
	<u>LABOUR</u>			
	TO PUTTY ,SRPAY PAINT ON REAR AFFECTED ACCIDENT AREAS.		1,200.00	900.00
	TOREMOVE & RENEW REAR AFFECTED ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL .		1,400.00	800.00
	TO TRANSFER ALL BOOTLID COMPONENTS TO FACILITATE REPAIRS.		150.00	60.00
	TO TRANSFER ALL BOOTLID INTERIOR COMPONENTS TO FACILITATE REPAIRS UPHOLSTERY.		150.00	80.00
	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING.		50.00	20.00
	TO RE-POSITION & INSTALL REVERSE SENSOR .		150.00	50.00
	TO REMOVE & INSTALL REAR WINDSCREEN GLASS .	NOT NECESSARY	120.00	-
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	150.00	-
	TO RE-PROGRAMME & RESET DIAGNOSTIC .	NOT NECESSARY	250.00	-
	TO RUST PROOF AFFECTED AREAS.		100.00	80.00
			3,720.00	1,990.00
	GRAND TOTAL		15,309.28	5,132.08

Report Ref No. CC4/ASM20003099/Upa3q2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

CHUA KANG SENG

Licensed Appraiser